



n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB270@0 96.477MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB270@0 96.181MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB273@0 97.378MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB273@0 97.223MHz



n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB273@0 97.262MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB273@0 97.221MHz




n78\_3


n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.577MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.610MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.566MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.560MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.563MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM  
QPSK\_RB24@0 8.577MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM 16  
QAM\_RB24@0 8.574MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM 64  
QAM\_RB24@0 8.568MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM 256  
QAM\_RB24@0 8.609MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.460MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.445MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.521MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.457MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.450MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM  
QPSK\_RB38@0 13.571MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM 16  
QAM\_RB38@0 13.577MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM 64  
QAM\_RB38@0 13.585MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM 256  
QAM\_RB38@0 13.527MHz




n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.019MHz




n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.094MHz




n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.094MHz



n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.033MHz



n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.006MHz



n78\_3\_20MHz\_30kHz\_3750MHz\_CP-OFDM  
QPSK\_RB51@0 18.166MHz

