


n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB243@0 86.549MHz




n78_3_90MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB243@0 86.420MHz



n78_3_90MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB245@0 87.248MHz




n78_3_90MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB245@0 87.227MHz




n78_3_90MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB245@0 87.193MHz




n78_3_90MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB245@0 87.189MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB270@0 96.465MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB270@0 96.509MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB270@0 96.109MHz




n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB270@0 96.192MHz



n78_3_100MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB270@0 96.111MHz




n78_3_100MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB273@0 97.356MHz



n78_3_100MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB273@0 97.207MHz



n78_3_100MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB273@0 97.251MHz



n78_3_100MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB273@0 97.260MHz

