




n7\_5MHz\_15kHz\_2567.5MHz\_CP-OFDM 16  
QAM\_RB25@0 4.464MHz




n7\_5MHz\_15kHz\_2567.5MHz\_CP-OFDM 64  
QAM\_RB25@0 4.467MHz




n7\_5MHz\_15kHz\_2567.5MHz\_CP-OFDM 256  
QAM\_RB25@0 4.468MHz




n7\_10MHz\_15kHz\_2505MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 9.212MHz




n7\_10MHz\_15kHz\_2505MHz\_DFT-s-OFDM  
QPSK\_RB50@0 9.178MHz




n7\_10MHz\_15kHz\_2505MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 9.219MHz




n7\_10MHz\_15kHz\_2505MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 9.204MHz




n7\_10MHz\_15kHz\_2505MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 9.173MHz




n7\_10MHz\_15kHz\_2505MHz\_CP-OFDM QPSK\_RB52@0  
9.283MHz




n7\_10MHz\_15kHz\_2505MHz\_CP-OFDM 16  
QAM\_RB52@0 9.297MHz




n7\_10MHz\_15kHz\_2505MHz\_CP-OFDM 64  
QAM\_RB52@0 9.281MHz




n7\_10MHz\_15kHz\_2505MHz\_CP-OFDM 256  
QAM\_RB52@0 9.260MHz




n7\_10MHz\_15kHz\_2535MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 9.173MHz




n7\_10MHz\_15kHz\_2535MHz\_DFT-s-OFDM  
QPSK\_RB50@0 9.177MHz




n7\_10MHz\_15kHz\_2535MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 9.252MHz




n7\_10MHz\_15kHz\_2535MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 9.210MHz




n7\_10MHz\_15kHz\_2535MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 9.204MHz




n7\_10MHz\_15kHz\_2535MHz\_CP-OFDM QPSK\_RB52@0  
9.258MHz




n7\_10MHz\_15kHz\_2535MHz\_CP-OFDM 16  
QAM\_RB52@0 9.323MHz




n7\_10MHz\_15kHz\_2535MHz\_CP-OFDM 64  
QAM\_RB52@0 9.293MHz




n7\_10MHz\_15kHz\_2535MHz\_CP-OFDM 256  
QAM\_RB52@0 9.260MHz




n7\_10MHz\_15kHz\_2565MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 9.178MHz




n7\_10MHz\_15kHz\_2565MHz\_DFT-s-OFDM  
QPSK\_RB50@0 9.204MHz




n7\_10MHz\_15kHz\_2565MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 9.246MHz




n7\_10MHz\_15kHz\_2565MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 9.207MHz




n7\_10MHz\_15kHz\_2565MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 9.179MHz




n7\_10MHz\_15kHz\_2565MHz\_CP-OFDM QPSK\_RB52@0  
9.258MHz




n7\_10MHz\_15kHz\_2565MHz\_CP-OFDM 16  
QAM\_RB52@0 9.323MHz



n7\_10MHz\_15kHz\_2565MHz\_CP-OFDM 64  
QAM\_RB52@0 9.289MHz



n7\_10MHz\_15kHz\_2565MHz\_CP-OFDM 256  
QAM\_RB52@0 9.283MHz




n7\_15MHz\_15kHz\_2507.5MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 13.942MHz




n7\_15MHz\_15kHz\_2507.5MHz\_DFT-s-OFDM  
QPSK\_RB75@0 13.946MHz




n7\_15MHz\_15kHz\_2507.5MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 13.984MHz



n7\_15MHz\_15kHz\_2507.5MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 13.950MHz



n7\_15MHz\_15kHz\_2507.5MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 13.933MHz



n7\_15MHz\_15kHz\_2507.5MHz\_CP-OFDM  
QPSK\_RB79@0 14.068MHz

