




n38_5MHz_15kHz_2595MHz_CP-OFDM 16
QAM_RB25@0 4.450MHz




n38_5MHz_15kHz_2595MHz_CP-OFDM 64
QAM_RB25@0 4.467MHz




n38_5MHz_15kHz_2595MHz_CP-OFDM 256
QAM_RB25@0 4.470MHz




n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB25@0 4.480MHz




n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM
QPSK_RB25@0 4.469MHz




n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM 16
QAM_RB25@0 4.464MHz




n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM 64
QAM_RB25@0 4.488MHz




n38_5MHz_15kHz_2617.5MHz_DFT-s-OFDM 256
QAM_RB25@0 4.466MHz




n38_5MHz_15kHz_2617.5MHz_CP-OFDM
QPSK_RB25@0 4.482MHz




n38_5MHz_15kHz_2617.5MHz_CP-OFDM 16
QAM_RB25@0 4.465MHz




n38_5MHz_15kHz_2617.5MHz_CP-OFDM 64
QAM_RB25@0 4.466MHz




n38_5MHz_15kHz_2617.5MHz_CP-OFDM 256
QAM_RB25@0 4.481MHz




n38_10MHz_30kHz_2575MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0 8.569MHz




n38_10MHz_30kHz_2575MHz_DFT-s-OFDM
QPSK_RB24@0 8.611MHz




n38_10MHz_30kHz_2575MHz_DFT-s-OFDM 16
QAM_RB24@0 8.570MHz




n38_10MHz_30kHz_2575MHz_DFT-s-OFDM 64
QAM_RB24@0 8.536MHz




n38_10MHz_30kHz_2575MHz_DFT-s-OFDM 256
QAM_RB24@0 8.535MHz




n38_10MHz_30kHz_2575MHz_CP-OFDM
QPSK_RB24@0 8.568MHz




n38_10MHz_30kHz_2575MHz_CP-OFDM 16
QAM_RB24@0 8.572MHz




n38_10MHz_30kHz_2575MHz_CP-OFDM 64
QAM_RB24@0 8.566MHz




n38_10MHz_30kHz_2575MHz_CP-OFDM 256
QAM_RB24@0 8.610MHz




n38_10MHz_30kHz_2595MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0 8.570MHz




n38_10MHz_30kHz_2595MHz_DFT-s-OFDM
QPSK_RB24@0 8.573MHz




n38_10MHz_30kHz_2595MHz_DFT-s-OFDM 16
QAM_RB24@0 8.572MHz




n38_10MHz_30kHz_2595MHz_DFT-s-OFDM 64
QAM_RB24@0 8.580MHz




n38_10MHz_30kHz_2595MHz_DFT-s-OFDM 256
QAM_RB24@0 8.569MHz




n38_10MHz_30kHz_2595MHz_CP-OFDM
QPSK_RB24@0 8.562MHz




n38_10MHz_30kHz_2595MHz_CP-OFDM 16
QAM_RB24@0 8.573MHz




n38_10MHz_30kHz_2595MHz_CP-OFDM 64
QAM_RB24@0 8.568MHz




n38_10MHz_30kHz_2595MHz_CP-OFDM 256
QAM_RB24@0 8.610MHz




n38_10MHz_30kHz_2615MHz_DFT-s-OFDM $\pi/2$
BPSK_RB24@0 8.568MHz




n38_10MHz_30kHz_2615MHz_DFT-s-OFDM
QPSK_RB24@0 8.615MHz




n38_10MHz_30kHz_2615MHz_DFT-s-OFDM 16
QAM_RB24@0 8.578MHz



n38_10MHz_30kHz_2615MHz_DFT-s-OFDM 64
QAM_RB24@0 8.572MHz



n38_10MHz_30kHz_2615MHz_DFT-s-OFDM 256
QAM_RB24@0 8.537MHz



n38_10MHz_30kHz_2615MHz_CP-OFDM
QPSK_RB24@0 8.603MHz

