



n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.462MHz




n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM
QPSK_RB36@0 13.454MHz




n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM 16
QAM_RB36@0 13.466MHz




n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.445MHz




n77_1_15MHz_30kHz_3457.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.466MHz




n77_1_15MHz_30kHz_3457.5MHz_CP-OFDM
QPSK_RB38@0 13.563MHz




n77_1_15MHz_30kHz_3457.5MHz_CP-OFDM 16
QAM_RB38@0 13.570MHz




n77_1_15MHz_30kHz_3457.5MHz_CP-OFDM 64
QAM_RB38@0 13.571MHz




n77_1_15MHz_30kHz_3457.5MHz_CP-OFDM 256
QAM_RB38@0 13.529MHz




n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.454MHz




n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB36@0 13.457MHz




n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB36@0 13.465MHz




n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB36@0 13.465MHz




n77_1_15MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB36@0 13.466MHz




n77_1_15MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB38@0 13.566MHz




n77_1_15MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB38@0 13.573MHz




n77_1_15MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB38@0 13.575MHz




n77_1_15MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB38@0 13.524MHz




n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.442MHz




n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 13.409MHz




n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM 16
QAM_RB36@0 13.516MHz




n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.457MHz




n77_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.464MHz




n77_1_15MHz_30kHz_3542.5MHz_CP-OFDM
QPSK_RB38@0 13.577MHz




n77_1_15MHz_30kHz_3542.5MHz_CP-OFDM 16
QAM_RB38@0 13.571MHz




n77_1_15MHz_30kHz_3542.5MHz_CP-OFDM 64
QAM_RB38@0 13.629MHz




n77_1_15MHz_30kHz_3542.5MHz_CP-OFDM 256
QAM_RB38@0 13.573MHz




n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.085MHz




n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 18.017MHz




n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM 16
QAM_RB50@0 18.102MHz




n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM 64
QAM_RB50@0 18.019MHz




n77_1_20MHz_30kHz_3460MHz_DFT-s-OFDM 256
QAM_RB50@0 18.029MHz




n77_1_20MHz_30kHz_3460MHz_CP-OFDM
QPSK_RB51@0 18.168MHz



n77_1_20MHz_30kHz_3460MHz_CP-OFDM 16
QAM_RB51@0 18.116MHz



n77_1_20MHz_30kHz_3460MHz_CP-OFDM 64
QAM_RB51@0 18.190MHz



n77_1_20MHz_30kHz_3460MHz_CP-OFDM 256
QAM_RB51@0 18.190MHz

