




n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.026MHz




n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM
QPSK_RB128@0 47.265MHz




n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM 16
QAM_RB128@0 47.041MHz




n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM 64
QAM_RB128@0 46.857MHz




n77_1_50MHz_30kHz_3475MHz_DFT-s-OFDM 256
QAM_RB128@0 46.881MHz



n77_1_50MHz_30kHz_3475MHz_CP-OFDM
QPSK_RB133@0 47.406MHz




n77_1_50MHz_30kHz_3475MHz_CP-OFDM 16
QAM_RB133@0 47.428MHz




n77_1_50MHz_30kHz_3475MHz_CP-OFDM 64
QAM_RB133@0 47.409MHz




n77_1_50MHz_30kHz_3475MHz_CP-OFDM 256
QAM_RB133@0 47.267MHz




n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.039MHz




n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB128@0 47.276MHz




n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB128@0 47.016MHz




n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB128@0 46.870MHz




n77_1_50MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB128@0 47.215MHz




n77_1_50MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB133@0 47.273MHz




n77_1_50MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB133@0 47.441MHz




n77_1_50MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB133@0 47.447MHz




n77_1_50MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB133@0 47.285MHz




n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.048MHz




n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM
QPSK_RB128@0 47.249MHz




n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM 16
QAM_RB128@0 47.027MHz




n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM 64
QAM_RB128@0 46.838MHz




n77_1_50MHz_30kHz_3525MHz_DFT-s-OFDM 256
QAM_RB128@0 47.008MHz




n77_1_50MHz_30kHz_3525MHz_CP-OFDM
QPSK_RB133@0 47.424MHz




n77_1_50MHz_30kHz_3525MHz_CP-OFDM 16
QAM_RB133@0 47.430MHz




n77_1_50MHz_30kHz_3525MHz_CP-OFDM 64
QAM_RB133@0 47.415MHz




n77_1_50MHz_30kHz_3525MHz_CP-OFDM 256
QAM_RB133@0 47.282MHz




n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM $\pi/2$
BPSK_RB162@0 57.680MHz




n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM
QPSK_RB162@0 57.698MHz




n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM 16
QAM_RB162@0 57.714MHz




n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM 64
QAM_RB162@0 57.905MHz




n77_1_60MHz_30kHz_3480MHz_CP-OFDM
QPSK_RB162@0 57.695MHz




n77_1_60MHz_30kHz_3480MHz_CP-OFDM 64
QAM_RB162@0 57.858MHz



n77_1_60MHz_30kHz_3480MHz_DFT-s-OFDM 256
QAM_RB162@0 57.479MHz



n77_1_60MHz_30kHz_3480MHz_CP-OFDM 16
QAM_RB162@0 57.672MHz



n77_1_60MHz_30kHz_3480MHz_CP-OFDM 256
QAM_RB162@0 57.610MHz

