




n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB36@0 13.458MHz




n78_1_15MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB36@0 13.468MHz




n78_1_15MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB38@0 13.565MHz




n78_1_15MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB38@0 13.578MHz




n78_1_15MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB38@0 13.572MHz




n78_1_15MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB38@0 13.529MHz




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM $\pi/2$
BPSK_RB36@0 13.451MHz




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM
QPSK_RB36@0 13.446MHz




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM 16
QAM_RB36@0 13.501MHz




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM 64
QAM_RB36@0 13.455MHz




n78_1_15MHz_30kHz_3542.5MHz_DFT-s-OFDM 256
QAM_RB36@0 13.463MHz




n78_1_15MHz_30kHz_3542.5MHz_CP-OFDM
QPSK_RB38@0 13.579MHz




n78_1_15MHz_30kHz_3542.5MHz_CP-OFDM 16
QAM_RB38@0 13.569MHz




n78_1_15MHz_30kHz_3542.5MHz_CP-OFDM 64
QAM_RB38@0 13.582MHz




n78_1_15MHz_30kHz_3542.5MHz_CP-OFDM 256
QAM_RB38@0 13.570MHz




n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.103MHz




n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM
QPSK_RB50@0 18.036MHz




n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM 16
QAM_RB50@0 18.103MHz




n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM 64
QAM_RB50@0 18.029MHz




n78_1_20MHz_30kHz_3460MHz_DFT-s-OFDM 256
QAM_RB50@0 18.028MHz




n78_1_20MHz_30kHz_3460MHz_CP-OFDM
QPSK_RB51@0 18.169MHz




n78_1_20MHz_30kHz_3460MHz_CP-OFDM 16
QAM_RB51@0 18.180MHz




n78_1_20MHz_30kHz_3460MHz_CP-OFDM 64
QAM_RB51@0 18.190MHz




n78_1_20MHz_30kHz_3460MHz_CP-OFDM 256
QAM_RB51@0 18.187MHz




n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.024MHz




n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB50@0 18.022MHz




n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM 16
QAM_RB50@0 18.038MHz




n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM 64
QAM_RB50@0 18.028MHz




n78_1_20MHz_30kHz_3500MHz_DFT-s-OFDM 256
QAM_RB50@0 18.015MHz




n78_1_20MHz_30kHz_3500MHz_CP-OFDM
QPSK_RB51@0 18.112MHz




n78_1_20MHz_30kHz_3500MHz_CP-OFDM 16
QAM_RB51@0 18.174MHz




n78_1_20MHz_30kHz_3500MHz_CP-OFDM 64
QAM_RB51@0 18.168MHz




n78_1_20MHz_30kHz_3500MHz_CP-OFDM 256
QAM_RB51@0 18.193MHz



n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM $\pi/2$
BPSK_RB50@0 18.021MHz



n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM
QPSK_RB50@0 18.082MHz



n78_1_20MHz_30kHz_3540MHz_DFT-s-OFDM 16
QAM_RB50@0 18.097MHz

