



n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB100@0 37.294MHz




n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB100@0 37.194MHz




n78_3_40MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB106@0 37.795MHz




n78_3_40MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB106@0 37.783MHz




n78_3_40MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB106@0 37.837MHz




n78_3_40MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB106@0 37.776MHz



n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.509MHz




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 37.496MHz




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM 16
QAM_RB100@0 37.327MHz




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM 64
QAM_RB100@0 37.310MHz




n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM 256
QAM_RB100@0 37.310MHz




n78_3_40MHz_30kHz_3780MHz_CP-OFDM
QPSK_RB106@0 37.771MHz




n78_3_40MHz_30kHz_3780MHz_CP-OFDM 16
QAM_RB106@0 37.782MHz



n78_3_40MHz_30kHz_3780MHz_CP-OFDM 64
QAM_RB106@0 37.921MHz




n78_3_40MHz_30kHz_3780MHz_CP-OFDM 256
QAM_RB106@0 37.775MHz




n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 46.889MHz



n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 47.233MHz




n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM 16
QAM_RB128@0 47.047MHz




n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM 64
QAM_RB128@0 46.886MHz




n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM 256
QAM_RB128@0 46.863MHz




n78_3_50MHz_30kHz_3725MHz_CP-OFDM
QPSK_RB133@0 47.404MHz




n78_3_50MHz_30kHz_3725MHz_CP-OFDM 16
QAM_RB133@0 47.473MHz




n78_3_50MHz_30kHz_3725MHz_CP-OFDM 64
QAM_RB133@0 47.405MHz




n78_3_50MHz_30kHz_3725MHz_CP-OFDM 256
QAM_RB133@0 47.401MHz



n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.053MHz




n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB128@0 47.415MHz




n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM 16
QAM_RB128@0 47.202MHz




n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM 64
QAM_RB128@0 47.032MHz




n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM 256
QAM_RB128@0 47.248MHz




n78_3_50MHz_30kHz_3750MHz_CP-OFDM
QPSK_RB133@0 47.411MHz




n78_3_50MHz_30kHz_3750MHz_CP-OFDM 16
QAM_RB133@0 47.463MHz



n78_3_50MHz_30kHz_3750MHz_CP-OFDM 64
QAM_RB133@0 47.464MHz




n78_3_50MHz_30kHz_3750MHz_CP-OFDM 256
QAM_RB133@0 47.418MHz



n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM $\pi/2$
BPSK_RB128@0 47.073MHz



n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM
QPSK_RB128@0 46.868MHz



n78_3_50MHz_30kHz_3775MHz_DFT-s-OFDM 16
QAM_RB128@0 47.019MHz

