



n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB1@244 -40.78dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 05:38:01

n78_1_90MHz_30kHz_3495MHz_DFT-s-OFDM
QPSK_RB243@0 -39.86dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 05:39:02

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.99dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 05:40:05

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@244 -41dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 05:41:10

n78_1_90MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB243@0 -40.51dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 05:42:12

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@0 -40.99dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 24.SEP.2024 05:43:19

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB1@244 -40.83dBm




ProjectNo.: 2401W26164E-RF Tester:Kangfumeister LiJiang
Date: 24_SEP.2024 05:44:20

n78_1_90MHz_30kHz_3505MHz_DFT-s-OFDM
QPSK_RB243@0 -40.80dBm




ProjectNo.: 2401W26164E-RF Tester:Kangfumeister LiJiang
Date: 24_SEP.2024 05:45:22

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@0 -40.98dBm




ProjectNo.: 2401W26164E-RF Tester:Kangfumeister LiJiang
Date: 24_SEP.2024 05:46:31

n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB1@272 -40.55dBm



ProjectNo.: 2401W26164E-RF Tester:Kangfumeister LiJiang
Date: 24_SEP.2024 05:47:33


n78_1_100MHz_30kHz_3500MHz_DFT-s-OFDM
QPSK_RB270@0 -41.24dBm



ProjectNo.: 2401W26164E-RF Tester:Kangfumeister LiJiang
Date: 24_SEP.2024 05:48:34


n78_3

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@0 -38.31dBm




ProjectNo.: 2401W26164E-RF Tester:Kangfumeister LiJiang
Date: 23_SEP.2024 22:41:47

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB1@23 -37.72dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfunmaster Liang
Date: 23_SEP.2024 22:42:48

n78_3_10MHz_30kHz_3705MHz_DFT-s-OFDM
QPSK_RB24@0 -38.27dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfunmaster Liang
Date: 23_SEP.2024 22:43:49

n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -38.85dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfunmaster Liang
Date: 23_SEP.2024 22:44:55

n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@23 -39.11dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfunmaster Liang
Date: 23_SEP.2024 22:45:56

n78_3_10MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB24@0 -38.08dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfunmaster Liang
Date: 23_SEP.2024 22:46:57

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@0 -39.14dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfunmaster Liang
Date: 23_SEP.2024 22:48:03

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB1@23 -38.88dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister, Liang
Date: 23_SEP.2024 22:49:04

n78_3_10MHz_30kHz_3795MHz_DFT-s-OFDM
QPSK_RB24@0 -38.68dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister, Liang
Date: 23_SEP.2024 22:50:06

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38.85dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister, Liang
Date: 23_SEP.2024 22:52:05

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB1@37 -38.25dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister, Liang
Date: 23_SEP.2024 22:53:07

n78_3_15MHz_30kHz_3707.5MHz_DFT-s-OFDM
QPSK_RB36@0 -38.99dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister, Liang
Date: 23_SEP.2024 22:54:08

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -39.37dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister, Liang
Date: 23_SEP.2024 22:55:14

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@37 -39.05dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 22:56:14

n78_3_15MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB36@0 -39.35dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 22:57:17

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@0 -39.45dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 22:58:24

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB1@37 -38.97dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 22:59:26

n78_3_15MHz_30kHz_3792.5MHz_DFT-s-OFDM
QPSK_RB36@0 -39.48dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:00:26

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@0 -39.19dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:02:27

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB1@50 -39.32dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:03:25

n78_3_20MHz_30kHz_3710MHz_DFT-s-OFDM
QPSK_RB50@0 -38.60dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:04:31

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -38.90dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:05:35

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@50 -39.33dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:06:40

n78_3_20MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB50@0 -39.14dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:07:42

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@0 -39.50dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:08:48

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB1@50 -38.66dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:09:51

n78_3_20MHz_30kHz_3790MHz_DFT-s-OFDM
QPSK_RB50@0 -38.30dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:10:53

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@0 -39.53dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:23:34

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB1@77 -39.43dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:24:36

n78_3_30MHz_30kHz_3715MHz_DFT-s-OFDM
QPSK_RB75@0 -39.36dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:25:38

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -39.33dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:26:45

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@77 -39.31dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:27:48

n78_3_30MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB75@0 -39.27dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:28:51

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@0 -39.31dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:29:59

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB1@77 -38.96dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:31:02

n78_3_30MHz_30kHz_3785MHz_DFT-s-OFDM
QPSK_RB75@0 -38.80dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:32:04

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB100@0 -39.54dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeaster Liang
Date: 23_SEP.2024 23:36:21

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@0 -38.78dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:34:14

n78_3_40MHz_30kHz_3720MHz_DFT-s-OFDM
QPSK_RB1@105 -38.97dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:35:19

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB100@0 -39.68dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:39:35

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@0 -38.94dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:37:30

n78_3_40MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB1@105 -39.53dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:39:32

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB100@0 -39.57dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:42:48

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@0 -39.12dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:40:43

n78_3_40MHz_30kHz_3780MHz_DFT-s-OFDM
QPSK_RB1@105 -38.79dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:41:46

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB128@0 -39.59dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:47:05

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@0 -39.40dBm




ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:45:02

n78_3_50MHz_30kHz_3725MHz_DFT-s-OFDM
QPSK_RB1@132 -39.40dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:46:05

n78_3_50MHz_30kHz_3750MHz_DFT-s-OFDM
QPSK_RB128@0 -39.12dBm



ProjectNo.: 2401W26164E-RF Tester: Kingfumeister Liang
Date: 23_SEP.2024 23:50:28