




n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.461MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.460MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.529MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.502MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.451MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_CP-OFDM  
QPSK\_RB38@0 13.568MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_CP-OFDM 16  
QAM\_RB38@0 13.578MHz




n77\_3\_15MHz\_30kHz\_3840MHz\_CP-OFDM 64  
QAM\_RB38@0 13.580MHz



n77\_3\_15MHz\_30kHz\_3840MHz\_CP-OFDM 256  
QAM\_RB38@0 13.525MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.084MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.081MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.083MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64  
QAM\_RB50@0 18.094MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_DFT-s-OFDM 256  
QAM\_RB50@0 18.013MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_CP-OFDM  
QPSK\_RB51@0 18.181MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_CP-OFDM 16  
QAM\_RB51@0 18.183MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_CP-OFDM 64  
QAM\_RB51@0 18.169MHz




n77\_3\_20MHz\_30kHz\_3840MHz\_CP-OFDM 256  
QAM\_RB51@0 18.189MHz




n77\_3\_30MHz\_30kHz\_3840MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB75@0 27.533MHz




n77\_3\_30MHz\_30kHz\_3840MHz\_DFT-s-OFDM  
QPSK\_RB75@0 27.628MHz



n77\_3\_30MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16  
QAM\_RB75@0 27.735MHz




n77\_3\_30MHz\_30kHz\_3840MHz\_DFT-s-OFDM 64  
QAM\_RB75@0 27.605MHz




n77\_3\_30MHz\_30kHz\_3840MHz\_DFT-s-OFDM 256  
QAM\_RB75@0 27.503MHz




n77\_3\_30MHz\_30kHz\_3840MHz\_CP-OFDM  
QPSK\_RB78@0 27.874MHz




n77\_3\_30MHz\_30kHz\_3840MHz\_CP-OFDM 16  
QAM\_RB78@0 27.842MHz



n77\_3\_30MHz\_30kHz\_3840MHz\_CP-OFDM 64  
QAM\_RB78@0 27.759MHz



n77\_3\_30MHz\_30kHz\_3840MHz\_CP-OFDM 256  
QAM\_RB78@0 27.759MHz



n77\_3\_40MHz\_30kHz\_3840MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB100@0 37.505MHz



n77\_3\_40MHz\_30kHz\_3840MHz\_DFT-s-OFDM  
QPSK\_RB100@0 37.602MHz



n77\_3\_40MHz\_30kHz\_3840MHz\_DFT-s-OFDM 16  
QAM\_RB100@0 37.291MHz

