




n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB270@0 96.517MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM  
QPSK\_RB270@0 96.511MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 16  
QAM\_RB270@0 96.116MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 64  
QAM\_RB270@0 96.418MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_DFT-s-OFDM 256  
QAM\_RB270@0 96.139MHz



n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM  
QPSK\_RB273@0 97.270MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 16  
QAM\_RB273@0 96.988MHz



n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 64  
QAM\_RB273@0 97.245MHz




n78\_1\_100MHz\_30kHz\_3500MHz\_CP-OFDM 256  
QAM\_RB273@0 97.351MHz




n78\_3


n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB24@0 8.564MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB24@0 8.578MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM 16  
QAM\_RB24@0 8.564MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM 64  
QAM\_RB24@0 8.561MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_DFT-s-OFDM 256  
QAM\_RB24@0 8.564MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM  
QPSK\_RB24@0 8.577MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM 16  
QAM\_RB24@0 8.572MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM 64  
QAM\_RB24@0 8.566MHz




n78\_3\_10MHz\_30kHz\_3750MHz\_CP-OFDM 256  
QAM\_RB24@0 8.608MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB36@0 13.458MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB36@0 13.444MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM 16  
QAM\_RB36@0 13.464MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM 64  
QAM\_RB36@0 13.453MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_DFT-s-OFDM 256  
QAM\_RB36@0 13.446MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM  
QPSK\_RB38@0 13.574MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM 16  
QAM\_RB38@0 13.583MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM 64  
QAM\_RB38@0 13.576MHz




n78\_3\_15MHz\_30kHz\_3750MHz\_CP-OFDM 256  
QAM\_RB38@0 13.525MHz



n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM  $\pi/2$   
BPSK\_RB50@0 18.020MHz



n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM  
QPSK\_RB50@0 18.033MHz



n78\_3\_20MHz\_30kHz\_3750MHz\_DFT-s-OFDM 16  
QAM\_RB50@0 18.098MHz

