



n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:24:56

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@23 -37.51dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:25:31

n41_10MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB24@0 -37.29dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:26:06

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@0 -35.64dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:27:19

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB1@23 -37.78dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:27:52

n41_10MHz_30kHz_2685MHz_DFT-s-OFDM
QPSK_RB24@0 -37.84dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:28:26

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@0 -38dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:29:39

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB1@37 -37.51dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:30:13

n41_15MHz_30kHz_2503.5MHz_DFT-s-OFDM
QPSK_RB36@0 -37.60dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:30:47

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.73dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:31:47

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@37 -37.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:32:21

n41_15MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB36@0 -37.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:32:55

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@0 -36.66dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:34:11

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB1@37 -37.47dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:34:46

n41_15MHz_30kHz_2682.48MHz_DFT-s-OFDM
QPSK_RB36@0 -37.52dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:35:20

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@0 -36.96dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:36:18

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB1@50 -37.60dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:36:52

n41_20MHz_30kHz_2506.02MHz_DFT-s-OFDM
QPSK_RB50@0 -37.51dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:37:25

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.02dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:39:08

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@50 -37.44dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:39:42

n41_20MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB50@0 -37.59dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:40:16

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.80dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:41:29

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB1@50 -37.37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:42:04

n41_20MHz_30kHz_2679.99MHz_DFT-s-OFDM
QPSK_RB50@0 -37.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:42:38

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@0 -37.42dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:43:53

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB1@77 -37.49dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:44:28

n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB75@0 -37.41dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:45:02

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.09dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:47:01

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@77 -37.81dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:47:35

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB75@0 -36.98dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:48:10

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@0 -36.74dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:49:24

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB1@77 -37.76dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:49:59

n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB75@0 -36.76dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 31.JUL.2024 08:50:33

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0 -37.44dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:12:11

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.12dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:11:05

n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB1@105 -37.46dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:11:38

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB100@0 -37.68dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:14:53

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.69dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:13:21

n41_40MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@105 -37.66dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:14:20

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB100@0 -37.35dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:16:55

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@0 -37.85dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:15:49

n41_40MHz_30kHz_2670MHz_DFT-s-OFDM
QPSK_RB1@105 -37.60dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:16:22

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB128@0 -37.60dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:19:02

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.27dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:17:51

n41_50MHz_30kHz_2521.02MHz_DFT-s-OFDM
QPSK_RB1@132 -37.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:18:24

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB128@0 -37.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:21:53

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.70dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:20:39

n41_50MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@132 -37.63dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:21:16

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB128@0 -37.41dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:24:38

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.42dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:23:07

n41_50MHz_30kHz_2664.99MHz_DFT-s-OFDM
QPSK_RB1@132 -36.66dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:24:05

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB162@0 -37.17dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:27:06

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@0 -37.18dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:25:35

n41_60MHz_30kHz_2526MHz_DFT-s-OFDM
QPSK_RB1@161 -37.21dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:26:09

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB162@0 -37.14dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:29:09

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:28:02

n41_60MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@161 -37.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:28:36

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB162@0 -36.87dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:31:54

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@0 -37.50dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:30:47

n41_60MHz_30kHz_2659.98MHz_DFT-s-OFDM
QPSK_RB1@161 -37.72dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:31:20

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@0 -37.30dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:32:50

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB1@216 -37.89dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:33:48

n41_80MHz_30kHz_2536.02MHz_DFT-s-OFDM
QPSK_RB216@0 -37.54dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:34:22

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.50dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:35:35

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@216 -37.16dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:36:09

n41_80MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB216@0 -37.72dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:36:43

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.87dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:37:57

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB1@216 -37.18dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:38:33

n41_80MHz_30kHz_2649.99MHz_DFT-s-OFDM
QPSK_RB216@0 -36.93dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:39:09

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@0 -36.87dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:40:12

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB1@244 -37.71dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:40:46

n41_90MHz_30kHz_2541MHz_DFT-s-OFDM
QPSK_RB243@0 -37.26dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:41:20

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -36.98dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:42:32

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@244 -37.62dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:43:31

n41_90MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB243@0 -37.15dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:44:05

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@0 -37.42dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:45:16

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB1@244 -37.80dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:45:50

n41_90MHz_30kHz_2644.98MHz_DFT-s-OFDM
QPSK_RB243@0 -37.65dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:46:23

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@0 -37.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:47:34

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB1@272 -37.52dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:48:08

n41_100MHz_30kHz_2546.01MHz_DFT-s-OFDM
QPSK_RB270@0 -37.52dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:48:41

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@0 -37.59dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:49:38

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB1@272 -37.39dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:50:11

n41_100MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK_RB270@0 -37.58dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:50:46

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@0 -37.42dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:51:45


n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB1@272 -37.85dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:52:19


n66

n41_100MHz_30kHz_2640MHz_DFT-s-OFDM
QPSK_RB270@0 -37.69dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:52:54

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@0 -37.18dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:54:02

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB1@24 -37.11dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:54:30

n66_5MHz_15kHz_1712.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:54:59

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.39dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:56:10

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@24 -36.35dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:56:39

n66_5MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB25@0 -36.79dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:57:08

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.84dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:58:14

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB1@24 -36.97dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:58:43

n66_5MHz_15kHz_1777.5MHz_DFT-s-OFDM
QPSK_RB25@0 -37.14dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 06:59:12

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@0 -37.16dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:00:18

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB1@51 -37.29dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:00:47

n66_10MHz_15kHz_1715MHz_DFT-s-OFDM
QPSK_RB50@0 -37.55dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:01:16

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.22dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:02:08

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@51 -36.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:02:37

n66_10MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB50@0 -36.56dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:03:06

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@0 -36.68dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:04:12

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB1@51 -36.77dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:04:41

n66_10MHz_15kHz_1775MHz_DFT-s-OFDM
QPSK_RB50@0 -36.13dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:05:10

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.21dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:06:16

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB1@78 -37.16dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:06:45

n66_15MHz_15kHz_1717.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.92dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:07:14

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.03dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:08:25

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@78 -37.33dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:08:53

n66_15MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB75@0 -37.14dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:09:22

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.87dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:10:29

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB1@78 -36.95dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:10:58

n66_15MHz_15kHz_1772.5MHz_DFT-s-OFDM
QPSK_RB75@0 -36.78dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:11:27

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB100@0 -36.98dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:13:31

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@0 -36.29dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:12:33

n66_20MHz_15kHz_1720MHz_DFT-s-OFDM
QPSK_RB1@105 -37.27dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:13:02

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB100@0 -36.65dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:15:22

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -36.89dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:14:24

n66_20MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@105 -36.45dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:14:53

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB100@0 -36.49dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:17:30

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@0 -36.93dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:16:32

n66_20MHz_15kHz_1770MHz_DFT-s-OFDM
QPSK_RB1@105 -37.32dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:17:01

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB128@0 -37.34dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:19:37

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.89dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:18:39

n66_25MHz_15kHz_1722.5MHz_DFT-s-OFDM
QPSK_RB1@132 -36.27dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:19:08

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB128@0 -36.40dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:21:45

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@0 -37.17dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:20:47

n66_25MHz_15kHz_1745MHz_DFT-s-OFDM
QPSK_RB1@132 -37dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:21:16

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB128@0 -37.22dBm




ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:23:53

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@0 -36.58dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:22:55

n66_25MHz_15kHz_1767.5MHz_DFT-s-OFDM
QPSK_RB1@132 -37.10dBm



ProjectNo.:2401U82760E-RF Tester:Jim Cheng
Date: 2.AUG.2024 07:23:24