



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 15.FEB.2022 22:09:24

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 3.JAN.2022 13:15:16

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 3.JAN.2022 13:15:37

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 3.JAN.2022 13:15:57

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 3.JAN.2022 13:16:15

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 3.JAN.2022 13:16:32

Band 2_3 MHz_High_QPSK_RB15#0




Date: 3.JAN.2022 13:16:52

Band 2_3 MHz_High_16QAM_RB15#0




Date: 3.JAN.2022 13:17:09

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 3.JAN.2022 13:17:27

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 13:17:44

Band 2_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 13:18:04

Band 2_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 13:18:24

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:18:45

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:19:04

Band 2_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:19:23

Band 2_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:19:42

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 3.JAN.2022 13:20:07

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 3.JAN.2022 13:20:31

Band 2_15 MHz_High_QPSK_RB75#0




Date: 3.JAN.2022 13:20:55

Band 2_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2022 13:21:19

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 3.JAN.2022 13:21:44

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 3.JAN.2022 13:22:07

Band 2_20 MHz_High_QPSK_RB100#0




Date: 3.JAN.2022 13:22:31

Band 2_20 MHz_High_16QAM_RB100#0




Date: 3.JAN.2022 13:22:55

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 3.JAN.2022 13:23:16

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 3.JAN.2022 13:23:36

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 3.JAN.2022 13:23:56

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 3.JAN.2022 13:24:16

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 3.JAN.2022 13:24:38

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 3.JAN.2022 13:24:54

Band 4_3 MHz_High_QPSK_RB15#0




Date: 3.JAN.2022 13:25:15

Band 4_3 MHz_High_16QAM_RB15#0




Date: 3.JAN.2022 13:25:35

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 3.JAN.2022 13:25:53

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 13:26:25

Band 4_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 13:26:46

Band 4_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 13:27:02

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:27:26

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:27:54

Band 4_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:28:14

Band 4_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:28:33

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 3.JAN.2022 13:29:01

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 3.JAN.2022 13:29:24

Band 4_15 MHz_High_QPSK_RB75#0




Date: 3.JAN.2022 13:29:49

Band 4_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2022 13:30:12

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 3.JAN.2022 13:30:37

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 3.JAN.2022 13:31:01

Band 4_20 MHz_High_QPSK_RB100#0




Date: 3.JAN.2022 13:31:25

Band 4_20 MHz_High_16QAM_RB100#0




Date: 3.JAN.2022 13:31:48

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 3.JAN.2022 13:32:11

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 3.JAN.2022 13:32:28

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 3.JAN.2022 13:32:45

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 3.JAN.2022 13:33:08

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 3.JAN.2022 13:33:27

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 3.JAN.2022 13:33:43

Band 5_3 MHz_High_QPSK_RB15#0




Date: 3.JAN.2022 13:34:04

Band 5_3 MHz_High_16QAM_RB15#0




Date: 3.JAN.2022 13:34:24

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 3.JAN.2022 13:34:45

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 13:35:02

Band 5_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 13:35:19

Band 5_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 13:35:42

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:36:03

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:36:22

Band 5_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:36:45

Band 5_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:37:04

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 3.JAN.2022 13:37:22

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 13:37:39

Band 7_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 13:37:56

Band 7_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 13:38:13

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:38:33

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:38:53

Band 7_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:39:12

Band 7_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:39:31

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 3.JAN.2022 13:39:56

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 3.JAN.2022 13:40:20

Band 7_15 MHz_High_QPSK_RB75#0




Date: 3.JAN.2022 13:40:44

Band 7_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2022 13:41:07

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 3.JAN.2022 13:41:32

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 3.JAN.2022 13:41:56

Band 7_20 MHz_High_QPSK_RB100#0




Date: 3.JAN.2022 13:42:20

Band 7_20 MHz_High_16QAM_RB100#0




Date: 3.JAN.2022 13:42:43

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 3.JAN.2022 13:43:01

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 3.JAN.2022 13:43:21

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 3.JAN.2022 13:43:42

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 3.JAN.2022 13:43:59

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 3.JAN.2022 13:44:17

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 3.JAN.2022 13:44:34

Band 12_3 MHz_High_QPSK_RB15#0




Date: 3.JAN.2022 13:44:54

Band 12_3 MHz_High_16QAM_RB15#0




Date: 3.JAN.2022 13:45:14

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 4.JAN.2022 11:35:11

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 4.JAN.2022 11:36:35

Band 12_5 MHz_High_QPSK_RB25#0




Date: 4.JAN.2022 11:37:54

Band 12_5 MHz_High_16QAM_RB25#0




Date: 4.JAN.2022 11:38:42

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:46:56

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:47:15

Band 12_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:47:35

Band 12_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:47:54

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 4.JAN.2022 11:40:30

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 4.JAN.2022 11:41:55

Band 17_5 MHz_High_QPSK_RB25#0




Date: 4.JAN.2022 11:44:44

Band 17_5 MHz_High_16QAM_RB25#0




Date: 4.JAN.2022 11:45:08

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:49:27

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:49:46

Band 17_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:50:06

Band 17_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:50:25

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 3.JAN.2022 16:11:27

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 16:11:50

Band 38_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 16:12:23

Band 38_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 16:12:40

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 16:13:06

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 16:13:28

Band 38_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 16:13:54

Band 38_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 16:14:16

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 3.JAN.2022 16:14:56

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 3.JAN.2022 16:15:29

Band 38_15 MHz_High_QPSK_RB75#0




Date: 3.JAN.2022 16:15:59

Band 38_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2022 16:16:29

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 3.JAN.2022 16:17:06

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 3.JAN.2022 16:17:39

Band 38_20 MHz_High_QPSK_RB100#0




Date: 3.JAN.2022 16:18:12

Band 38_20 MHz_High_16QAM_RB100#0




Date: 3.JAN.2022 16:18:42

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 3.JAN.2022 17:53:57

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 17:54:36

Band 41_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 17:55:02

Band 41_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 17:55:22

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 17:55:49

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 17:56:11

Band 41_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 17:56:36

Band 41_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 17:56:58

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 3.JAN.2022 17:57:39

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 3.JAN.2022 17:58:11

Band 41_15 MHz_High_QPSK_RB75#0




Date: 3.JAN.2022 17:58:42

Band 41_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2022 17:59:17

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 3.JAN.2022 17:59:49

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 3.JAN.2022 18:00:18

Band 41_20 MHz_High_QPSK_RB100#0




Date: 3.JAN.2022 18:00:55

Band 41_20 MHz_High_16QAM_RB100#0




Date: 3.JAN.2022 18:01:31

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 3.JAN.2022 13:50:55

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 3.JAN.2022 13:51:18

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 3.JAN.2022 13:51:36

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 3.JAN.2022 13:51:52

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 3.JAN.2022 13:52:17

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 3.JAN.2022 13:52:43

Band 66_3 MHz_High_QPSK_RB15#0




Date: 3.JAN.2022 13:53:04

Band 66_3 MHz_High_16QAM_RB15#0




Date: 3.JAN.2022 13:53:20

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 4.JAN.2022 11:46:37

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 3.JAN.2022 13:53:55

Band 66_5 MHz_High_QPSK_RB25#0




Date: 3.JAN.2022 13:54:13

Band 66_5 MHz_High_16QAM_RB25#0




Date: 3.JAN.2022 13:54:30

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 3.JAN.2022 13:54:50

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 3.JAN.2022 13:55:09

Band 66_10 MHz_High_QPSK_RB50#0




Date: 3.JAN.2022 13:55:29

Band 66_10 MHz_High_16QAM_RB50#0




Date: 3.JAN.2022 13:55:48

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 4.JAN.2022 11:49:19

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 3.JAN.2022 13:56:51

Band 66_15 MHz_High_QPSK_RB75#0




Date: 3.JAN.2022 13:57:15

Band 66_15 MHz_High_16QAM_RB75#0




Date: 3.JAN.2022 13:57:39

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 4.JAN.2022 11:50:52

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 3.JAN.2022 13:58:43

Band 66_20 MHz_High_QPSK_RB100#0



Date: 3.JAN.2022 13:59:07

Band 66_20 MHz_High_16QAM_RB100#0



Date: 3.JAN.2022 13:59:31