



n77\_1

10MHz\_15kHz\_3455MHz\_DFT-s-OFDM QPSK\_RB1@0&-26.74 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:22:02

10MHz\_15kHz\_3455MHz\_DFT-s-OFDM QPSK\_RB50@0&-39.23 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:04:50

10MHz\_15kHz\_3545MHz\_DFT-s-OFDM QPSK\_RB1@51&-28.12 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:06:17

10MHz\_15kHz\_3545MHz\_DFT-s-OFDM QPSK\_RB50@0&-37.89 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:07:41

10MHz\_30kHz\_3455MHz\_DFT-s-OFDM QPSK\_RB1@0&-37.70 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:34:57

10MHz\_30kHz\_3455MHz\_DFT-s-OFDM QPSK\_RB24@0&-35.69 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:39:51

10MHz\_30kHz\_3545MHz\_DFT-s-OFDM QPSK\_RB1@23&-36.51 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:36:57

10MHz\_30kHz\_3545MHz\_DFT-s-OFDM QPSK\_RB24@0&-41.57 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:41:12

15MHz\_15kHz\_3457.5MHz\_DFT-s-OFDM QPSK\_RB1@0&-26.90 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:09:52

15MHz\_15kHz\_3457.5MHz\_DFT-s-OFDM QPSK\_RB75@0&-37.62 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:11:28

15MHz\_15kHz\_3542.5MHz\_DFT-s-OFDM QPSK\_RB1@78&-26.65 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:14:01

15MHz\_15kHz\_3542.5MHz\_DFT-s-OFDM QPSK\_RB75@0&-43.36 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:15:55

15MHz\_30kHz\_3457.5MHz\_DFT-s-OFDM QPSK\_RB1@0&-31.48 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:42:41

15MHz\_30kHz\_3457.5MHz\_DFT-s-OFDM QPSK\_RB36@0&-38.67 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:39:52

15MHz\_30kHz\_3542.5MHz\_DFT-s-OFDM QPSK\_RB1@37&-32.50 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:41:19

15MHz\_30kHz\_3542.5MHz\_DFT-s-OFDM QPSK\_RB36@0&-41.42 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:43:53

20MHz\_15kHz\_3460MHz\_DFT-s-OFDM QPSK\_RB1@0&-25.27 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:17:01

20MHz\_15kHz\_3460MHz\_DFT-s-OFDM QPSK\_RB100@0&-40.70 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:18:07

20MHz\_15kHz\_3540MHz\_DFT-s-OFDM QPSK\_RB1@105&-28.14 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:20:25

20MHz\_15kHz\_3540MHz\_DFT-s-OFDM QPSK\_RB100@0&-43.33 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:23:10

20MHz\_30kHz\_3460MHz\_DFT-s-OFDM QPSK\_RB1@0&-33.66 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:43:44

20MHz\_30kHz\_3460MHz\_DFT-s-OFDM QPSK\_RB50@0&-42.73 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:45:03

20MHz\_30kHz\_3540MHz\_DFT-s-OFDM QPSK\_RB1@50&-33.18 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:46:33

20MHz\_30kHz\_3540MHz\_DFT-s-OFDM QPSK\_RB50@0&-42.97 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:47:41

30MHz\_15kHz\_3465MHz\_DFT-s-OFDM QPSK\_RB1@0&-28.02 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:22:49

30MHz\_15kHz\_3465MHz\_DFT-s-OFDM QPSK\_RB160@0&-42.15 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:23:52

30MHz\_15kHz\_3535MHz\_DFT-s-OFDM QPSK\_RB1@159&-26.62 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:26:29

30MHz\_15kHz\_3535MHz\_DFT-s-OFDM QPSK\_RB160@0&-41.45 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:27:38

40MHz\_15kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB1@0&-22.81 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:32:41

40MHz\_15kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB216@0&-33.50 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:27:52

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB1@215&-41.11 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:35:08

40MHz\_15kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB216@0&-30.28 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:36:16

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB1@0&-27.77 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:47:35

40MHz\_30kHz\_3470MHz\_DFT-s-OFDM QPSK\_RB100@0&-42.70 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:50:45

40MHz\_30kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB1@105&-27.28 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:51:53

40MHz\_30kHz\_3530MHz\_DFT-s-OFDM QPSK\_RB100@0&-45.58 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:58:19

50MHz\_15kHz\_3475MHz\_DFT-s-OFDM QPSK\_RB1@0&-17.33 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:30:48

50MHz\_15kHz\_3475MHz\_DFT-s-OFDM QPSK\_RB270@0&-38.58 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:31:52

50MHz\_15kHz\_3525MHz\_DFT-s-OFDM QPSK\_RB1@269&-16.12 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:38:41

50MHz\_15kHz\_3525MHz\_DFT-s-OFDM QPSK\_RB270@0&-39.85 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:33:52

50MHz\_30kHz\_3475MHz\_DFT-s-OFDM QPSK\_RB1@0&-28.83 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:51:27

50MHz\_30kHz\_3475MHz\_DFT-s-OFDM QPSK\_RB128@0&-41.16 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:59:32

50MHz\_30kHz\_3525MHz\_DFT-s-OFDM QPSK\_RB1@132&-30.44 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:53:26

50MHz\_30kHz\_3525MHz\_DFT-s-OFDM QPSK\_RB128@0&-45.91 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:53:11

60MHz\_30kHz\_3480MHz\_DFT-s-OFDM QPSK\_RB1@0&-25.99 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:00:54

60MHz\_30kHz\_3480MHz\_DFT-s-OFDM QPSK\_RB162@0&-45.29 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:54:29

60MHz\_30kHz\_3520MHz\_DFT-s-OFDM QPSK\_RB1@161&-26.96 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:03:12


60MHz\_30kHz\_3520MHz\_DFT-s-OFDM QPSK\_RB162@0&-43.49 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 13:58:21




70MHz\_30kHz\_3485MHz\_DFT-s-OFDM QPSK\_RB1@0&-29.37 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:13:26

70MHz\_30kHz\_3485MHz\_DFT-s-OFDM QPSK\_RB180@0&-40.76 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:14:33

70MHz\_30kHz\_3515MHz\_DFT-s-OFDM QPSK\_RB1@188&-23.28 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:16:35

70MHz\_30kHz\_3515MHz\_DFT-s-OFDM QPSK\_RB180@0&-44.21 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:17:54

80MHz\_30kHz\_3490MHz\_DFT-s-OFDM QPSK\_RB1@0&-26.25 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:08:44

80MHz\_30kHz\_3490MHz\_DFT-s-OFDM QPSK\_RB216@0&-30.73 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:10:47

80MHz\_30kHz\_3510MHz\_DFT-s-OFDM QPSK\_RB1@216&-22.17 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:19:15

80MHz\_30kHz\_3510MHz\_DFT-s-OFDM QPSK\_RB216@0&-38.85 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:18:53

90MHz\_30kHz\_3495MHz\_DFT-s-OFDM QPSK\_RB1@0&-38.08 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:24:41

90MHz\_30kHz\_3495MHz\_DFT-s-OFDM QPSK\_RB243@0&-28.13 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 14:04:23

90MHz\_30kHz\_3505MHz\_DFT-s-OFDM QPSK\_RB1@244&-24.50 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:21:00

90MHz\_30kHz\_3505MHz\_DFT-s-OFDM QPSK\_RB243@0&-44.45 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 14:06:23

100MHz\_30kHz\_3500MHz\_DFT-s-OFDM QPSK\_RB1@0&-20.04 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:35:36


100MHz\_30kHz\_3500MHz\_DFT-s-OFDM QPSK\_RB270@0&-28.16 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:36:48


n77\_2

10MHz\_15kHz\_3705MHz\_DFT-s-OFDM QPSK\_RB1@0&-29.72 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:37:58

10MHz\_15kHz\_3705MHz\_DFT-s-OFDM QPSK\_RB50@0&-37.85 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:39:07

10MHz\_15kHz\_3975MHz\_DFT-s-OFDM QPSK\_RB1@51&-13.58 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:16:32

10MHz\_15kHz\_3975MHz\_DFT-s-OFDM QPSK\_RB50@0&-34.60 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:18:23

10MHz\_30kHz\_3705MHz\_DFT-s-OFDM QPSK\_RB1@0&-36.08 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:37:38

10MHz\_30kHz\_3705MHz\_DFT-s-OFDM QPSK\_RB24@0&-37.96 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:38:51

10MHz\_30kHz\_3975MHz\_DFT-s-OFDM QPSK\_RB1@23&-31.93 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:30:52

10MHz\_30kHz\_3975MHz\_DFT-s-OFDM QPSK\_RB24@0&-36.37 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:43:08

15MHz\_15kHz\_3707.5MHz\_DFT-s-OFDM QPSK\_RB1@0&-27.13 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:43:43

15MHz\_15kHz\_3707.5MHz\_DFT-s-OFDM QPSK\_RB75@0&-39.32 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:45:40

15MHz\_15kHz\_3972.5MHz\_DFT-s-OFDM QPSK\_RB1@78&-15.94 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:47:51

15MHz\_15kHz\_3972.5MHz\_DFT-s-OFDM QPSK\_RB75@0&-38.19 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:48:58

15MHz\_30kHz\_3707.5MHz\_DFT-s-OFDM QPSK\_RB1@0&-30.51 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:44:19

15MHz\_30kHz\_3707.5MHz\_DFT-s-OFDM QPSK\_RB36@0&-43.05 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:08:20

15MHz\_30kHz\_3972.5MHz\_DFT-s-OFDM QPSK\_RB1@37&-32.37 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:32:00

15MHz\_30kHz\_3972.5MHz\_DFT-s-OFDM QPSK\_RB36@0&-35.21 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:33:03

20MHz\_15kHz\_3710MHz\_DFT-s-OFDM QPSK\_RB1@0&-24.29 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:22:55

20MHz\_15kHz\_3710MHz\_DFT-s-OFDM QPSK\_RB100@0&-40.39 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:51:33

20MHz\_15kHz\_3970MHz\_DFT-s-OFDM QPSK\_RB1@105&-20.05 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:53:44

20MHz\_15kHz\_3970MHz\_DFT-s-OFDM QPSK\_RB100@0&-39.75 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:24:25

20MHz\_30kHz\_3710MHz\_DFT-s-OFDM QPSK\_RB1@0&-33.35 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:12:46

20MHz\_30kHz\_3710MHz\_DFT-s-OFDM QPSK\_RB50@0&-40.75 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:23:47

20MHz\_30kHz\_3970MHz\_DFT-s-OFDM QPSK\_RB1@50&-33.90 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:47:26

20MHz\_30kHz\_3970MHz\_DFT-s-OFDM QPSK\_RB50@0&-37.11 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:28:29

30MHz\_15kHz\_3715MHz\_DFT-s-OFDM QPSK\_RB1@0&-28.12 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:55:55

30MHz\_15kHz\_3715MHz\_DFT-s-OFDM QPSK\_RB160@0&-40.31 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:57:02

30MHz\_15kHz\_3965MHz\_DFT-s-OFDM QPSK\_RB1@159&-23.23 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 17:59:39

30MHz\_15kHz\_3965MHz\_DFT-s-OFDM QPSK\_RB160@0&-38.39 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 18:00:50

40MHz\_15kHz\_3720MHz\_DFT-s-OFDM QPSK\_RB1@0&-35.10 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 18:18:02


40MHz\_15kHz\_3720MHz\_DFT-s-OFDM QPSK\_RB216@0&-32.80 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:25:46




40MHz\_15kHz\_3960MHz\_DFT-s-OFDM QPSK\_RB1@215&-27.87 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:29:21

40MHz\_15kHz\_3960MHz\_DFT-s-OFDM QPSK\_RB16@0&-30.40 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:29:26

40MHz\_30kHz\_3720MHz\_DFT-s-OFDM QPSK\_RB1@0&-28.73 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:29:46

40MHz\_30kHz\_3720MHz\_DFT-s-OFDM QPSK\_RB100@0&-41.36 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:31:08

40MHz\_30kHz\_3960MHz\_DFT-s-OFDM QPSK\_RB1@105&-28.60 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:49:57

40MHz\_30kHz\_3960MHz\_DFT-s-OFDM QPSK\_RB100@0&-40.74 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:35:44

50MHz\_15kHz\_3725MHz\_DFT-s-OFDM QPSK\_RB1@0&-25.02 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:31:12

50MHz\_15kHz\_3725MHz\_DFT-s-OFDM QPSK\_RB270@0&-39.11 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:33:03

50MHz\_15kHz\_3955MHz\_DFT-s-OFDM QPSK\_RB1@269&-18.44 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:34:52

50MHz\_15kHz\_3955MHz\_DFT-s-OFDM QPSK\_RB270@0&-39.45 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:36:20

50MHz\_30kHz\_3725MHz\_DFT-s-OFDM QPSK\_RB1@0&-26.78 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 19:36:51

50MHz\_30kHz\_3725MHz\_DFT-s-OFDM QPSK\_RB128@0&-38.97 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:38:01

50MHz\_30kHz\_3955MHz\_DFT-s-OFDM QPSK\_RB1@132&-26.95 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:51:08

50MHz\_30kHz\_3955MHz\_DFT-s-OFDM QPSK\_RB128@0&-40.02 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:41:28

60MHz\_30kHz\_3730MHz\_DFT-s-OFDM QPSK\_RB1@0&-24.07 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:42:58

60MHz\_30kHz\_3730MHz\_DFT-s-OFDM QPSK\_RB162@0&-41.40 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:52:26

60MHz\_30kHz\_3950MHz\_DFT-s-OFDM QPSK\_RB1@161&-25.93 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:50:12

60MHz\_30kHz\_3950MHz\_DFT-s-OFDM QPSK\_RB162@0&-41.06 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:54:01

70MHz\_30kHz\_3735MHz\_DFT-s-OFDM QPSK\_RB1@0&-34.57 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:55:59

70MHz\_30kHz\_3735MHz\_DFT-s-OFDM QPSK\_RB180@0&-43.19 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:34:08

70MHz\_30kHz\_3945MHz\_DFT-s-OFDM QPSK\_RB1@188&-25.51 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 20:59:31

70MHz\_30kHz\_3945MHz\_DFT-s-OFDM QPSK\_RB180@0&-42.09 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:00:49

80MHz\_30kHz\_3740MHz\_DFT-s-OFDM QPSK\_RB1@0&-22.16 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:02:23

80MHz\_30kHz\_3740MHz\_DFT-s-OFDM QPSK\_RB216@0&-32.81 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:53:55

80MHz\_30kHz\_3940MHz\_DFT-s-OFDM QPSK\_RB1@216&-23.40 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:03:41

80MHz\_30kHz\_3940MHz\_DFT-s-OFDM QPSK\_RB216@0&-41.90 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 15:57:33

90MHz\_30kHz\_3745MHz\_DFT-s-OFDM QPSK\_RB1@0&-23.46 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:00:37

90MHz\_30kHz\_3745MHz\_DFT-s-OFDM QPSK\_RB243@0&-27.41 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:02:01

90MHz\_30kHz\_3935MHz\_DFT-s-OFDM QPSK\_RB1@244&-22.32 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:05:07

90MHz\_30kHz\_3935MHz\_DFT-s-OFDM QPSK\_RB243@0&-41.96 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:05:33

100MHz\_30kHz\_3750MHz\_DFT-s-OFDM QPSK\_RB1@0&-24.50 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:06:36

100MHz\_30kHz\_3750MHz\_DFT-s-OFDM QPSK\_RB270@0&-31.06 dBm




ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 21.JAN.2024 16:07:38

100MHz\_30kHz\_3930MHz\_DFT-s-OFDM QPSK\_RB1@272&-20.78 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:10:08

100MHz\_30kHz\_3930MHz\_DFT-s-OFDM QPSK\_RB270@0&-42.51 dBm



ProjectNo.:CR231167220-RF Tester:One Luo  
Date: 23.JAN.2024 21:12:23