




20MHz_30kHz_2679.99MHz_CP-OFDM 16 QAM_RB51@0&18.177 MHz




20MHz_30kHz_2679.99MHz_CP-OFDM 256 QAM_RB51@0&18.177 MHz




20MHz_30kHz_2679.99MHz_CP-OFDM 64 QAM_RB51@0&18.179 MHz




20MHz_30kHz_2679.99MHz_CP-OFDM QPSK_RB51@0&18.204 MHz



20MHz_30kHz_2679.99MHz_DFT-s-OFDM 16 QAM_RB50@0&18.052 MHz




20MHz_30kHz_2679.99MHz_DFT-s-OFDM 256 QAM_RB50@0&18.011 MHz




20MHz_30kHz_2679.99MHz_DFT-s-OFDM 64 QAM_RB50@0&18.048 MHz




20MHz_30kHz_2679.99MHz_DFT-s-OFDM PI/2 BPSK_RB50@0&18.088 MHz




20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB50@0&18.052 MHz




30MHz_30kHz_2511MHz_CP-OFDM 16 QAM_RB78@0&27.840 MHz




30MHz_30kHz_2511MHz_CP-OFDM 256 QAM_RB78@0&27.842 MHz



30MHz_30kHz_2511MHz_CP-OFDM 64 QAM_RB78@0&27.804 MHz




30MHz_30kHz_2511MHz_CP-OFDM QPSK_RB78@0&27.796 MHz




30MHz_30kHz_2511MHz_DFT-s-OFDM 16 QAM_RB75@0&27.493 MHz




30MHz_30kHz_2511MHz_DFT-s-OFDM 256 QAM_RB75@0&27.553 MHz




30MHz_30kHz_2511MHz_DFT-s-OFDM 64 QAM_RB75@0&27.541 MHz




30MHz_30kHz_2511MHz_DFT-s-OFDM PI/2 BPSK_RB75@0&27.492 MHz




30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB75@0&27.547 MHz




30MHz_30kHz_2592.99MHz_CP-OFDM 16 QAM_RB78@0&27.845 MHz




30MHz_30kHz_2592.99MHz_CP-OFDM 256 QAM_RB78@0&27.794 MHz




30MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB78@0&27.794 MHz




30MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB78@0&27.805 MHz




30MHz_30kHz_2592.99MHz_DFT-s-OFDM 16 QAM_RB75@0&27.542 MHz




30MHz_30kHz_2592.99MHz_DFT-s-OFDM 256 QAM_RB75@0&27.548 MHz




30MHz_30kHz_2592.99MHz_DFT-s-OFDM 64 QAM_RB75@0&27.486 MHz




30MHz_30kHz_2592.99MHz_DFT-s-OFDM PI/2 BPSK_RB75@0&27.435 MHz




30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB75@0&27.499 MHz




30MHz_30kHz_2674.98MHz_CP-OFDM 16 QAM_RB78@0&27.854 MHz




30MHz_30kHz_2674.98MHz_CP-OFDM 256 QAM_RB78@0&27.804 MHz




30MHz_30kHz_2674.98MHz_CP-OFDM 64 QAM_RB78@0&27.806 MHz




30MHz_30kHz_2674.98MHz_CP-OFDM QPSK_RB78@0&27.808 MHz




30MHz_30kHz_2674.98MHz_DFT-s-OFDM 16 QAM_RB75@0&27.617 MHz




30MHz_30kHz_2674.98MHz_DFT-s-OFDM 256 QAM_RB75@0&27.689 MHz




30MHz_30kHz_2674.98MHz_DFT-s-OFDM 64 QAM_RB75@0&27.630 MHz




30MHz_30kHz_2674.98MHz_DFT-s-OFDM PI/2 BPSK_RB75@0&27.611 MHz




30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB75@0&27.673 MHz




40MHz_30kHz_2516.01MHz_CP-OFDM 16 QAM_RB106@0&37.720 MHz




40MHz_30kHz_2516.01MHz_CP-OFDM 256 QAM_RB106@0&37.781 MHz




40MHz_30kHz_2516.01MHz_CP-OFDM 64 QAM_RB106@0&37.762 MHz




40MHz_30kHz_2516.01MHz_CP-OFDM QPSK_RB106@0&37.732 MHz




40MHz_30kHz_2516.01MHz_DFT-s-OFDM 16 QAM_RB100@0&37.409 MHz




40MHz_30kHz_2516.01MHz_DFT-s-OFDM 256 QAM_RB100@0&37.501 MHz




40MHz_30kHz_2516.01MHz_DFT-s-OFDM 64 QAM_RB100@0&37.506 MHz




40MHz_30kHz_2516.01MHz_DFT-s-OFDM PI/2 BPSK_RB100@0&37.451 MHz




40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB100@0&37.443 MHz




40MHz_30kHz_2592.99MHz_CP-OFDM 16 QAM_RB106@0&37.725 MHz




40MHz_30kHz_2592.99MHz_CP-OFDM 256 QAM_RB106@0&37.780 MHz



40MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB106@0&37.767 MHz




40MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB106@0&37.773 MHz




40MHz_30kHz_2592.99MHz_DFT-s-OFDM 16 QAM_RB100@0&37.338 MHz




40MHz_30kHz_2592.99MHz_DFT-s-OFDM 256 QAM_RB100@0&37.301 MHz




40MHz_30kHz_2592.99MHz_DFT-s-OFDM 64 QAM_RB100@0&37.340 MHz




40MHz_30kHz_2592.99MHz_DFT-s-OFDM PI/2 BPSK_RB100@0&37.356 MHz




40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB100@0&37.404 MHz




40MHz_30kHz_2670MHz_CP-OFDM 16 QAM_RB106@0&37.774 MHz




40MHz_30kHz_2670MHz_CP-OFDM 256 QAM_RB106@0&37.823 MHz




40MHz_30kHz_2670MHz_CP-OFDM 64 QAM_RB106@0&37.778 MHz




40MHz_30kHz_2670MHz_CP-OFDM QPSK_RB106@0&37.784 MHz




40MHz_30kHz_2670MHz_DFT-s-OFDM 16 QAM_RB100@0&37.612 MHz




40MHz_30kHz_2670MHz_DFT-s-OFDM 256 QAM_RB100@0&37.463 MHz




40MHz_30kHz_2670MHz_DFT-s-OFDM 64 QAM_RB100@0&37.515 MHz




40MHz_30kHz_2670MHz_DFT-s-OFDM PI/2 BPSK_RB100@0&37.660 MHz




40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB100@0&37.551 MHz




50MHz_30kHz_2521.02MHz_CP-OFDM 16 QAM_RB133@0&47.354 MHz




50MHz_30kHz_2521.02MHz_CP-OFDM 256 QAM_RB133@0&47.373 MHz




50MHz_30kHz_2521.02MHz_CP-OFDM 64 QAM_RB133@0&47.367 MHz



50MHz_30kHz_2521.02MHz_CP-OFDM QPSK_RB133@0&47.359 MHz




50MHz_30kHz_2521.02MHz_DFT-s-OFDM 16 QAM_RB128@0&46.761 MHz




50MHz_30kHz_2521.02MHz_DFT-s-OFDM 256 QAM_RB128@0&46.813 MHz




50MHz_30kHz_2521.02MHz_DFT-s-OFDM 64 QAM_RB128@0&46.867 MHz




50MHz_30kHz_2521.02MHz_DFT-s-OFDM PI/2 BPSK_RB128@0&46.951 MHz




50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB128@0&46.900 MHz




50MHz_30kHz_2592.99MHz_CP-OFDM 16 QAM_RB133@0&47.366 MHz




50MHz_30kHz_2592.99MHz_CP-OFDM 256 QAM_RB133@0&47.413 MHz



50MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB133@0&47.406 MHz




50MHz_30kHz_2592.99MHz_CP-OFDM QPSK_RB133@0&47.400 MHz



50MHz_30kHz_2592.99MHz_DFT-s-OFDM 16 QAM_RB128@0&46.774 MHz




50MHz_30kHz_2592.99MHz_DFT-s-OFDM 256 QAM_RB128@0&46.817 MHz



50MHz_30kHz_2592.99MHz_DFT-s-OFDM 64 QAM_RB128@0&46.869 MHz




50MHz_30kHz_2592.99MHz_DFT-s-OFDM 1/2 BPSK_RB128@0&46.866 MHz




50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB128@0&46.971 MHz




50MHz_30kHz_2664.99MHz_CP-OFDM 16 QAM_RB133@0&47.422 MHz




50MHz_30kHz_2664.99MHz_CP-OFDM 256 QAM_RB133@0&47.456 MHz




50MHz_30kHz_2664.99MHz_CP-OFDM 64 QAM_RB133@0&47.417 MHz




50MHz_30kHz_2664.99MHz_CP-OFDM QPSK_RB133@0&47.411 MHz




50MHz_30kHz_2664.99MHz_DFT-s-OFDM 16 QAM_RB128@0&47.065 MHz




50MHz_30kHz_2664.99MHz_DFT-s-OFDM 256 QAM_RB128@0&47.067 MHz




50MHz_30kHz_2664.99MHz_DFT-s-OFDM 64 QAM_RB128@0&47.161 MHz




50MHz_30kHz_2664.99MHz_DFT-s-OFDM PI/2 BPSK_RB128@0&47.124 MHz




50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB128@0&47.216 MHz




60MHz_30kHz_2526MHz_CP-OFDM 16 QAM_RB162@0&57.726 MHz




60MHz_30kHz_2526MHz_CP-OFDM 256 QAM_RB162@0&57.683 MHz




60MHz_30kHz_2526MHz_CP-OFDM 64 QAM_RB162@0&57.674 MHz




60MHz_30kHz_2526MHz_CP-OFDM QPSK_RB162@0&57.672 MHz




60MHz_30kHz_2526MHz_DFT-s-OFDM 16 QAM_RB162@0&57.746 MHz




60MHz_30kHz_2526MHz_DFT-s-OFDM 256 QAM_RB162@0&57.688 MHz




60MHz_30kHz_2526MHz_DFT-s-OFDM 64 QAM_RB162@0&57.687 MHz




60MHz_30kHz_2526MHz_DFT-s-OFDM PI/2 BPSK_RB162@0&57.725 MHz




60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB162@0&57.685 MHz



60MHz_30kHz_2592.99MHz_CP-OFDM 16 QAM_RB162@0&57.732 MHz



60MHz_30kHz_2592.99MHz_CP-OFDM 256 QAM_RB162@0&57.720 MHz



60MHz_30kHz_2592.99MHz_CP-OFDM 64 QAM_RB162@0&57.680 MHz

