




n41_20MHz_30kHz_2679.99MHz_CP-OFDM 16
QAM_RB51@0 18.173MHz




n41_20MHz_30kHz_2679.99MHz_CP-OFDM 64
QAM_RB51@0 18.195MHz



n41_20MHz_30kHz_2679.99MHz_CP-OFDM 256
QAM_RB51@0 18.180MHz




n41_30MHz_30kHz_2511MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.629MHz




n41_30MHz_30kHz_2511MHz_DFT-s-OFDM
QPSK_RB75@0 27.602MHz




n41_30MHz_30kHz_2511MHz_DFT-s-OFDM 16
QAM_RB75@0 27.750MHz




n41_30MHz_30kHz_2511MHz_DFT-s-OFDM 64
QAM_RB75@0 27.740MHz




n41_30MHz_30kHz_2511MHz_DFT-s-OFDM 256
QAM_RB75@0 27.536MHz




n41_30MHz_30kHz_2511MHz_CP-OFDM QPSK_RB78@0
27.865MHz




n41_30MHz_30kHz_2511MHz_CP-OFDM 16
QAM_RB78@0 27.775MHz






n41_30MHz_30kHz_2511MHz_CP-OFDM 64
QAM_RB78@0 27.772MHz




n41_30MHz_30kHz_2511MHz_CP-OFDM 256
QAM_RB78@0 27.775MHz




n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM
QPSK RB75@0 27.506MHz

n41_30MHz_30kHz_2592.99MHz_DFT-s-OFDM 64
QAM RB75@0 27.609MHzn41_30MHz_30kHz_2592.99MHz_CP-OFDM
OPSK RB78@0 27.857MHz


n41_30MHz_30kHz_2592.99MHz_CP-OFDM 16
QAM_RB78@0 27.773MHz




n41_30MHz_30kHz_2592.99MHz_CP-OFDM 64
QAM_RB78@0 27.763MHz




n41_30MHz_30kHz_2592.99MHz_CP-OFDM 256
QAM_RB78@0 27.766MHz



n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM $\pi/2$
BPSK_RB75@0 27.617MHz




n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM
QPSK_RB75@0 27.652MHz




n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM 16
QAM_RB75@0 27.778MHz



n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM 64
QAM_RB75@0 27.744MHz




n41_30MHz_30kHz_2674.98MHz_DFT-s-OFDM 256
QAM_RB75@0 27.637MHz




n41_30MHz_30kHz_2674.98MHz_CP-OFDM
QPSK_RB78@0 27.873MHz



n41_30MHz_30kHz_2674.98MHz_CP-OFDM 16
QAM_RB78@0 27.883MHz




n41_30MHz_30kHz_2674.98MHz_CP-OFDM 64
QAM_RB78@0 27.770MHz




n41_30MHz_30kHz_2674.98MHz_CP-OFDM 256
QAM_RB78@0 27.849MHz




n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM $\pi/2$
BPSK_RB100@0 37.465MHz




n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM
QPSK_RB100@0 37.484MHz



n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM 16
QAM_RB100@0 37.286MHz



n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM 64
QAM_RB100@0 37.198MHz



n41_40MHz_30kHz_2516.01MHz_DFT-s-OFDM 256
QAM_RB100@0 37.292MHz



n41_40MHz_30kHz_2516.01MHz_CP-OFDM
QPSK_RB106@0 37.767MHz

