

The difference between the 1# prototype and the 2# prototype is that the component layout and components of the power supply circuit are inconsistent.

The report only embodies the test data of the 2# prototype #1 refer to original test report NO.CQASZ20220701193E