






Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz






Plot on Channel 6865 MHz




05:00:08 PM 12/21/2023

Plot on Channel 6945 MHz



05:11:53 PM 12/21/2023

Plot on Channel 7025 MHz




05:17:30 PM 12/21/2023




EUT Mode 802.11be EHT160 Full RU


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz





Plot on Channel 6665 MHz





Plot on Channel 6825 MHz


Plot on Channel 6985 MHz






EUT Mode 802.11be EHT160 106OFDMA RU16


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz






Plot on Channel 6825 MHz

Plot on Channel 6985 MHz



02:04:50 PM 12/21/2023




02:07:15 PM 12/21/2023




EUT Mode 802.11be EHT160 Puncture20 1


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz





Plot on Channel 6665 MHz





Plot on Channel 6825 MHz


Plot on Channel 6985 MHz






EUT Mode 802.11be EHT160 Puncture40 1

Plot on Channel 6185 MHz




08:25:56 PM 12/21/2023

Plot on Channel 6345 MHz




08:34:00 PM 12/21/2023

Plot on Channel 6505 MHz



08:38:24 PM 12/21/2023

Plot on Channel 6665 MHz




08:51:00 PM 12/21/2023




Plot on Channel 6825 MHz

Plot on Channel 6985 MHz



08:56:22 PM 12/21/2023




09:01:02 PM 12/21/2023




EUT Mode 802.11be EHT320 Full RU


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz






Plot on Channel 6905 MHz






EUT Mode 802.11be EHT320 242OFDMA RU16


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz




03:07:28 PM 12/21/2023




EUT Mode 802.11be EHT320 Puncture40 1


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz






Plot on Channel 6905 MHz






EUT Mode 802.11be EHT320 Puncture80 1


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz




11:31:45 AM 12/22/2023




EUT Mode 802.11be EHT320 Puncture80+40 7


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz



Plot on Channel 6745 MHz





Plot on Channel 6905 MHz

