





Plot on Channel 6545 MHz




03:26:34 PM 12/18/2023

Plot on Channel 6625 MHz




03:35:06 PM 12/18/2023

Plot on Channel 6705 MHz



03:38:25 PM 12/18/2023


Plot on Channel 6785 MHz




03:41:58 PM 12/18/2023




Plot on Channel 6865 MHz



Plot on Channel 6945 MHz




Plot on Channel 7025 MHz






EUT Mode 802.11be EHT80 52OFDMA RU16

Plot on Channel 6145 MHz




11:55:46 AM 12/21/2023

Plot on Channel 6305 MHz




11:58:06 AM 12/21/2023

Plot on Channel 6385 MHz



11:59:53 AM 12/21/2023


Plot on Channel 6465 MHz




12:01:25 PM 12/21/2023




Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz







Plot on Channel 6865 MHz



Plot on Channel 6945 MHz




Plot on Channel 7025 MHz






EUT Mode 802.11be EHT80 Puncture20 1


Plot on Channel 6145 MHz




Plot on Channel 6305 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz







Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz







Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz









EUT Mode 802.11be EHT160 Full RU


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz






Plot on Channel 6825 MHz

Plot on Channel 6985 MHz



05:12:19 PM 12/18/2023




05:17:06 PM 12/18/2023




EUT Mode 802.11be EHT160 106OFDMA RU16


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz





Plot on Channel 6825 MHz


Plot on Channel 6985 MHz






EUT Mode 802.11be EHT160 Puncture20 1


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz






Plot on Channel 6825 MHz

Plot on Channel 6985 MHz



08:08:44 PM 12/21/2023




08:15:51 PM 12/21/2023




EUT Mode 802.11be EHT160 Puncture40 1


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz




Plot on Channel 6665 MHz






Plot on Channel 6825 MHz

Plot on Channel 6985 MHz



09:01:18 PM 12/21/2023




09:05:58 PM 12/21/2023






EUT Mode 802.11be EHT320 Full RU


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz



04:20:21 PM 12/19/2023