





EUT Mode 802.11be EHT320 242OFDMA RU16


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz




03:12:22 PM 12/21/2023




EUT Mode 802.11be EHT320 Puncture40 1


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz




10:30:14 AM 12/22/2023




EUT Mode 802.11be EHT320 Puncture80 1


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz




11:36:40 AM 12/22/2023




EUT Mode 802.11be EHT320 Puncture80+40 7


Plot on Channel 6265 MHz




Plot on Channel 6425 MHz



Plot on Channel 6585 MHz




Plot on Channel 6745 MHz





Plot on Channel 6905 MHz









MIMO <Ant. 5+6+7+8(8)>

EUT Mode 802.11be EHT20 Full RU


Plot on Channel 6115 MHz




Plot on Channel 6275 MHz



Plot on Channel 6415 MHz




Plot on Channel 6435 MHz






Plot on Channel 6475 MHz




04:11:20 AM 12/18/2023

Plot on Channel 6515 MHz




04:18:45 AM 12/18/2023

Plot on Channel 6535 MHz



04:24:19 AM 12/18/2023


Plot on Channel 6695 MHz




04:27:59 AM 12/18/2023




Plot on Channel 6855 MHz




Plot on Channel 6875 MHz



Plot on Channel 6895 MHz



Plot on Channel 6995 MHz






Plot on Channel 7095 MHz

Plot on Channel 7115 MHz



04:56:45 AM 12/18/2023




03:23:50 AM 12/21/2023




EUT Mode 802.11be EHT20 52OFDMA RU4


Plot on Channel 6115 MHz




Plot on Channel 6275 MHz



Plot on Channel 6415 MHz




Plot on Channel 6435 MHz







Plot on Channel 6475 MHz




Plot on Channel 6515 MHz



Plot on Channel 6535 MHz




Plot on Channel 6695 MHz






Plot on Channel 6855 MHz




02:52:23 AM 12/21/2023

Plot on Channel 6875 MHz




02:54:21 AM 12/21/2023

Plot on Channel 6895 MHz



02:55:42 AM 12/21/2023

Plot on Channel 6995 MHz




02:56:52 AM 12/21/2023




Plot on Channel 7095 MHz

Plot on Channel 7115 MHz



02:59:13 AM 12/21/2023




03:32:10 AM 12/21/2023






EUT Mode 802.11be EHT40 Full RU


Plot on Channel 6125 MHz




Plot on Channel 6285 MHz



Plot on Channel 6405 MHz




Plot on Channel 6445 MHz







Plot on Channel 6485 MHz




Plot on Channel 6525 MHz



Plot on Channel 6565 MHz




Plot on Channel 6685 MHz







Plot on Channel 6845 MHz



Plot on Channel 6885 MHz



Plot on Channel 6925 MHz



Plot on Channel 7005 MHz

