




Plot on Channel 7085 MHz




08:03:55 AM 12/18/2023




EUT Mode 802.11be EHT40 52OFDMA RU8


Plot on Channel 6125 MHz




Plot on Channel 6285 MHz



Plot on Channel 6405 MHz



Plot on Channel 6445 MHz






Plot on Channel 6485 MHz




Plot on Channel 6525 MHz



Plot on Channel 6565 MHz




Plot on Channel 6685 MHz







Plot on Channel 6845 MHz




Plot on Channel 6885 MHz



Plot on Channel 6925 MHz




Plot on Channel 7005 MHz





Plot on Channel 7085 MHz




04:48:27 AM 12/21/2023




EUT Mode 802.11be EHT80 Full RU


Plot on Channel 6145 MHz




Plot on Channel 6305 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz






Plot on Channel 6545 MHz




08:25:54 AM 12/18/2023

Plot on Channel 6625 MHz




08:34:26 AM 12/18/2023

Plot on Channel 6705 MHz



08:37:45 AM 12/18/2023


Plot on Channel 6785 MHz




08:41:18 AM 12/18/2023




Plot on Channel 6865 MHz



Plot on Channel 6945 MHz



Plot on Channel 7025 MHz









EUT Mode 802.11be EHT80 52OFDMA RU16


Plot on Channel 6145 MHz




Plot on Channel 6305 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz







Plot on Channel 6545 MHz




Plot on Channel 6625 MHz



Plot on Channel 6705 MHz




Plot on Channel 6785 MHz







Plot on Channel 6865 MHz



Plot on Channel 6945 MHz




Plot on Channel 7025 MHz






EUT Mode 802.11be EHT80 Puncture20 1


Plot on Channel 6145 MHz




Plot on Channel 6305 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz






Plot on Channel 6545 MHz




09:42:20 AM 12/21/2023

Plot on Channel 6625 MHz




09:48:21 AM 12/21/2023

Plot on Channel 6705 MHz



09:53:27 AM 12/21/2023


Plot on Channel 6785 MHz




09:58:55 AM 12/21/2023




Plot on Channel 6865 MHz



Plot on Channel 6945 MHz




Plot on Channel 7025 MHz






EUT Mode 802.11be EHT160 Full RU


Plot on Channel 6185 MHz




Plot on Channel 6345 MHz



Plot on Channel 6505 MHz





Plot on Channel 6665 MHz





Plot on Channel 6825 MHz

Plot on Channel 6985 MHz









EUT Mode 802.11be EHT160 106OFDMA RU16

Plot on Channel 6185 MHz




07:00:38 AM 12/21/2023

Plot on Channel 6345 MHz




07:03:17 AM 12/21/2023

Plot on Channel 6505 MHz



07:05:23 AM 12/21/2023

Plot on Channel 6665 MHz




07:07:18 AM 12/21/2023




Plot on Channel 6825 MHz

Plot on Channel 6985 MHz



07:09:04 AM 12/21/2023



07:11:33 AM 12/21/2023