

英日说明书 HRM802 COOSPO

材料:80克光道林纸 单色双面印刷 上下对折+风琴折








折法:上下对折+风琴折

第一步:上下对折



版本	版本说明	修改日期	修改人	审核
A	生产	2021/05/14	郑春阳	谢海亮
I		· ·		I
品名	说明书 HRM802			



	月书 HRM802 90x		RM802		
单色双面	面印刷 风琴折(CO	物料编号/文件 53.	编号 HRM802-0001-00		
制图	日期	页次 ,	比例	图档名	
郑春阳	2021/05/14	1/1	1:1	53.	HRM802-0001-00
^{审核} 谢海亮 ^{核准}	日期 2021/05/14 日期	<mark>深圳</mark> ī Shenzh	市汇泰 nen Fitca	科电子 re Electr	• 有限公司 onics Co.,Ltd.

NOTE: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.

- Increase the separation between the equipment and receiver.

-Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.

-Consult the dealer or an experienced radio/TV technician for help

Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

(1) this device may not cause harmful interference, and

(2) this device must accept any interference received, including interference that may cause undesired operation.