


Innovative Technology Electronics LLC  
Address: 1 Channel Drive, Port Washington, NY 11050, USA  
Tel: 1-516-883-8220  
Fax: 1-516-883-8838  
Email: [alfonso@victrola.com](mailto:alfonso@victrola.com)

Date: 2020/08/13

To whom it may concern:

The RF chip, model BK3266, which installed in our product VICTROLA LINDEN, Model: VRS-5000, FCC ID: 2AFHW-VRS5000, supports BDR (GFSK), EDR ( $\pi/4$ -DQPSK, 8DPSK), and BLE functions. For use in America and this chip will not support/enable BLE function. The BLE function has been shielded by the manufacturer using the software.

Sincerely Yours,

A handwritten signature in cursive script that reads "Alfonso Minopoli".

Alfonso Minopoli

Compliance & Quality Manager