






EUT PHOTO(Internal Photos)


Test Model: SK-32WD










BT module being shielded, the PCB ANT does not work.

The product has BT module in the designer, the product does not need BT module in use, The BT module has being shielded.









***** END OF REPORT *****