

Telecommunication Certification Body UL VS Ltd Units 1-3, Horizon Wade Road Kingsland Business Park Basingstoke Hampshire RG24 8AH United Kingdom

ROLI 2 Glebe Rd London E8 4BD +44 (0)207 254 2155 www.roli.com

16/10/2019

Subject: Tune-Up Information (Transmitter Power Output Tolerance)

FCC Number: 2AFT3-LKB01

To whom it may concern

We, ROLI Ltd., hereby attest that the LKB01 has the following transmitter maximum conducted output power, with tune up tolerance that is set in the factory, to be:

0 dBm (+ 4 / - 4 dB)

Once the devices have left the factory, the user does not have access to the devices to alter the output power.

Yours faithfully,

**Christopher Slater** 

Hardware Engineering Manager

C. Storter