




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_QPSK\_2685MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_16\_QAM\_2501.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_16\_QAM\_2685MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_64\_QAM\_2501.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_64\_QAM\_2685MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_256\_QAM\_2501.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_10MHz\_CP-OFDM\_256\_QAM\_2685MHz\_Outer\_Full\_Ant2




3.2.2 30k\_SISO\_15MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_QPSK\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_QPSK\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_16\_QAM\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41 30kHz SISO NTN 15MHz DFT-s-OFDM 16 QAM 2682.48MHz Outer Full Ant2




n41 30kHz SISO NTN 15MHz DFT-s-OFDM 64 QAM 2503.5MHz Outer Full Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_64\_QAM\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_256\_QAM\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_DFT-s-OFDM\_256\_QAM\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_QPSK\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_QPSK\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_16\_QAM\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_16\_QAM\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_64\_QAM\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_64\_QAM\_2682.48MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_256\_QAM\_2503.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_15MHz\_CP-OFDM\_256\_QAM\_2682.48MHz\_Outer\_Full\_Ant2




3.2.3 30k\_SISO\_20MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_QPSK\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_QPSK\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_16\_QAM\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_16\_QAM\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_64\_QAM\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_64\_QAM\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_256\_QAM\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_DFT-s-OFDM\_256\_QAM\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_QPSK\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_QPSK\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_16\_QAM\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_16\_QAM\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_64\_QAM\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_64\_QAM\_2679.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_256\_QAM\_2506.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_20MHz\_CP-OFDM\_256\_QAM\_2679.99MHz\_Outer\_Full\_Ant2




3.2.4 30k\_SISO\_25MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM PI/2 BPSK\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM QPSK\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_QPSK\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_16\_QAM\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_16\_QAM\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_64\_QAM\_2508.51MHz\_Outer\_Full\_Ant2




n41 30kHz SISO NTN 25MHz DFT-s-OFDM 64 QAM 2592.99MHz Outer Full Ant2




n41 30kHz SISO NTN 25MHz DFT-s-OFDM 64 QAM 2677.5MHz Outer Full Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_256\_QAM\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_DFT-s-OFDM\_256\_QAM\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_QPSK\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_QPSK\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_16\_QAM\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_16\_QAM\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_64\_QAM\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_64\_QAM\_2677.5MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_256\_QAM\_2508.51MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_25MHz\_CP-OFDM\_256\_QAM\_2677.5MHz\_Outer\_Full\_Ant2




3.2.5 30k\_SISO\_30MHz\_NTNV




n41 30kHz SISO NTN 30MHz DFT-s-OFDM PI/2 BPSK 2674.98MHz Outer Full Ant2




n41 30kHz SISO NTN 30MHz DFT-s-OFDM QPSK 2511MHz Outer Full Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_QPSK\_2674.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_16\_QAM\_2511MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_16\_QAM\_2674.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_64\_QAM\_2511MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_64\_QAM\_2674.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_256\_QAM\_2511MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41 30kHz SISO NTN 30MHz DFT-s-OFDM 256 QAM 2674.98MHz Outer Full Ant2




n41 30kHz SISO NTN 30MHz CP-OFDM QPSK 2511MHz Outer Full Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_QPSK\_2674.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_16\_QAM\_2511MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM 16 QAM 2674.98MHz Outer Full Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM 64 QAM 2511MHz Outer Full Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_64\_QAM\_2674.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_256\_QAM\_2511MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_30MHz\_CP-OFDM\_256\_QAM\_2674.98MHz\_Outer\_Full\_Ant2




3.2.6 30k\_SISO\_40MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_QPSK\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_QPSK\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_16\_QAM\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_16\_QAM\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_64\_QAM\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_64\_QAM\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_256\_QAM\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_DFT-s-OFDM\_256\_QAM\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_QPSK\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_QPSK\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_16\_QAM\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_16\_QAM\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_64\_QAM\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_64\_QAM\_2670MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_256\_QAM\_2516.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_40MHz\_CP-OFDM\_256\_QAM\_2670MHz\_Outer\_Full\_Ant2




3.2.7 30k\_SISO\_50MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_QPSK\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_QPSK\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_16\_QAM\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_16\_QAM\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_64\_QAM\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_64\_QAM\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_256\_QAM\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_DFT-s-OFDM\_256\_QAM\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_QPSK\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_QPSK\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_16\_QAM\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_16\_QAM\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_64\_QAM\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_64\_QAM\_2664.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_256\_QAM\_2521.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_50MHz\_CP-OFDM\_256\_QAM\_2664.99MHz\_Outer\_Full\_Ant2




3.2.8 30k\_SISO\_60MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_QPSK\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_QPSK\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_16\_QAM\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_16\_QAM\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_64\_QAM\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_64\_QAM\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_256\_QAM\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_DFT-s-OFDM\_256\_QAM\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_QPSK\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_QPSK\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_16\_QAM\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_16\_QAM\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_64\_QAM\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_64\_QAM\_2659.98MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_256\_QAM\_2526MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_60MHz\_CP-OFDM\_256\_QAM\_2659.98MHz\_Outer\_Full\_Ant2




3.2.9 30k\_SISO\_70MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_QPSK\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_QPSK\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_16\_QAM\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_16\_QAM\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_64\_QAM\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_64\_QAM\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_256\_QAM\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_DFT-s-OFDM\_256\_QAM\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_QPSK\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_QPSK\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_16\_QAM\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_16\_QAM\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_64\_QAM\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_64\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_64\_QAM\_2655MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_256\_QAM\_2531.01MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_256\_QAM\_2592.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_70MHz\_CP-OFDM\_256\_QAM\_2655MHz\_Outer\_Full\_Ant2




3.2.10 30k\_SISO\_80MHz\_NTNV




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_PI/2\_BPSK\_2649.99MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_QPSK\_2536.02MHz\_Outer\_Full\_Ant2




n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_QPSK\_2592.99MHz\_Outer\_Full\_Ant2



n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_QPSK\_2649.99MHz\_Outer\_Full\_Ant2



n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_16\_QAM\_2536.02MHz\_Outer\_Full\_Ant2



n41\_30kHz\_SISO\_NTNV\_80MHz\_DFT-s-OFDM\_16\_QAM\_2592.99MHz\_Outer\_Full\_Ant2

