

## Golden Unions Limited

Date: 6/7/2016

To: Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD

To Whom It May Concern:

We, **Golden Unions Limited**, state that our device, **FCC ID: 2AG78B1**, has a battery, but the battery will not be placed in the battery compartment when delivery, it is visible to the users as they purchase the products and install the battery. The back cover can be moved away, there is not enough space to print FCC ID label in surface of products, so the label has to be placed in battery compartment.

Sincerely,



---

Signature

[Pepper Zhang]

[Engineer]

[Golden Unions Limited]