



USA | AUSTRALIA | EUROPE  
rolleaseacmeda.com

ROLLEASE ACMEDA USA  
Rollease Acmeda Inc  
750 East Main Street  
Stamford CT 06902-6320 USA  
T 800 552 5100  
info@rolleaseacmeda.com

## Declaration Letter

We, Rollease Acmeda Inc, hereby declare that the product Pulse 2 Hub is not capable of operating with channel 12 and 13 in regions of US and Canada.

Versions of the product available for import and sale in the US and Canada will not operate on channels 12 and 13. It will not be possible for users and configure these channels in the US and Canada version.

By: Jonny Matuichuk  
(Signature<sup>1</sup>)

Jonny Matuichuk  
(Print name)

Title: Product Manager - Motorization

---

<sup>1</sup> -Must be signed by applicant contact given for applicant on the FCC site, or by the authorized agent if an appropriate authorized agent letter has been provided. Letters should be placed on appropriate letterhead.