

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules and Multiple Listing of Certification service per clause 11.5 of RSP-100

Reference: FCC ID: 2AGGZMTACQRF356 and IC: 21769-MTACQRF356

Statement from applicant

On the behalf of Rollease Acmeda Inc I am writing to apply for certification of the following product from our company:

Grantee name: Rollease Acmeda Inc

Model / HVIN & PMN name: MTACQRF35-6

FCC ID: 2AGGZMTACQRF356

IC: 21769-MTACQRF356

The above product, for which we are applying for certification, is identical to the following product:

Grantee name: NINGBO DOOYA MECHANIC & ELECTRONIC TECHNOLOGY CO., LTD.

Granted date of FCC and IC: 7/7/2016 and 10/6/2016

Model / HVIN & PMN name: DM35EQ/S-6/24


Original FCC ID: VYYDM350633

Original IC: 21396-DM350633

in design, circuitry and construction except for trade name, model number and logo. The documents on file with FCC/ISED from the original certification remain unchanged and continue to be valid, except for user manual and label location.

As a result, the original test results of above FCC ID and IC granted product continue to be representative of and applicable to the product from our company for certification.

Date: Jan 10, 2019

By: 
(Signature¹)

Jere Gianola
Jere Gianola

Title: Program Manager - Motorization

On behalf of: Rollease Acmeda Inc
(Company Name)

Telephone: +1 (203) 964-1573