






Out of band measurement
 Test Band = GSM850
 Test Mode = EDGE /TM2
 Test Channel = MCH




Out of band measurement
 Test Band = GSM850
 Test Mode = EDGE /TM2
 Test Channel = HCH




Out of band measurement
 Test Band = GSM1900
 Test Mode = GSM /TM1
 Test Channel = LCH




Date: 2.JUL.2019 16:44:46



Date: 2.JUL.2019 16:44:57




Date: 2.JUL.2019 16:45:07




Date: 2.JUL.2019 16:45:16


Out of band measurement
 Test Band = GSM1900
 Test Mode = GSM /TM1
 Test Channel = MCH




Date: 2.JUL.2019 16:45:52



Date: 2.JUL.2019 16:46:03




Date: 2.JUL.2019 16:46:13




Date: 2.JUL.2019 16:46:23


Out of band measurement
 Test Band = GSM1900
 Test Mode = GSM /TM1
 Test Channel = HCH




Date: 2.JUL.2019 17:05:15



Date: 2.JUL.2019 17:05:25




Date: 2.JUL.2019 17:05:34




Date: 2.JUL.2019 17:05:43


Out of band measurement
 Test Band = GSM1900
 Test Mode = EDGE /TM2
 Test Channel = LCH




Date: 2.JUL.2019 17:17:25




Date: 2.JUL.2019 17:17:35




Date: 2.JUL.2019 17:17:44



Date: 2.JUL.2019 17:17:53




Date: 2.JUL.2019 17:18:48




Date: 2.JUL.2019 17:18:57


Out of band measurement
 Test Band = GSM1900
 Test Mode = EDGE /TM2
 Test Channel = HCH




Date: 2.JUL.2019 17:19:33



Date: 2.JUL.2019 17:19:43





Date: 2.JUL.2019 17:19:52





Date: 2.JUL.2019 17:20:01



Out of band measurement
 Test Band = WCDMA850
 Test Mode = UMTS/TM3
 Test Channel = LCH




Out of band measurement
 Test Band = WCDMA850
 Test Mode = UMTS/TM3
 Test Channel = MCH




Out of band measurement
 Test Band = WCDMA850
 Test Mode = UMTS/TM3
 Test Channel = HCH




Test Band=WCDMA1900
Test Mode=UMTS/TM3
Test Channel=LCH




Date: 2.JUL.2019 15:43:50



Date: 2.JUL.2019 15:44:00




Date: 2.JUL.2019 15:44:08




Date: 2.JUL.2019 15:44:16


Test Band=WCDMA1900
 Test Mode=UMTS/TM3
 Test Channel=MCH




Date: 2.JUL.2019 15:44:57



Date: 2.JUL.2019 15:45:07




Date: 2.JUL.2019 15:45:15




Date: 2.JUL.2019 15:45:24


Test Band=WCDMA1900
 Test Mode=UMTS/TM3
 Test Channel=HCH




Date: 2.JUL.2019 15:46:05



Date: 2.JUL.2019 15:46:14






Date: 2.JUL.2019 15:46:23




Date: 2.JUL.2019 15:46:31

LTE Band 2:




Band2_1.4MHz_QPSK_18607_1RB#0




Date: 3.JUL.2019 16:07:04

Band2_1.4MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:09:28

Band2_1.4MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:09:52

Band2_1.4MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:10:15

Band2_1.4MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:10:38

Band2_1.4MHz_QPSK_19193_1RB#0




Date: 3.JUL.2019 16:13:02

Band2_1.4MHz_QPSK_19193_1RB#0




Date: 3.JUL.2019 16:13:27

Band2_1.4MHz_QPSK_19193_1RB#0




Date: 3.JUL.2019 16:13:49

Band2_1.4MHz_QPSK_19193_1RB#0




Date: 3.JUL.2019 16:14:12

Band2_1.4MHz_16QAM_18607_1RB#0




Date: 3.JUL.2019 16:07:40

Band2_1.4MHz_16QAM_18607_1RB#0




Date: 3.JUL.2019 16:08:05

Band2_1.4MHz_16QAM_18607_1RB#0




Date: 3.JUL.2019 16:08:27

Band2 1.4MHz 16QAM 18607 1RB#0




Date: 3.JUL.2019 16:08:50

Band2 1.4MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 16:11:14

Band2 1.4MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 16:11:38

Band2_1.4MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:12:01

Band2_1.4MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:12:24

Band2_1.4MHz_16QAM_19193_1RB#0




Date: 3.JUL.2019 16:14:48

Band2 1.4MHz 16QAM 19193 1RB#0




Date: 3.JUL.2019 16:15:12

Band2 1.4MHz 16QAM 19193 1RB#0




Date: 3.JUL.2019 16:15:35

Band2 1.4MHz 16QAM 19193 1RB#0




Date: 3.JUL.2019 16:15:58

Band2_3MHz_QPSK_18615_1RB#0




Date: 3.JUL.2019 16:24:14

Band2_3MHz_QPSK_18615_1RB#0




Date: 3.JUL.2019 16:24:38

Band2_3MHz_QPSK_18615_1RB#0




Date: 3.JUL.2019 16:25:01

Band2_3MHz_QPSK_18615_1RB#0




Date: 3.JUL.2019 16:25:24

Band2_3MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:27:47

Band2_3MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:28:12

Band2_3MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:28:34

Band2_3MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:28:57

Band2_3MHz_QPSK_19185_1RB#0




Date: 3.JUL.2019 16:31:21


Band2_3MHz_QPSK_19185_1RB#0




Band2_3MHz_QPSK_19185_1RB#0



Band2_3MHz_QPSK_19185_1RB#0




Band2_3MHz_16QAM_18615_1RB#0




Date: 3.JUL.2019 16:26:00

Band2_3MHz_16QAM_18615_1RB#0




Date: 3.JUL.2019 16:26:24

Band2_3MHz_16QAM_18615_1RB#0




Date: 3.JUL.2019 16:26:46

Band2_3MHz_16QAM_18615_1RB#0




Date: 3.JUL.2019 16:27:09

Band2_3MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:29:33

Band2_3MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:29:57

Band2_3MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:30:20

Band2_3MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:30:43

Band2_3MHz_16QAM_19185_1RB#0




Date: 3.JUL.2019 16:33:07

Band2_3MHz_16QAM_19185_1RB#0




Date: 3.JUL.2019 16:33:31

Band2_3MHz_16QAM_19185_1RB#0




Date: 3.JUL.2019 16:33:54

Band2_3MHz_16QAM_19185_1RB#0




Date: 3.JUL.2019 16:34:17

Band2_5MHz_QPSK_18625_1RB#0




Date: 3.JUL.2019 16:36:16

Band2_5MHz_QPSK_18625_1RB#0




Date: 3.JUL.2019 16:36:40

Band2_5MHz_QPSK_18625_1RB#0




Date: 3.JUL.2019 16:37:03

Band2_5MHz_QPSK_18625_1RB#0




Date: 3.JUL.2019 16:37:25

Band2_5MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:39:49

Band2_5MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:40:13

Band2_5MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:40:36

Band2_5MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:40:59

Band2_5MHz_QPSK_19175_1RB#0




Date: 3.JUL.2019 16:43:23

Band2_5MHz_QPSK_19175_1RB#0




Date: 3.JUL.2019 16:43:47

Band2_5MHz_QPSK_19175_1RB#0




Date: 3.JUL.2019 16:44:10

Band2_5MHz_QPSK_19175_1RB#0




Date: 3.JUL.2019 16:44:32

Band2_5MHz_16QAM_18625_1RB#0




Date: 3.JUL.2019 16:38:01

Band2_5MHz_16QAM_18625_1RB#0




Date: 3.JUL.2019 16:38:25

Band2_5MHz_16QAM_18625_1RB#0




Date: 3.JUL.2019 16:38:48

Band2_5MHz_16QAM_18625_1RB#0




Date: 3.JUL.2019 16:39:11

Band2_5MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:41:35

Band2_5MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:41:59

Band2_5MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:42:22

Band2_5MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 16:42:44

Band2_5MHz_16QAM_19175_1RB#0




Date: 3.JUL.2019 16:45:08

Band2_5MHz_16QAM_19175_1RB#0




Date: 3.JUL.2019 16:45:32

Band2_5MHz_16QAM_19175_1RB#0




Date: 3.JUL.2019 16:45:55

Band2_5MHz_16QAM_19175_1RB#0




Date: 3.JUL.2019 16:46:18

Band2_10MHz_QPSK_18650_1RB#0




Date: 3.JUL.2019 16:55:15

Band2_10MHz_QPSK_18650_1RB#0




Date: 3.JUL.2019 16:55:40

Band2_10MHz_QPSK_18650_1RB#0




Date: 3.JUL.2019 16:56:02

Band2_10MHz_QPSK_18650_1RB#0




Date: 3.JUL.2019 16:56:25

Band2_10MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:58:49

Band2_10MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:59:13

Band2_10MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:59:36

Band2_10MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 16:59:59

Band2_10MHz_QPSK_19150_1RB#0




Date: 3.JUL.2019 17:02:23

Band2_10MHz_QPSK_19150_1RB#0




Date: 3.JUL.2019 17:02:47

Band2_10MHz_QPSK_19150_1RB#0




Date: 3.JUL.2019 17:03:10

Band2_10MHz_QPSK_19150_1RB#0




Date: 3.JUL.2019 17:03:33

Band2 10MHz 16QAM 18650 1RB#0




Date: 3.JUL.2019 16:57:01

Band2 10MHz 16QAM 18650 1RB#0




Date: 3.JUL.2019 16:57:25

Band2 10MHz 16QAM 18650 1RB#0




Date: 3.JUL.2019 16:57:48

Band2 10MHz 16QAM 18650 1RB#0




Date: 3.JUL.2019 16:58:11

Band2 10MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 17:00:35

Band2 10MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 17:00:59

Band2_10MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 17:01:22

Band2_10MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 17:01:44

Band2_10MHz_16QAM_19150_1RB#0




Date: 3.JUL.2019 17:04:09

Band2 10MHz 16QAM 19150 1RB#0




Date: 3.JUL.2019 17:04:33

Band2 10MHz 16QAM 19150 1RB#0




Date: 3.JUL.2019 17:04:55

Band2 10MHz 16QAM 19150 1RB#0




Date: 3.JUL.2019 17:05:18

Band2_15MHz_QPSK_18675_1RB#0




Date: 3.JUL.2019 17:10:01

Band2_15MHz_QPSK_18675_1RB#0




Date: 3.JUL.2019 17:10:25

Band2_15MHz_QPSK_18675_1RB#0




Date: 3.JUL.2019 17:10:48

Band2_15MHz_QPSK_18675_1RB#0




Date: 3.JUL.2019 17:11:11

Band2_15MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:13:35

Band2_15MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:13:59

Band2_15MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:14:22

Band2_15MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:14:44

Band2_15MHz_QPSK_19125_1RB#0




Date: 3.JUL.2019 17:17:09

Band2_15MHz_QPSK_19125_1RB#0




Date: 3.JUL.2019 17:17:33

Band2_15MHz_QPSK_19125_1RB#0




Date: 3.JUL.2019 17:17:56

Band2_15MHz_QPSK_19125_1RB#0




Date: 3.JUL.2019 17:18:18

Band2_15MHz_16QAM_18675_1RB#0




Date: 3.JUL.2019 17:11:47

Band2_15MHz_16QAM_18675_1RB#0




Date: 3.JUL.2019 17:12:11

Band2_15MHz_16QAM_18675_1RB#0




Date: 3.JUL.2019 17:12:34

Band2_15MHz_16QAM_18675_1RB#0




Date: 3.JUL.2019 17:12:57

Band2_15MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 17:15:20

Band2_15MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 17:15:45

Band2_15MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 17:16:07

Band2_15MHz_16QAM_18900_1RB#0




Date: 3.JUL.2019 17:16:30

Band2_15MHz_16QAM_19125_1RB#0




Date: 3.JUL.2019 17:18:54

Band2_15MHz_16QAM_19125_1RB#0




Date: 3.JUL.2019 17:19:19

Band2_15MHz_16QAM_19125_1RB#0




Date: 3.JUL.2019 17:19:41

Band2_15MHz_16QAM_19125_1RB#0




Date: 3.JUL.2019 17:20:04

Band2_20MHz_QPSK_18700_1RB#0




Date: 3.JUL.2019 17:26:27

Band2_20MHz_QPSK_18700_1RB#0




Date: 3.JUL.2019 17:26:51

Band2_20MHz_QPSK_18700_1RB#0




Date: 3.JUL.2019 17:27:14

Band2_20MHz_QPSK_18700_1RB#0




Date: 3.JUL.2019 17:27:37

Band2_20MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:30:02

Band2_20MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:30:26

Band2_20MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:30:48

Band2_20MHz_QPSK_18900_1RB#0




Date: 3.JUL.2019 17:31:11

Band2_20MHz_QPSK_19100_1RB#0




Date: 3.JUL.2019 17:33:36

Band2_20MHz_QPSK_19100_1RB#0




Date: 3.JUL.2019 17:34:00

Band2_20MHz_QPSK_19100_1RB#0




Date: 3.JUL.2019 17:34:23

Band2_20MHz_QPSK_19100_1RB#0




Date: 3.JUL.2019 17:34:46

Band2 20MHz 16QAM 18700 1RB#0




Date: 3.JUL.2019 17:28:13

Band2 20MHz 16QAM 18700 1RB#0




Date: 3.JUL.2019 17:28:38

Band2 20MHz 16QAM 18700 1RB#0




Date: 3.JUL.2019 17:29:00

Band2 20MHz 16QAM 18700 1RB#0




Date: 3.JUL.2019 17:29:23

Band2 20MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 17:31:48

Band2 20MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 17:32:12

Band2 20MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 17:32:35

Band2 20MHz 16QAM 18900 1RB#0




Date: 3.JUL.2019 17:32:57

Band2 20MHz 16QAM 19100 1RB#0




Date: 3.JUL.2019 17:35:22


Band2 20MHz 16QAM 19100 1RB#0






Band2 20MHz 16QAM 19100 1RB#0




Band2 20MHz 16QAM 19100 1RB#0



LTE Band 4:




Band4 1.4MHz QPSK 19957 1RB#0




Date: 3.JUL.2019 17:48:11

Band4 1.4MHz QPSK 20175 1RB#0




Date: 3.JUL.2019 17:50:35

Band4 1.4MHz QPSK 20175 1RB#0




Date: 3.JUL.2019 17:50:59

Band4_1.4MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 17:51:22

Band4_1.4MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 17:51:44

Band4_1.4MHz_QPSK_20393_1RB#0




Date: 3.JUL.2019 17:54:08

Band4 1.4MHz QPSK 20393 1RB#0




Date: 3.JUL.2019 17:54:32

Band4 1.4MHz QPSK 20393 1RB#0




Date: 3.JUL.2019 17:54:55

Band4 1.4MHz QPSK 20393 1RB#0




Date: 3.JUL.2019 17:55:18

Band4 1.4MHz 16QAM 19957 1RB#0




Date: 3.JUL.2019 17:48:47

Band4 1.4MHz 16QAM 19957 1RB#0




Date: 3.JUL.2019 17:49:11

Band4 1.4MHz 16QAM 19957 1RB#0




Date: 3.JUL.2019 17:49:34

Band4 1.4MHz 16QAM 19957 1RB#0




Date: 3.JUL.2019 17:49:56

Band4 1.4MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 17:52:20

Band4 1.4MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 17:52:45

Band4 1.4MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 17:53:07

Band4 1.4MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 17:53:30

Band4 1.4MHz 16QAM 20393 1RB#0




Date: 3.JUL.2019 17:55:54

Band4 1.4MHz 16QAM 20393 1RB#0




Date: 3.JUL.2019 17:56:18

Band4 1.4MHz 16QAM 20393 1RB#0




Date: 3.JUL.2019 17:56:41

Band4 1.4MHz 16QAM 20393 1RB#0




Date: 3.JUL.2019 17:57:03

Band4_3MHz_QPSK_19965_1RB#0




Date: 3.JUL.2019 18:05:15

Band4_3MHz_QPSK_19965_1RB#0




Date: 3.JUL.2019 18:05:39

Band4_3MHz_QPSK_19965_1RB#0




Date: 3.JUL.2019 18:06:02

Band4_3MHz_QPSK_19965_1RB#0




Date: 3.JUL.2019 18:06:25

Band4_3MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:08:49

Band4_3MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:09:13

Band4_3MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:09:36

Band4_3MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:09:59

Band4_3MHz_QPSK_20385_1RB#0




Date: 3.JUL.2019 18:12:22

Band4_3MHz_QPSK_20385_1RB#0




Date: 3.JUL.2019 18:12:46

Band4_3MHz_QPSK_20385_1RB#0




Date: 3.JUL.2019 18:13:09

Band4_3MHz_QPSK_20385_1RB#0




Date: 3.JUL.2019 18:13:31


Band4_3MHz_16QAM_19965_1RB#0




Band4_3MHz_16QAM_19965_1RB#0



Band4_3MHz_16QAM_19965_1RB#0




Band4_3MHz_16QAM_19965_1RB#0




Date: 3.JUL.2019 18:08:10

Band4_3MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:10:35

Band4_3MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:10:59

Band4_3MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:11:22

Band4_3MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:11:44

Band4_3MHz_16QAM_20385_1RB#0




Date: 3.JUL.2019 18:14:07

Band4_3MHz_16QAM_20385_1RB#0




Date: 3.JUL.2019 18:14:31

Band4_3MHz_16QAM_20385_1RB#0




Date: 3.JUL.2019 18:14:54

Band4_3MHz_16QAM_20385_1RB#0




Date: 3.JUL.2019 18:15:17

Band4_5MHz_QPSK_19975_1RB#0




Date: 3.JUL.2019 18:22:44

Band4_5MHz_QPSK_19975_1RB#0




Date: 3.JUL.2019 18:23:08

Band4_5MHz_QPSK_19975_1RB#0




Date: 3.JUL.2019 18:23:31

Band4_5MHz_QPSK_19975_1RB#0




Date: 3.JUL.2019 18:23:53

Band4_5MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:26:17

Band4_5MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:26:41

Band4_5MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:27:03

Band4_5MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:27:26

Band4_5MHz_QPSK_20375_1RB#0




Date: 3.JUL.2019 18:29:49

Band4_5MHz_QPSK_20375_1RB#0




Date: 3.JUL.2019 18:30:13

Band4_5MHz_QPSK_20375_1RB#0




Date: 3.JUL.2019 18:30:36

Band4_5MHz_QPSK_20375_1RB#0




Date: 3.JUL.2019 18:30:59

Band4_5MHz_16QAM_19975_1RB#0




Date: 3.JUL.2019 18:24:29

Band4_5MHz_16QAM_19975_1RB#0




Date: 3.JUL.2019 18:24:53

Band4_5MHz_16QAM_19975_1RB#0




Date: 3.JUL.2019 18:25:16

Band4_5MHz_16QAM_19975_1RB#0




Date: 3.JUL.2019 18:25:39

Band4_5MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:28:02

Band4_5MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:28:26

Band4_5MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:28:49

Band4_5MHz_16QAM_20175_1RB#0




Date: 3.JUL.2019 18:29:11

Band4_5MHz_16QAM_20375_1RB#0




Date: 3.JUL.2019 18:31:34

Band4_5MHz_16QAM_20375_1RB#0




Date: 3.JUL.2019 18:31:58

Band4_5MHz_16QAM_20375_1RB#0




Date: 3.JUL.2019 18:32:21

Band4_5MHz_16QAM_20375_1RB#0




Date: 3.JUL.2019 18:32:44

Band4 10MHz QPSK 2000 1RB#0




Date: 3.JUL.2019 18:39:30

Band4 10MHz QPSK 2000 1RB#0




Date: 3.JUL.2019 18:39:54

Band4 10MHz QPSK 2000 1RB#0




Date: 3.JUL.2019 18:40:16

Band4_10MHz_QPSK_2000_1RB#0




Date: 3.JUL.2019 18:40:39

Band4_10MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:43:02

Band4_10MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:43:27

Band4_10MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:43:49

Band4_10MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:44:12

Band4_10MHz_QPSK_20350_1RB#0




Date: 3.JUL.2019 18:46:35

Band4_10MHz_QPSK_20350_1RB#0




Date: 3.JUL.2019 18:46:59

Band4_10MHz_QPSK_20350_1RB#0




Date: 3.JUL.2019 18:47:22

Band4_10MHz_QPSK_20350_1RB#0




Date: 3.JUL.2019 18:47:44

Band4 10MHz 16QAM 20000 1RB#0




Date: 3.JUL.2019 18:41:15

Band4 10MHz 16QAM 20000 1RB#0




Date: 3.JUL.2019 18:41:39

Band4 10MHz 16QAM 20000 1RB#0




Date: 3.JUL.2019 18:42:02

Band4 10MHz 16QAM 20000 1RB#0




Date: 3.JUL.2019 18:42:24

Band4 10MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:44:48

Band4 10MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:45:12

Band4 10MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:45:34

Band4 10MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:45:57

Band4 10MHz 16QAM 20350 1RB#0




Date: 3.JUL.2019 18:48:20

Band4 10MHz 16QAM 20350 1RB#0




Date: 3.JUL.2019 18:48:44

Band4 10MHz 16QAM 20350 1RB#0




Date: 3.JUL.2019 18:49:07

Band4 10MHz 16QAM 20350 1RB#0




Date: 3.JUL.2019 18:49:30

Band4_15MHz_QPSK_20025_1RB#0




Date: 3.JUL.2019 18:53:47

Band4_15MHz_QPSK_20025_1RB#0




Date: 3.JUL.2019 18:54:11

Band4_15MHz_QPSK_20025_1RB#0




Date: 3.JUL.2019 18:54:34

Band4_15MHz_QPSK_20025_1RB#0




Date: 3.JUL.2019 18:54:57

Band4_15MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:57:20

Band4_15MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:57:44

Band4_15MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:58:07

Band4_15MHz_QPSK_20175_1RB#0




Date: 3.JUL.2019 18:58:30

Band4_15MHz_QPSK_20325_1RB#0




Date: 3.JUL.2019 19:00:53

Band4_15MHz_QPSK_20325_1RB#0




Date: 3.JUL.2019 19:01:17

Band4_15MHz_QPSK_20325_1RB#0




Date: 3.JUL.2019 19:01:40

Band4_15MHz_QPSK_20325_1RB#0




Date: 3.JUL.2019 19:02:02

Band4 15MHz 16QAM 20025 1RB#0




Date: 3.JUL.2019 18:55:33

Band4 15MHz 16QAM 20025 1RB#0




Date: 3.JUL.2019 18:55:57

Band4 15MHz 16QAM 20025 1RB#0




Date: 3.JUL.2019 18:56:20

Band4 15MHz 16QAM 20025 1RB#0




Date: 3.JUL.2019 18:56:42

Band4 15MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:59:06

Band4 15MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:59:30

Band4 15MHz 16QAM 20175 1RB#0




Date: 3.JUL.2019 18:59:52

Band4 15MHz 16QAM 20175 1RB#0



Date: 3.JUL.2019 19:00:15

Band4 15MHz 16QAM 20325 1RB#0



Date: 3.JUL.2019 19:02:38