



Date: 24.APR.2024 15:48:49




Date: 24.APR.2024 15:48:58

Band2_1.4MHz_QPSK_18900_1RB#0_3000~20000_00_3000~20000

Band2_1.4MHz_16QAM_18900_1RB#0_0.009~0.15_15_0.009~0.15




Date: 24.APR.2024 15:49:06




Date: 24.APR.2024 15:49:14

Band2_1.4MHz_16QAM_18900_1RB#0_0.15~30_0.15~30


Band2_1.4MHz_16QAM_18900_1RB#0_30~1000_30~1000




Date: 24.APR.2024 15:49:23




Date: 24.APR.2024 15:49:31







Band2_1.4MHz_QPSK_19193_1RB#0_3000~20000_00_3000~20000



Band2_1.4MHz_16QAM_19193_1RB#0_0.009~0.15_15_0.009~0.15



Band2_1.4MHz_16QAM_19193_1RB#0_0.15~30_0.15~30



Band2_1.4MHz_16QAM_19193_1RB#0_30~1000_30~1000

