


Date: 25.APR.2024 15:05:52


Date: 25.APR.2024 15:06:28

Band38_5MHz_QPSK_38225_1RB#0_20000~27000
000_20000~27000

Band38_5MHz_16QAM_38225_1RB#0_0.009~0.1
5_0.009~0.15




Date: 25.APR.2024 15:06:47




Date: 25.APR.2024 15:07:08

Band38_5MHz_16QAM_38225_1RB#0_0.15~30
_0.15~30


Band38_5MHz_16QAM_38225_1RB#0_30~1000_
30~1000





Date: 25.APR.2024 15:07:29





Date: 25.APR.2024 15:07:52







Band38_10MHz_QPSK_37800_1RB#0_20000~27000


Band38_10MHz_16QAM_37800_1RB#0_0.009~0.15





Band38_10MHz_QPSK_37800_1RB#0_0.15~30

Band38_10MHz_16QAM_37800_1RB#0_30~1000









Band38_10MHz_QPSK_38000_1RB#0_20000~27000

Band38_10MHz_16QAM_38000_1RB#0_0.009~0.15



Band38_10MHz_16QAM_38000_1RB#0_0.15~30

Band38_10MHz_16QAM_38000_1RB#0_30~1000

