

Label Sample and Location

FCC ID: 2AHVPSB7800M5BANA



UHF Class B Signal Booster / BDA

Model: SB7800M5B-ANA SN: TESTSMP

FCC ID: 2AHVPSB7800M5BANA

Radio Solutions, Inc
www.radiosolutionsinc.com

RSI
Designed and Built In USA

This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference, and
- (2) This device must accept any interference received,
that may cause undesired operation.

Part 90 Signal Boosters

THIS IS A 90.219 CLASS B DEVICE

WARNING This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.