



Please refer to following plots:




Date: 12.AUG.2022 15:34:43




Date: 12.AUG.2022 15:34:49

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 12.AUG.2022 15:34:56

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 12.AUG.2022 15:35:03

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 12.AUG.2022 15:36:07

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 12.AUG.2022 15:36:13

Band 2_3 MHz_High_QPSK_RB15#0




Date: 12.AUG.2022 15:36:20

Band 2_3 MHz_High_16QAM_RB15#0




Date: 12.AUG.2022 15:36:27

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 12.AUG.2022 15:39:00

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 12.AUG.2022 15:39:06

Band 2_5 MHz_High_QPSK_RB25#0




Date: 12.AUG.2022 15:39:14

Band 2_5 MHz_High_16QAM_RB25#0




Date: 12.AUG.2022 15:39:21

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 12.AUG.2022 15:42:15

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 12.AUG.2022 15:53:27

Band 2_10 MHz_High_QPSK_RB50#0




Date: 12.AUG.2022 15:53:36

Band 2_10 MHz_High_16QAM_RB50#0




Date: 12.AUG.2022 15:55:15

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 12.AUG.2022 16:01:08

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 12.AUG.2022 16:05:13

Band 2_15 MHz_High_QPSK_RB75#0




Date: 12.AUG.2022 16:05:23

Band 2_15 MHz_High_16QAM_RB75#0




Date: 12.AUG.2022 16:07:09

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 12.AUG.2022 16:08:21

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 12.AUG.2022 16:08:59

Band 2_20 MHz_High_QPSK_RB100#0




Date: 12.AUG.2022 16:09:09

Band 2_20 MHz_High_16QAM_RB100#0




Date: 12.AUG.2022 16:09:53

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 12.AUG.2022 16:10:04

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 12.AUG.2022 16:10:10

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 12.AUG.2022 16:10:17

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 12.AUG.2022 16:10:23

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 12.AUG.2022 16:11:35

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 12.AUG.2022 16:11:42

Band 4_3 MHz_High_QPSK_RB15#0




Date: 12.AUG.2022 16:11:49

Band 4_3 MHz_High_16QAM_RB15#0




Date: 12.AUG.2022 16:11:55

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 12.AUG.2022 16:13:00

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 12.AUG.2022 16:13:08

Band 4_5 MHz_High_QPSK_RB25#0




Date: 12.AUG.2022 16:13:16

Band 4_5 MHz_High_16QAM_RB25#0




Date: 12.AUG.2022 16:13:23

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 12.AUG.2022 16:14:37

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 12.AUG.2022 16:17:51

Band 4_10 MHz_High_QPSK_RB50#0




Date: 12.AUG.2022 16:17:59

Band 4_10 MHz_High_16QAM_RB50#0




Date: 12.AUG.2022 16:19:17

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 12.AUG.2022 16:20:33

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 12.AUG.2022 16:21:16

Band 4_15 MHz_High_QPSK_RB75#0




Date: 12.AUG.2022 16:21:26

Band 4_15 MHz_High_16QAM_RB75#0




Date: 12.AUG.2022 16:22:08

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 12.AUG.2022 16:23:23

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 12.AUG.2022 16:29:44

Band 4_20 MHz_High_QPSK_RB100#0




Date: 12.AUG.2022 16:29:54

Band 4_20 MHz_High_16QAM_RB100#0




Date: 12.AUG.2022 16:30:53

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 12.AUG.2022 16:32:12

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 12.AUG.2022 16:32:19

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 12.AUG.2022 16:32:26

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 12.AUG.2022 16:32:32

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 12.AUG.2022 16:33:35

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 12.AUG.2022 16:33:43

Band 12_3 MHz_High_QPSK_RB15#0




Date: 12.AUG.2022 16:33:50

Band 12_3 MHz_High_16QAM_RB15#0




Date: 12.AUG.2022 16:33:56

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 12.AUG.2022 16:35:08

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 12.AUG.2022 16:35:16

Band 12_5 MHz_High_QPSK_RB25#0




Date: 12.AUG.2022 16:35:23

Band 12_5 MHz_High_16QAM_RB25#0




Date: 12.AUG.2022 16:35:30

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 12.AUG.2022 16:36:44

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 12.AUG.2022 16:40:42

Band 12_10 MHz_High_QPSK_RB50#0



Date: 12.AUG.2022 16:40:50

Band 12_10 MHz_High_16QAM_RB50#0



Date: 12.AUG.2022 16:42:02