



**Appendix C: Band Edge**

1 Band 2\_1.4 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 11:27:21

2 Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 11.JUN.2024 11:30:37

3 Band 2\_1.4 MHz\_Low\_16QAM\_RB1#0




Date: 11.JUN.2024 11:28:07

4 Band 2\_1.4 MHz\_Low\_16QAM\_RB5#0




Date: 11.JUN.2024 11:29:04

5 Band 2\_1.4 MHz\_High\_QPSK\_RB1#5




Date: 13.JUN.2024 13:41:09

6 Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 11.JUN.2024 11:34:37

7 Band 2\_1.4 MHz\_High\_16QAM\_RB1#5




Date: 13.JUN.2024 13:38:50

8 Band 2\_1.4 MHz\_High\_16QAM\_RB5#1




Date: 11.JUN.2024 12:06:43

9 Band 2\_3 MHz\_Low\_QPSK\_RB1#1




Date: 11.JUN.2024 13:07:08

10 Band 2\_3 MHz\_Low\_QPSK\_RB6#0




Date: 11.JUN.2024 13:09:17

11 Band 2\_3 MHz\_Low\_16QAM\_RB1#1




Date: 11.JUN.2024 13:12:16

12 Band 2\_3 MHz\_Low\_16QAM\_RB5#0




Date: 11.JUN.2024 13:11:09

13 Band 2\_3 MHz\_High\_QPSK\_RB1#13




Date: 13.JUN.2024 13:43:10

14 Band 2\_3 MHz\_High\_QPSK\_RB6#8




Date: 11.JUN.2024 13:16:54

15 Band 2\_3 MHz\_High\_16QAM\_RB1#13



Date: 13.JUN.2024 13:44:48


16 Band 2\_3 MHz\_High\_16QAM\_RB5#0



Date: 25.JUN.2024 14:04:04




17 Band 2\_5 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 13:21:22

18 Band 2\_5 MHz\_Low\_QPSK\_RB6#0




Date: 11.JUN.2024 13:23:08

19 Band 2\_5 MHz\_Low\_16QAM\_RB1#0




Date: 11.JUN.2024 13:26:18

20 Band 2\_5 MHz\_Low\_16QAM\_RB5#0




Date: 11.JUN.2024 13:24:12

21 Band 2\_5 MHz\_High\_QPSK\_RB1#24




Date: 13.JUN.2024 13:48:51

22 Band 2\_5 MHz\_High\_QPSK\_RB6#19




Date: 11.JUN.2024 13:29:41

### 23 Band 2\_5 MHz\_High\_16QAM\_RB1#24




Date: 13.JUN.2024 13:47:45

### 24 Band 2\_5 MHz\_High\_16QAM\_RB5#20




Date: 25.JUN.2024 14:17:02

### 25 Band 2\_10 MHz\_Low\_QPSK\_RB1#1




Date: 11.JUN.2024 13:33:39

### 26 Band 2\_10 MHz\_Low\_QPSK\_RB6#1




Date: 11.JUN.2024 13:35:09

27 Band 2\_10 MHz\_Low\_16QAM\_RB1#1




Date: 11.JUN.2024 13:36:28

28 Band 2\_10 MHz\_Low\_16QAM\_RB5#1




Date: 11.JUN.2024 13:38:06

29 Band 2\_10 MHz\_High\_QPSK\_RB1#48




Date: 13.JUN.2024 14:07:33

30 Band 2\_10 MHz\_High\_QPSK\_RB6#43




Date: 11.JUN.2024 13:42:05

### 31 Band 2\_10 MHz\_High\_16QAM\_RB1#48



Date: 13.JUN.2024 14:03:45


### 32 Band 2\_10 MHz\_High\_16QAM\_RB5#0



Date: 25.JUN.2024 14:19:59




33 Band 2\_15 MHz\_Low\_QPSK\_RB1#1




Date: 11.JUN.2024 13:48:17

34 Band 2\_15 MHz\_Low\_QPSK\_RB6#1




Date: 11.JUN.2024 13:49:16

### 35 Band 2\_15 MHz\_Low\_16QAM\_RB1#1




Date: 11.JUN.2024 13:50:13

### 36 Band 2\_15 MHz\_Low\_16QAM\_RB5#1




Date: 11.JUN.2024 13:54:34

### 37 Band 2\_15 MHz\_High\_QPSK\_RB1#73




Date: 13.JUN.2024 13:55:22

### 38 Band 2\_15 MHz\_High\_QPSK\_RB6#68




Date: 11.JUN.2024 13:59:09

### 39 Band 2\_15 MHz\_High\_16QAM\_RB1#73




Date: 13.JUN.2024 13:56:16

### 40 Band 2\_15 MHz\_High\_16QAM\_RB5#0




Date: 25.JUN.2024 14:22:52

41 Band 2\_20 MHz\_Low\_QPSK\_RB1#1




Date: 11.JUN.2024 14:11:23

42 Band 2\_20 MHz\_Low\_QPSK\_RB6#0




Date: 11.JUN.2024 14:13:44

### 43 Band 2\_20 MHz\_Low\_16QAM\_RB1#1




Date: 11.JUN.2024 14:16:06

### 44 Band 2\_20 MHz\_Low\_16QAM\_RB5#0




Date: 11.JUN.2024 14:17:30

### 45 Band 2\_20 MHz\_High\_QPSK\_RB1#97




Date: 13.JUN.2024 13:58:37

### 46 Band 2\_20 MHz\_High\_QPSK\_RB6#0




Date: 11.JUN.2024 14:20:15

### 47 Band 2\_20 MHz\_High\_16QAM\_RB1#97



Date: 13.JUN.2024 14:00:44


### 48 Band 2\_20 MHz\_High\_16QAM\_RB5#0



Date: 11.JUN.2024 14:24:34




49 Band 5\_1.4 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 14:27:44

50 Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 11.JUN.2024 14:28:43

51 Band 5\_1.4 MHz\_Low\_16QAM\_RB1#5




Date: 11.JUN.2024 14:30:18

52 Band 5\_1.4 MHz\_Low\_16QAM\_RB5#0




Date: 11.JUN.2024 14:32:30

53 Band 5\_1.4 MHz\_High\_QPSK\_RB1#5



Date: 11.JUN.2024 14:34:27


54 Band 5\_1.4 MHz\_High\_QPSK\_RB6#0



Date: 11.JUN.2024 14:36:23




57 Band 5\_3 MHz\_Low\_QPSK\_RB1#1



Date: 11.JUN.2024 14:42:21


58 Band 5\_3 MHz\_Low\_QPSK\_RB6#1



Date: 11.JUN.2024 14:45:15




61 Band 5\_3 MHz\_High\_QPSK\_RB1#13




Date: 13.JUN.2024 14:11:09

62 Band 5\_3 MHz\_High\_QPSK\_RB6#8




Date: 11.JUN.2024 14:52:54

63 Band 5\_3 MHz\_High\_16QAM\_RB1#13



Date: 13.JUN.2024 14:12:26


64 Band 5\_3 MHz\_High\_16QAM\_RB5#0



Date: 25.JUN.2024 14:29:14




65 Band 5\_5 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 15:01:00

66 Band 5\_5 MHz\_Low\_QPSK\_RB6#0




Date: 11.JUN.2024 15:02:15

67 Band 5\_5 MHz\_Low\_16QAM\_RB1#0




Date: 11.JUN.2024 15:03:32

68 Band 5\_5 MHz\_Low\_16QAM\_RB5#0




Date: 11.JUN.2024 15:06:08

69 Band 5\_5 MHz\_High\_QPSK\_RB1#24




Date: 13.JUN.2024 14:23:12

70 Band 5\_5 MHz\_High\_QPSK\_RB6#18




Date: 11.JUN.2024 15:09:40

### 71 Band 5\_5 MHz\_High\_16QAM\_RB1#24




Date: 13.JUN.2024 14:24:28

### 72 Band 5\_5 MHz\_High\_16QAM\_RB5#20




Date: 25.JUN.2024 14:32:22

73 Band 5\_10 MHz\_Low\_QPSK\_RB1#1



Date: 11.JUN.2024 15:16:28


74 Band 5\_10 MHz\_Low\_QPSK\_RB6#1



Date: 11.JUN.2024 15:19:34




77 Band 5\_10 MHz\_High\_QPSK\_RB1#48




Date: 13.JUN.2024 14:26:49

78 Band 5\_10 MHz\_High\_QPSK\_RB6#43




Date: 11.JUN.2024 15:26:03

79 Band 5\_10 MHz\_High\_16QAM\_RB1#48



Date: 13.JUN.2024 14:28:11


80 Band 5\_10 MHz\_High\_16QAM\_RB5#44



Date: 25.JUN.2024 14:35:12




1 Band 4\_1.4 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:16:37

2 Band 4\_1.4 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:17:01

3 Band 4\_1.4 MHz\_High\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:17:28

4 Band 4\_1.4 MHz\_High\_16QAM\_NB0\_RB5#1




Date: 10.JUN.2024 14:17:52

### 5 Band 4\_3 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:18:56

### 6 Band 4\_3 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:19:20

7 Band 4\_3 MHz\_High\_QPSK\_NB1\_RB6#0




Date: 10.JUN.2024 14:19:46

8 Band 4\_3 MHz\_High\_16QAM\_NB1\_RB5#1




Date: 10.JUN.2024 14:20:09

### 9 Band 4\_5 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:21:13

### 10 Band 4\_5 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:21:37

11 Band 4\_5 MHz\_High\_QPSK\_NB3\_RB6#0




Date: 10.JUN.2024 14:22:03

12 Band 4\_5 MHz\_High\_16QAM\_NB3\_RB5#1




Date: 10.JUN.2024 14:22:27

13 Band 4\_10 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:23:30

14 Band 4\_10 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:23:54

### 15 Band 4\_10 MHz\_High\_QPSK\_NB7\_RB6#0



Date: 10.JUN.2024 14:24:20

### 16 Band 4\_10 MHz\_High\_16QAM\_NB7\_RB5#1




Date: 10.JUN.2024 14:24:45






19 Band 4\_15 MHz\_High\_QPSK\_NB3\_NB11\_RB6#0




Date: 10.JUN.2024 14:26:39

20 Band 4\_15 MHz\_High\_16QAM\_NB11\_RB5#1




Date: 10.JUN.2024 14:27:03

21 Band 4\_20 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:28:07

22 Band 4\_20 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:28:31

23 Band 4\_20 MHz\_High\_QPSK\_NB15\_RB6#0




Date: 10.JUN.2024 14:28:58

24 Band 4\_20 MHz\_High\_16QAM\_NB15\_RB5#1




Date: 10.JUN.2024 14:29:22

25 Band 12\_1.4 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:37:45

26 Band 12\_1.4 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:38:09

27 Band 12\_1.4 MHz\_High\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:38:38

28 Band 12\_1.4 MHz\_High\_16QAM\_NB0\_RB5#1




Date: 10.JUN.2024 14:39:02

29 Band 12\_3 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:41:11

30 Band 12\_3 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:41:35

31 Band 12\_3 MHz\_High\_QPSK\_NB1\_RB6#0



Date: 10.JUN.2024 14:42:01


32 Band 12\_3 MHz\_High\_16QAM\_NB1\_RB5#1



Date: 10.JUN.2024 14:42:25




33 Band 12\_5 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:43:29

34 Band 12\_5 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:43:53

35 Band 12\_5 MHz\_High\_QPSK\_NB3\_RB6#0




Date: 10.JUN.2024 14:44:19

36 Band 12\_5 MHz\_High\_16QAM\_NB3\_RB5#1




Date: 10.JUN.2024 14:44:43

37 Band 12\_10 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:47:01

38 Band 12\_10 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:47:25

39 Band 12\_10 MHz\_High\_QPSK\_NB7\_RB6#0




Date: 10.JUN.2024 14:47:51

40 Band 12\_10 MHz\_High\_16QAM\_NB7\_RB5#1




Date: 10.JUN.2024 14:48:15

41 Band 13\_5 MHz\_Low\_QPSK\_NB0\_RB6#0




Date: 10.JUN.2024 14:48:45

42 Band 13\_5 MHz\_Low\_16QAM\_NB0\_RB5#0




Date: 10.JUN.2024 14:49:09

43 Band 13\_5 MHz\_High\_QPSK\_NB3\_RB6#0



Date: 10.JUN.2024 14:49:35


44 Band 13\_5 MHz\_High\_16QAM\_NB3\_RB5#1



Date: 10.JUN.2024 14:49:59




47 Band 13\_10 MHz\_Middle\_QPSK\_NB7\_RB6#0



Date: 14.JUN.2024 15:30:20


48 Band 13\_10 MHz\_Middle\_16QAM\_NB7\_RB5#1



Date: 14.JUN.2024 15:31:16




1 Band 4\_1.4 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 09:47:00

2 Band 4\_1.4 MHz\_Low\_16QAM\_RB1#0




Date: 11.JUN.2024 09:46:03

3 Band 4\_1.4 MHz\_High\_QPSK\_RB1#5



Date: 11.JUN.2024 09:43:36


4 Band 4\_1.4 MHz\_High\_16QAM\_RB1#5



Date: 11.JUN.2024 09:42:23




7 Band 4\_3 MHz\_High\_QPSK\_RB1#13



Date: 11.JUN.2024 09:52:47

8 Band 4\_3 MHz\_High\_16QAM\_RB1#13




Date: 11.JUN.2024 09:51:21








15 Band 4\_10 MHz\_High\_QPSK\_RB1#48



Date: 11.JUN.2024 10:09:17


16 Band 4\_10 MHz\_High\_16QAM\_RB1#48



Date: 11.JUN.2024 10:08:24




17 Band 4\_15 MHz\_Low\_QPSK\_RB1#1



Date: 11.JUN.2024 10:10:51


18 Band 4\_15 MHz\_Low\_16QAM\_RB1#1



Date: 11.JUN.2024 10:11:56




21 Band 4\_20 MHz\_Low\_QPSK\_RB1#2



Date: 11.JUN.2024 10:23:06

22 Band 4\_20 MHz\_Low\_16QAM\_RB1#2




Date: 11.JUN.2024 10:24:04






27 Band 12\_1.4 MHz\_High\_QPSK\_RB1#5



Date: 11.JUN.2024 10:37:29


28 Band 12\_1.4 MHz\_High\_16QAM\_RB1#5



Date: 11.JUN.2024 10:35:53




31 Band 12\_3 MHz\_High\_QPSK\_RB1#13



Date: 11.JUN.2024 10:50:20


32 Band 12\_3 MHz\_High\_16QAM\_RB1#13



Date: 11.JUN.2024 10:48:44




33 Band 12\_5 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 10:53:07

34 Band 12\_5 MHz\_Low\_16QAM\_RB1#0




Date: 11.JUN.2024 10:55:00

35 Band 12\_5 MHz\_High\_QPSK\_RB1#24




Date: 11.JUN.2024 11:00:08

36 Band 12\_5 MHz\_High\_16QAM\_RB1#24




Date: 11.JUN.2024 10:58:15

37 Band 12\_10 MHz\_Low\_QPSK\_RB1#1




Date: 11.JUN.2024 11:02:59

38 Band 12\_10 MHz\_Low\_16QAM\_RB1#1




Date: 11.JUN.2024 11:05:06

39 Band 12\_10 MHz\_High\_QPSK\_RB1#48




Date: 11.JUN.2024 11:08:42

40 Band 12\_10 MHz\_High\_16QAM\_RB1#48




Date: 11.JUN.2024 11:07:39

41 Band 13\_5 MHz\_Low\_QPSK\_RB1#0




Date: 11.JUN.2024 09:30:01

42 Band 13\_5 MHz\_Low\_16QAM\_RB1#0




Date: 11.JUN.2024 09:31:35

43 Band 13\_5 MHz\_High\_QPSK\_RB1#24




Date: 11.JUN.2024 09:37:17

44 Band 13\_5 MHz\_High\_16QAM\_RB1#24




Date: 11.JUN.2024 09:35:48

### 45 Band 13\_10 MHz\_Middle\_QPSK\_RB1#1




Date: 11.JUN.2024 09:28:34

### 46 Band 13\_10 MHz\_Middle\_16QAM\_RB1#1




Date: 11.JUN.2024 09:27:24

47 Band 13\_10 MHz\_Middle\_QPSK\_RB1#48



Date: 14.JUN.2024 15:29:28

48 Band 13\_10 MHz\_Middle\_16QAM\_RB1#48



Date: 14.JUN.2024 15:28:41