

C2PC Request Letter

12/1/2023

Nemko North American, Inc
 303 River Road
 Ottawa
 K1V 1H2
 Canada

ATTN.: Reviewing Engineer


FCC ID: 2AI7A22210

We hereby request C2PC Certification for the above mentioned FCC ID.


The reason for this request is:

The PCB layout has been changed, and the circuit is almost identical, with only minor adjustments made to some resistance and capacitance values. The main RF functions and frequencies have not changed significantly, and the specific differences are as follows:

1. Schematics



2. PCB Layout



Change List

	ITEM	Before	After
1	Electronic component	SPKER	MIC: CD1007 / R6: 5K6 / R15: 22K / C17: 472

Change Note

Item	Main Pcb
Description	<p>WT-416V1.0</p> <p>91002V1.0</p> <p>WT-416V1.0 and 91002V1.0 PCBs are shown with red dashed boxes indicating the area of change. The WT-416V1.0 PCB is green, and the 91002V1.0 PCB is green with a black component.</p>

Kidz Toyz USA LLC

The differential samples have been arranged for testing and verification, and the results meet the standard limit requirements.

Kind regards

Signed: 

Printed name: Danny Siu
Title: Product Manager
Date: 12/1/2023