


## 1. Computer configuration

Specificaiton	
Language	Chinese, English... multi languages
Processor	Intel CherryTrail T3, 1.84GHz
Graphics processor	Intel Gen 8 LP, 8EU(600MHz)
System memory	1x64 DDR3L/RS-1600; 2G ;
Storage capacity	32GB (16G, 64G, 128G Optional);
Storage extention	Support Micro SD card, maximum support 128GB
Network	1*Micro SD card slot
Power supply	wired 10M/100M BaseT
HDMI output	DC 5V/3A 1*DC outlet (diameter 1.65mm)
USB port	1xHDMI A type port, HDMI1.4
R/L output port	USB 3.0*1 host
MIC	USB2.0*2 host
input port	1*3.5mm Headset seat
Network port	1*RJ45
IR	1* IR infrared receiver module
Key	Power keyswitch*1, touch switch
Product dimension	106*106*23mm



## 2. Port appearance introduction

- 1>. Power supply : Power switch: Startup&Shutdown, Standby key
- 2>. Remote control receiving (IR)window: Use for Remote control operation, Key remote control machine operates command
- 3>. Heat dissipation window: Good for product heat dissipation, machine internal temperature dispersed in time
- 4>. Micro SD slot: support Micro SD card, maximum support 128GB
- 5>. USB3.0 port : faster transfer, data copy and file
- 6>. 3.5mm audio output: use for external headset audio output port 3
- 7>. USB2.0 port: USB port enable multiple devices operation on the same computer, supporting hot plug and unplug, external devices can be connected or removed without restart the computer.
- 8>. HDMI port: HDMI A type port, HDMI1.4 compatibility
- 9>. RJ45 internet access: Connection with Ethernet, a good swim on internet pages
- 10>. DC power supply port: used for connection of electrical device

## 3. Computer application method

- 1>. AC Adapter is connected to power supply, default computer is auto power-on
- 2>. Computer Standby: (1) short press power button 1S, computer goes to system standby, mouse click desktop will recover interface. (2) Mouse move to screen bottom left corner click it, then click Power again, choose Standby option, computer goes to Standby mode.
- 3>. Computer Shutdown: (1) long press computer power button 10S, forced shutdown; (2) Mouse move to screen bottom left click, then click Power again, choose Shutdown item to shutdown the computer.