



Please refer to following plots:

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 15:23:00

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 15:23:24

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.OCT.2022 15:23:45

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.OCT.2022 15:24:02

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 15:24:20

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 15:24:34

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 15:25:25

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 15:25:39

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 19.OCT.2022 15:25:57

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 19.OCT.2022 15:26:17

Band 5_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 15:26:32

Band 5_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 15:26:46

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 15:27:57

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 15:28:15

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 15:28:40

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 15:29:01

Band 5_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 15:29:23

Band 5_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 15:29:44

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 15:30:35

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 15:30:53

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 15:31:12

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 15:31:31

Band 5_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 15:31:50

Band 5_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 15:32:09

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 15:32:29

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 15:32:43

Band 12_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.OCT.2022 15:32:57

Band 12_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.OCT.2022 15:33:15

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 15:33:36

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 15:33:53

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 15:34:54

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 15:35:14

Band 12_3 MHz_Middle_QPSK_RB15#0




Date: 19.OCT.2022 15:35:29

Band 12_3 MHz_Middle_16QAM_RB15#0




Date: 19.OCT.2022 15:35:47

Band 12_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 15:36:05

Band 12_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 15:36:19

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 15:38:36

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 15:38:57

Band 12_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 15:39:25

Band 12_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 15:39:46

Band 12_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 15:40:05

Band 12_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 15:40:29

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 15:41:12

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 15:41:31

Band 12_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 15:41:50

Band 12_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 15:42:09

Band 12_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 15:42:28

Band 12_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 15:42:47

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 15:43:13

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 15:43:31

Band 13_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 15:43:53

Band 13_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 15:44:17

Band 13_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 15:44:39

Band 13_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 15:45:00

Band 13_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 15:45:40

Band 13_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 15:45:59

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 11:34:47

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 11:35:06

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.OCT.2022 11:35:24

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.OCT.2022 11:35:42

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 11:36:03

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 11:36:17

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 11:36:50

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 11:37:04

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 19.OCT.2022 11:37:19

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 19.OCT.2022 11:37:37

Band 2_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 11:37:55

Band 2_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 11:38:12

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 11:38:58

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 11:39:13

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 11:39:38

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 11:39:59

Band 2_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 11:40:27

Band 2_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 11:40:51

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 11:44:14

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 11:48:18

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 11:48:37

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 11:50:19

Band 2_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 11:50:38

Band 2_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 11:52:34

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 11:53:40

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 11:54:07

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 19.OCT.2022 11:54:35

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 19.OCT.2022 11:55:03

Band 2_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 11:55:28

Band 2_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 11:55:55

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 11:57:39

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 11:58:00

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 19.OCT.2022 11:58:29

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 19.OCT.2022 11:58:54

Band 2_20 MHz_High_QPSK_RB100#0




Date: 19.OCT.2022 11:59:23

Band 2_20 MHz_High_16QAM_RB100#0




Date: 19.OCT.2022 11:59:47

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 12:00:14

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 12:00:31

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.OCT.2022 12:00:49

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.OCT.2022 12:01:06

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 12:01:27

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 12:01:44

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 12:02:26

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 12:02:44

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 19.OCT.2022 12:02:59

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 19.OCT.2022 12:03:13

Band 4_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 12:03:28

Band 4_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 12:03:45

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 12:04:31

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 12:04:49

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 12:05:11

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 12:05:32

Band 4_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 12:05:57

Band 4_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 12:06:15

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 13:04:07

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 13:04:25

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 13:04:45

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 13:05:00

Band 4_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 13:05:19

Band 4_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 13:05:38

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 13:06:11

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 13:06:32

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 19.OCT.2022 13:06:57

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 19.OCT.2022 13:07:22

Band 4_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 13:07:47

Band 4_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 13:08:08

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 13:09:00

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 13:09:22

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 19.OCT.2022 13:09:44

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 19.OCT.2022 13:10:06

Band 4_20 MHz_High_QPSK_RB100#0




Date: 19.OCT.2022 13:10:35

Band 4_20 MHz_High_16QAM_RB100#0




Date: 19.OCT.2022 13:11:00

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 13:11:23

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 13:11:44

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 13:12:03

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 13:12:21

Band 7_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 13:12:46

Band 7_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 13:13:01

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 13:13:31

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 13:13:50

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 13:14:09

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 13:17:11

Band 7_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 13:17:30

Band 7_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 13:19:25

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 13:21:02

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 13:21:23

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 19.OCT.2022 13:21:45

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 19.OCT.2022 13:22:03

Band 7_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 13:22:28

Band 7_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 13:22:49

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 13:23:34

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 13:23:55

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 19.OCT.2022 13:24:16

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 19.OCT.2022 13:24:34

Band 7_20 MHz_High_QPSK_RB100#0




Date: 19.OCT.2022 13:24:54

Band 7_20 MHz_High_16QAM_RB100#0




Date: 19.OCT.2022 13:25:15

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 13:25:38

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 13:25:52

Band 66_1.4 MHz_Middle_QPSK_RB6#0




Date: 19.OCT.2022 13:26:13

Band 66_1.4 MHz_Middle_16QAM_RB6#0




Date: 19.OCT.2022 13:26:27

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 13:26:45

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 13:27:03

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 13:27:26

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 13:27:40

Band 66_3 MHz_Middle_QPSK_RB15#0




Date: 19.OCT.2022 13:27:55

Band 66_3 MHz_Middle_16QAM_RB15#0




Date: 19.OCT.2022 13:28:12

Band 66_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 13:28:33

Band 66_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 13:28:48

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 13:29:49

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 13:30:13

Band 66_5 MHz_Middle_QPSK_RB25#0




Date: 19.OCT.2022 13:30:38

Band 66_5 MHz_Middle_16QAM_RB25#0




Date: 19.OCT.2022 13:31:02

Band 66_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 13:31:24

Band 66_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 13:31:45

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 13:32:36

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 13:32:54

Band 66_10 MHz_Middle_QPSK_RB50#0




Date: 19.OCT.2022 13:33:17

Band 66_10 MHz_Middle_16QAM_RB50#0




Date: 19.OCT.2022 13:33:35

Band 66_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 13:33:54

Band 66_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 13:35:47

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 13:36:15

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 13:36:42

Band 66_15 MHz_Middle_QPSK_RB75#0




Date: 19.OCT.2022 13:37:04

Band 66_15 MHz_Middle_16QAM_RB75#0




Date: 19.OCT.2022 13:37:32

Band 66_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 13:37:57

Band 66_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 13:38:21

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 13:39:11

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 13:39:45

Band 66_20 MHz_Middle_QPSK_RB100#0




Date: 19.OCT.2022 13:40:10

Band 66_20 MHz_Middle_16QAM_RB100#0




Date: 19.OCT.2022 13:40:38

Band 66_20 MHz_High_QPSK_RB100#0



Date: 19.OCT.2022 13:41:04

Band 66_20 MHz_High_16QAM_RB100#0



Date: 19.OCT.2022 13:41:28