



Please refer to following plots:




Date: 19.OCT.2022 13:43:08




Date: 19.OCT.2022 13:43:15

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 13:43:22

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 13:43:29

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 13:43:45

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 13:43:51

Band 2_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 13:43:59

Band 2_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 13:44:06

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 13:46:12

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 13:46:18

Band 2_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 13:46:27

Band 2_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 13:46:34

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 13:47:14

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 13:47:21

Band 2_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 13:47:38

Band 2_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 13:47:46

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 13:48:03

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 13:50:47

Band 2_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 13:50:54

Band 2_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 13:52:23

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 13:54:34

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 13:54:41

Band 2_20 MHz_High_QPSK_RB100#0




Date: 19.OCT.2022 13:54:49

Band 2_20 MHz_High_16QAM_RB100#0




Date: 19.OCT.2022 13:54:56

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 13:55:09

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 13:55:15

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 13:55:22

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 13:55:28

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 13:56:00

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 13:56:07

Band 4_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 13:56:14

Band 4_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 13:56:20

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 13:59:39

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 13:59:46

Band 4_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 13:59:54

Band 4_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 14:00:01

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 14:01:08

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 14:01:16

Band 4_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 14:01:25

Band 4_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 14:01:32

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 14:02:26

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 14:02:33

Band 4_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 14:02:40

Band 4_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 14:02:47

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 14:03:34

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 14:03:41

Band 4_20 MHz_High_QPSK_RB100#0




Date: 19.OCT.2022 14:03:49

Band 4_20 MHz_High_16QAM_RB100#0




Date: 19.OCT.2022 14:03:56

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 20.OCT.2022 13:17:49

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 20.OCT.2022 13:18:33

Band 7_5 MHz_High_QPSK_RB25#0




Date: 20.OCT.2022 13:19:23

Band 7_5 MHz_High_16QAM_RB25#0




Date: 20.OCT.2022 13:21:01

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 20.OCT.2022 13:21:50

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 20.OCT.2022 13:22:21

Band 7_10 MHz_High_QPSK_RB50#0




Date: 20.OCT.2022 13:23:05

Band 7_10 MHz_High_16QAM_RB50#0




Date: 20.OCT.2022 13:23:37

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 9.JAN.2023 13:32:43

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 9.JAN.2023 13:33:03

Band 7_15 MHz_High_QPSK_RB75#0




Date: 9.JAN.2023 13:33:46

Band 7_15 MHz_High_16QAM_RB75#0




Date: 9.JAN.2023 13:34:05

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 20.OCT.2022 13:30:04

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 20.OCT.2022 13:29:37

Band 7_20 MHz_High_QPSK_RB100#0




Date: 20.OCT.2022 13:29:02

Band 7_20 MHz_High_16QAM_RB100#0




Date: 20.OCT.2022 13:28:34

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 14:12:47

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 14:12:54

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 14:13:01

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 14:13:07

Band 66_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 14:14:00

Band 66_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 14:14:07

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 14:14:46

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 14:14:53

Band 66_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 14:15:02

Band 66_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 14:15:09

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 14:15:49

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 14:15:57

Band 66_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 14:16:06

Band 66_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 14:16:14

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 19.OCT.2022 14:16:47

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 19.OCT.2022 14:16:54

Band 66_15 MHz_High_QPSK_RB75#0




Date: 19.OCT.2022 14:17:02

Band 66_15 MHz_High_16QAM_RB75#0




Date: 19.OCT.2022 14:17:09

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 19.OCT.2022 14:19:42

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 19.OCT.2022 14:19:49

Band 66_20 MHz_High_QPSK_RB100#0




Date: 19.OCT.2022 14:19:57

Band 66_20 MHz_High_16QAM_RB100#0




Date: 19.OCT.2022 14:20:04

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 16:03:03

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 16:03:10

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 16:03:17

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 16:03:23

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 16:06:03

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 16:06:10

Band 5_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 16:06:17

Band 5_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 16:06:23

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 16:07:03

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 16:07:10

Band 5_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 16:07:17

Band 5_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 16:07:24

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 16:09:49

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 16:09:57

Band 5_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 16:10:06

Band 5_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 16:10:14

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 19.OCT.2022 16:10:26

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 19.OCT.2022 16:10:32

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 19.OCT.2022 16:10:39

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 19.OCT.2022 16:10:45

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 19.OCT.2022 16:11:24

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 19.OCT.2022 16:11:32

Band 12_3 MHz_High_QPSK_RB15#0




Date: 19.OCT.2022 16:11:38

Band 12_3 MHz_High_16QAM_RB15#0




Date: 19.OCT.2022 16:11:45

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 16:12:17

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 16:12:25

Band 12_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 16:12:32

Band 12_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 16:12:38

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 19.OCT.2022 16:15:31

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 19.OCT.2022 16:15:40

Band 12_10 MHz_High_QPSK_RB50#0




Date: 19.OCT.2022 16:15:48

Band 12_10 MHz_High_16QAM_RB50#0




Date: 19.OCT.2022 16:15:55

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 19.OCT.2022 16:16:28

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 19.OCT.2022 16:16:35

Band 13_5 MHz_High_QPSK_RB25#0




Date: 19.OCT.2022 16:16:42

Band 13_5 MHz_High_16QAM_RB25#0




Date: 19.OCT.2022 16:16:49

Band 13_10 MHz_Low_QPSK_RB50#0




Date: 20.OCT.2022 13:34:23

Band 13_10 MHz_Low_16QAM_RB50#0




Date: 20.OCT.2022 13:34:52

Band 13_10 MHz_High_QPSK_RB50#0



Date: 20.OCT.2022 13:36:12

Band 13_10 MHz_High_16QAM_RB50#0



Date: 20.OCT.2022 13:35:45