



Cellular Band, Left Band Edge for GSM (GMSK) Mode




Date: 19.OCT.2021 20:03:11

Cellular Band, Right Band Edge for GSM (GMSK) Mode




Date: 19.OCT.2021 20:01:58

Cellular Band, Left Band Edge for EGPRS (8PSK) Mode




Date: 19.OCT.2021 19:56:53

Cellular Band, Right Band Edge for EGPRS (8PSK) Mode




Date: 19.OCT.2021 19:59:33

Cellular Band, Left Band Edge for WCDMA (BPSK) Mode




Date: 20.OCT.2021 09:30:52

Cellular Band, Right Band Edge for WCDMA (BPSK) Mode




Date: 20.OCT.2021 09:31:54


Cellular Band, Left Band Edge for HSDPA (16QAM) Mode




Cellular Band, Right Band Edge for HSDPA (16QAM) Mode




Cellular Band, Left Band Edge for HSUPA (BPSK) Mode




Cellular Band, Right Band Edge for HSUPA (BPSK) Mode




PCS Band, Left Band Edge for GSM (GMSK) Mode




PCS Band, Right Band Edge for GSM (GMSK) Mode




PCS Band, Left Band Edge for EGPRS (8PSK) Mode



PCS Band, Right Band Edge for EGPRS (8PSK) Mode




PCS Band, Left Band Edge for WCDMA (BPSK) Mode




Date: 20.OCT.2021 09:29:15

PCS Band, Right Band Edge for WCDMA (BPSK) Mode




Date: 20.OCT.2021 09:27:42


PCS Band, Left Band Edge for HSDPA (16QAM) Mode



PCS Band, Right Band Edge for HSDPA (16QAM) Mode




PCS Band, Left Band Edge for HSUPA (BPSK) Mode




Date: 20.OCT.2021 09:10:28

PCS Band, Right Band Edge for HSUPA (BPSK) Mode




Date: 20.OCT.2021 09:11:57

LTE Mode:




Date: 20.JAN.2022 17:25:12




Date: 20.JAN.2022 17:25:29

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 20.JAN.2022 17:25:58

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 20.JAN.2022 17:26:21

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 20.JAN.2022 17:26:43

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 20.JAN.2022 17:27:00

Band 2_3 MHz_High_QPSK_RB15#0




Date: 20.JAN.2022 17:27:17

Band 2_3 MHz_High_16QAM_RB15#0




Date: 20.JAN.2022 17:27:34

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 18:57:55

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 18:58:48

Band 2_5 MHz_High_QPSK_RB25#0




Date: 20.JAN.2022 19:00:04

Band 2_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 18:59:29

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 17:29:13

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 20.JAN.2022 17:29:32

Band 2_10 MHz_High_QPSK_RB50#0




Date: 20.JAN.2022 17:29:52

Band 2_10 MHz_High_16QAM_RB50#0




Date: 20.JAN.2022 17:30:11

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 20.JAN.2022 19:01:52

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 20.JAN.2022 17:30:59

Band 2_15 MHz_High_QPSK_RB75#0




Date: 20.JAN.2022 17:31:23

Band 2_15 MHz_High_16QAM_RB75#0




Date: 20.JAN.2022 17:31:47

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 20.JAN.2022 17:32:15

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 20.JAN.2022 17:32:42

Band 2_20 MHz_High_QPSK_RB100#0




Date: 20.JAN.2022 17:33:06

Band 2_20 MHz_High_16QAM_RB100#0




Date: 20.JAN.2022 17:33:29

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 20.JAN.2022 17:33:51

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 20.JAN.2022 17:34:11

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 20.JAN.2022 17:34:28

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 20.JAN.2022 17:34:48

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 20.JAN.2022 17:35:07

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 20.JAN.2022 17:35:24

Band 4_3 MHz_High_QPSK_RB15#0




Date: 20.JAN.2022 17:35:41

Band 4_3 MHz_High_16QAM_RB15#0




Date: 20.JAN.2022 17:35:58

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 19:03:36

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 19:04:14

Band 4_5 MHz_High_QPSK_RB25#0




Date: 20.JAN.2022 19:05:26

Band 4_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 19:04:54

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 17:37:34

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 20.JAN.2022 17:37:53

Band 4_10 MHz_High_QPSK_RB50#0




Date: 20.JAN.2022 17:38:13

Band 4_10 MHz_High_16QAM_RB50#0




Date: 20.JAN.2022 17:38:32

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 20.JAN.2022 19:06:45

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 20.JAN.2022 17:39:27

Band 4_15 MHz_High_QPSK_RB75#0




Date: 20.JAN.2022 19:07:27

Band 4_15 MHz_High_16QAM_RB75#0




Date: 20.JAN.2022 19:08:03

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 20.JAN.2022 17:40:46

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 20.JAN.2022 17:41:13

Band 4_20 MHz_High_QPSK_RB100#0




Date: 20.JAN.2022 17:41:37

Band 4_20 MHz_High_16QAM_RB100#0




Date: 20.JAN.2022 17:42:04

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 20.JAN.2022 17:42:25

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 20.JAN.2022 17:42:42

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 20.JAN.2022 17:43:03

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 20.JAN.2022 17:43:19

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 20.JAN.2022 17:43:38

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 20.JAN.2022 17:43:55

Band 5_3 MHz_High_QPSK_RB15#0




Date: 20.JAN.2022 17:44:12

Band 5_3 MHz_High_16QAM_RB15#0




Date: 20.JAN.2022 17:44:32

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 19:09:28

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 19:10:10

Band 5_5 MHz_High_QPSK_RB25#0




Date: 20.JAN.2022 19:11:37

Band 5_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 19:11:05

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 17:46:08

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 20.JAN.2022 17:46:27

Band 5_10 MHz_High_QPSK_RB50#0




Date: 20.JAN.2022 17:46:47

Band 5_10 MHz_High_16QAM_RB50#0




Date: 20.JAN.2022 17:47:06

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 19:12:31

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 19:13:16

Band 7_5 MHz_High_QPSK_RB25#0




Date: 20.JAN.2022 19:14:40

Band 7_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 19:13:54

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 17:48:46

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 20.JAN.2022 17:49:05

Band 7_10 MHz_High_QPSK_RB50#0




Date: 20.JAN.2022 17:49:25

Band 7_10 MHz_High_16QAM_RB50#0




Date: 20.JAN.2022 17:49:44

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 20.JAN.2022 19:15:56

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 20.JAN.2022 17:50:33

Band 7_15 MHz_High_QPSK_RB75#0




Date: 20.JAN.2022 19:16:34

Band 7_15 MHz_High_16QAM_RB75#0




Date: 20.JAN.2022 19:17:06

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 20.JAN.2022 17:51:49

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 20.JAN.2022 17:52:16

Band 7_20 MHz_High_QPSK_RB100#0




Date: 20.JAN.2022 17:52:40

Band 7_20 MHz_High_16QAM_RB100#0




Date: 20.JAN.2022 17:53:07

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 20.JAN.2022 17:53:31

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 20.JAN.2022 17:53:51

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 20.JAN.2022 17:54:09

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 20.JAN.2022 17:54:25

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 20.JAN.2022 17:54:47

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 20.JAN.2022 17:55:04

Band 12_3 MHz_High_QPSK_RB15#0




Date: 20.JAN.2022 17:55:21

Band 12_3 MHz_High_16QAM_RB15#0




Date: 20.JAN.2022 17:55:41

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 19:18:45

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 19:19:11

Band 12_5 MHz_High_QPSK_RB25#0




Date: 20.JAN.2022 19:20:19

Band 12_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 19:19:44

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 17:57:18

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 20.JAN.2022 17:57:37

Band 12_10 MHz_High_QPSK_RB50#0




Date: 20.JAN.2022 17:57:57

Band 12_10 MHz_High_16QAM_RB50#0




Date: 20.JAN.2022 17:58:16

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 19:21:29

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 19:21:56

Band 13_5 MHz_High_QPSK_RB25#0




Date: 20.JAN.2022 19:23:18

Band 13_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 19:22:43

Band 13_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 19:26:00

Band 13_10 MHz_Low_16QAM_RB50#0




Date: 26.JAN.2022 14:22:08

Band 13_10 MHz_High_QPSK_RB50#0




Date: 26.JAN.2022 14:26:19

Band 13_10 MHz_High_16QAM_RB50#0




Date: 20.JAN.2022 19:28:37

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 20.JAN.2022 18:52:25

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 20.JAN.2022 18:53:32

Band 17_5 MHz_High_QPSK_RB25#0




Date: 26.JAN.2022 13:26:35

Band 17_5 MHz_High_16QAM_RB25#0




Date: 20.JAN.2022 18:54:26

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 20.JAN.2022 18:04:49

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 20.JAN.2022 18:05:08

Band 17_10 MHz_High_QPSK_RB50#0



Date: 20.JAN.2022 18:05:27

Band 17_10 MHz_High_16QAM_RB50#0



Date: 20.JAN.2022 18:05:46