



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:54:20

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:54:30

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:54:47

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:54:58

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:55:14

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:55:25

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:55:44

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:55:54

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:56:11

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:56:22

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:56:38

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:56:49

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:57:08

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:57:18

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:57:35

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:57:46

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:58:06

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:58:16

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:58:37

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:58:48

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:59:10

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:59:21

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 13:59:40

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.AUG.2021 13:59:50

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:00:19

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:00:30

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:00:53

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:01:04

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:01:30

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:01:41

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:02:06

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:02:17

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:02:40

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:02:51

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:03:14

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:03:25

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:03:44

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:03:54

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:04:14

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:04:25

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:04:42

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:04:52

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:05:11

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:05:22

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:05:39

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:05:49

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:06:06

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:06:17

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:06:36

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:06:46

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:07:03

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:07:14

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:07:31

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:07:41

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:08:02

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:08:13

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:08:32

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:08:42

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:09:02

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:09:12

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:09:38

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:09:48

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:10:15

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:10:26

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:10:49

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:11:00

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:11:25

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:11:36

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:11:59

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:12:10

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:12:34

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 16.AUG.2021 14:12:44

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:13:06

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:13:17

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:13:37

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:13:47

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:14:07

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:14:18

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:14:36

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:14:47

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:15:04

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:15:14

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:15:31

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:15:42

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:16:04

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:16:14

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:16:31

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:16:42

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:16:58

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:17:09

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:17:30

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:17:40

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:17:59

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:18:24

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:18:43

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 16.AUG.2021 14:18:54

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:19:16

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:19:26

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:19:43

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:19:54

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:20:10

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:20:21

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:20:42

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:20:52

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:21:11

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:21:22

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:21:41

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:21:52

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:22:20

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:22:31

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:22:54

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:23:05

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:23:32

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:23:42

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:24:08

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:24:18

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:24:45

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:24:56

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 16.AUG.2021 14:25:19

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 16.AUG.2021 14:25:30

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:17:25

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:17:35

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:17:55

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:18:06

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:18:22

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:18:33

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:18:57

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:19:08

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:19:27

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:19:37

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:19:59

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:20:10

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:20:35

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:20:46

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:21:09

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:21:20

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:21:43

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:21:54

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:22:20

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:22:30

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:22:57

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:23:07

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:23:31

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:23:41

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:24:00

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:24:10

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:24:27

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:24:38

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:24:54

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:25:05

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:25:29

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:25:40

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:25:59

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:26:09

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:26:32

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:26:42

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:27:11

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:27:21

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:27:45

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:27:55

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:28:19

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:28:29

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:28:55

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:29:05

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 17.AUG.2021 14:29:32

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 17.AUG.2021 14:29:42

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 17.AUG.2021 14:30:09

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 17.AUG.2021 14:30:20