



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 16.AUG.2021 13:23:01

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 16.AUG.2021 13:23:18

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 16.AUG.2021 13:23:39

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 16.AUG.2021 13:23:59

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 16.AUG.2021 13:24:18

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 16.AUG.2021 13:24:35

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 16.AUG.2021 13:24:52

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 16.AUG.2021 13:25:12

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 16.AUG.2021 13:25:32

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 16.AUG.2021 13:25:52

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 16.AUG.2021 13:26:09

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 16.AUG.2021 13:26:29

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 16.AUG.2021 13:26:51

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 16.AUG.2021 13:27:10

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 16.AUG.2021 13:27:30


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 16.AUG.2021 13:27:49




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 16.AUG.2021 13:28:15

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 16.AUG.2021 13:28:39

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 16.AUG.2021 13:29:03

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 16.AUG.2021 13:29:27

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 16.AUG.2021 13:29:53

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 16.AUG.2021 13:30:17

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 16.AUG.2021 13:30:41

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 16.AUG.2021 13:31:08

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 16.AUG.2021 13:31:30

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 16.AUG.2021 13:31:50

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 16.AUG.2021 13:32:11

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 16.AUG.2021 13:32:31

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 16.AUG.2021 13:32:51

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 16.AUG.2021 13:33:11

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 16.AUG.2021 13:33:32


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 16.AUG.2021 13:33:48




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 16.AUG.2021 13:34:08

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 16.AUG.2021 13:34:25

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 16.AUG.2021 13:34:42

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 16.AUG.2021 13:34:59

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 16.AUG.2021 13:35:21

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 16.AUG.2021 13:35:40

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 16.AUG.2021 13:36:00

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 16.AUG.2021 13:36:19

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 16.AUG.2021 13:36:49

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 16.AUG.2021 13:37:12

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 16.AUG.2021 13:37:36

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 16.AUG.2021 13:38:00

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 16.AUG.2021 13:38:27

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 16.AUG.2021 13:38:51

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 16.AUG.2021 13:39:15


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 16.AUG.2021 13:39:42




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 18.AUG.2021 16:30:23

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 18.AUG.2021 16:35:38

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 16.AUG.2021 13:40:49

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 16.AUG.2021 13:41:05

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 16.AUG.2021 13:41:28

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 16.AUG.2021 13:41:45

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 16.AUG.2021 13:42:06

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 16.AUG.2021 13:42:23

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 18.AUG.2021 16:42:50

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.AUG.2021 16:43:55

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 18.AUG.2021 16:50:56

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 18.AUG.2021 16:51:51

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 16.AUG.2021 13:44:30

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 16.AUG.2021 13:44:49

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 16.AUG.2021 13:45:09


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 16.AUG.2021 13:45:28




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 16.AUG.2021 13:45:47

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 16.AUG.2021 13:46:07

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 16.AUG.2021 13:46:25

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 16.AUG.2021 13:46:42

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 16.AUG.2021 13:47:03

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 16.AUG.2021 13:47:22

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 16.AUG.2021 13:47:42

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 16.AUG.2021 13:48:04

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 16.AUG.2021 13:48:31

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 16.AUG.2021 13:48:55

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 16.AUG.2021 13:49:19

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 16.AUG.2021 13:49:43

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 16.AUG.2021 13:50:09

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 16.AUG.2021 13:50:33

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 16.AUG.2021 13:50:57


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 16.AUG.2021 13:51:21




### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 17.AUG.2021 13:57:41

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 17.AUG.2021 13:58:11

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 17.AUG.2021 13:58:37

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 17.AUG.2021 13:59:04

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 17.AUG.2021 13:59:31

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 17.AUG.2021 13:59:57

### Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 17.AUG.2021 14:00:16

### Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 17.AUG.2021 14:00:38

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 17.AUG.2021 14:01:11

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 17.AUG.2021 14:01:43

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 17.AUG.2021 14:02:20

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 17.AUG.2021 14:02:56

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 17.AUG.2021 14:03:35

### Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 17.AUG.2021 14:04:04

### Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 17.AUG.2021 14:04:41


### Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 17.AUG.2021 14:05:17




### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 17.AUG.2021 14:05:49

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 17.AUG.2021 14:06:18

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 17.AUG.2021 14:06:42

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 19.AUG.2021 15:10:55

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 17.AUG.2021 14:07:29

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 17.AUG.2021 14:07:55

### Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 17.AUG.2021 14:08:17

### Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 17.AUG.2021 14:08:43

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 17.AUG.2021 14:09:15

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 17.AUG.2021 14:09:45

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 19.AUG.2021 15:15:43

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 17.AUG.2021 14:10:42

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 17.AUG.2021 14:11:17

### Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 17.AUG.2021 14:11:44

### Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 17.AUG.2021 14:12:14

### Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 17.AUG.2021 14:12:44