



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 30.SEP.2022 13:36:03

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 30.SEP.2022 13:36:26

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.SEP.2022 13:36:41

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.SEP.2022 13:36:59

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 30.SEP.2022 13:37:17

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 30.SEP.2022 13:37:38

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 30.SEP.2022 13:38:36

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 30.SEP.2022 13:38:54

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 30.SEP.2022 13:39:09

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 30.SEP.2022 13:39:26

Band 2_3 MHz_High_QPSK_RB15#0




Date: 30.SEP.2022 13:39:45

Band 2_3 MHz_High_16QAM_RB15#0




Date: 30.SEP.2022 13:40:05

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 30.SEP.2022 13:41:31

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 30.SEP.2022 13:41:50

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 30.SEP.2022 13:42:12

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 30.SEP.2022 13:42:31

Band 2_5 MHz_High_QPSK_RB25#0




Date: 30.SEP.2022 13:42:54

Band 2_5 MHz_High_16QAM_RB25#0




Date: 30.SEP.2022 13:43:19

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 30.SEP.2022 13:48:54

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 30.SEP.2022 13:49:14

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 30.SEP.2022 13:49:34

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 30.SEP.2022 13:49:53

Band 2_10 MHz_High_QPSK_RB50#0




Date: 30.SEP.2022 13:50:17

Band 2_10 MHz_High_16QAM_RB50#0




Date: 30.SEP.2022 13:50:36

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 30.SEP.2022 13:51:40

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 30.SEP.2022 13:52:02

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 30.SEP.2022 13:52:25

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 30.SEP.2022 13:52:47

Band 2_15 MHz_High_QPSK_RB75#0




Date: 30.SEP.2022 13:53:10

Band 2_15 MHz_High_16QAM_RB75#0




Date: 30.SEP.2022 13:53:32

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 30.SEP.2022 13:54:34

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 30.SEP.2022 13:54:56

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 30.SEP.2022 13:55:20

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 30.SEP.2022 13:55:42

Band 2_20 MHz_High_QPSK_RB100#0




Date: 30.SEP.2022 13:56:05

Band 2_20 MHz_High_16QAM_RB100#0




Date: 30.SEP.2022 13:56:28

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 30.SEP.2022 13:56:51

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 30.SEP.2022 13:57:06

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.SEP.2022 13:57:25

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.SEP.2022 13:57:43

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 30.SEP.2022 13:58:21

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 30.SEP.2022 13:58:42

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 30.SEP.2022 13:59:25

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 30.SEP.2022 13:59:47

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 30.SEP.2022 14:00:03

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 30.SEP.2022 14:00:19

Band 4_3 MHz_High_QPSK_RB15#0




Date: 30.SEP.2022 14:00:38

Band 4_3 MHz_High_16QAM_RB15#0




Date: 30.SEP.2022 14:01:02

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 30.SEP.2022 14:01:50

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 30.SEP.2022 14:02:09

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 30.SEP.2022 14:02:28

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 30.SEP.2022 14:02:44

Band 4_5 MHz_High_QPSK_RB25#0




Date: 30.SEP.2022 14:03:07

Band 4_5 MHz_High_16QAM_RB25#0




Date: 30.SEP.2022 14:03:22

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 30.SEP.2022 14:04:26

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 30.SEP.2022 14:04:55

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 30.SEP.2022 14:05:15

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 30.SEP.2022 14:05:35

Band 4_10 MHz_High_QPSK_RB50#0




Date: 30.SEP.2022 14:05:52

Band 4_10 MHz_High_16QAM_RB50#0




Date: 30.SEP.2022 14:06:11

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 30.SEP.2022 14:07:25

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 30.SEP.2022 14:07:44

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 30.SEP.2022 14:08:07

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 30.SEP.2022 14:08:29

Band 4_15 MHz_High_QPSK_RB75#0




Date: 30.SEP.2022 14:08:49

Band 4_15 MHz_High_16QAM_RB75#0




Date: 30.SEP.2022 14:09:10

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 30.SEP.2022 14:10:55

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 30.SEP.2022 14:11:17

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 30.SEP.2022 14:11:44

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 30.SEP.2022 14:12:06

Band 4_20 MHz_High_QPSK_RB100#0




Date: 30.SEP.2022 14:12:26

Band 4_20 MHz_High_16QAM_RB100#0




Date: 30.SEP.2022 14:12:49

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 30.SEP.2022 14:13:23

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 30.SEP.2022 14:13:42

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 30.SEP.2022 14:14:01

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 30.SEP.2022 14:14:23

Band 7_5 MHz_High_QPSK_RB25#0




Date: 30.SEP.2022 14:14:42

Band 7_5 MHz_High_16QAM_RB25#0




Date: 30.SEP.2022 14:15:04

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 30.SEP.2022 14:15:59

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 30.SEP.2022 14:16:18

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 30.SEP.2022 14:16:38

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 30.SEP.2022 14:16:58

Band 7_10 MHz_High_QPSK_RB50#0




Date: 30.SEP.2022 14:17:18

Band 7_10 MHz_High_16QAM_RB50#0




Date: 30.SEP.2022 14:17:37

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 30.SEP.2022 14:19:02

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 30.SEP.2022 14:19:24

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 30.SEP.2022 14:19:47

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 30.SEP.2022 14:20:12

Band 7_15 MHz_High_QPSK_RB75#0




Date: 30.SEP.2022 14:20:35

Band 7_15 MHz_High_16QAM_RB75#0




Date: 30.SEP.2022 14:20:54

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 30.SEP.2022 14:23:02

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 30.SEP.2022 14:23:24

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 30.SEP.2022 14:23:47

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 30.SEP.2022 14:24:10

Band 7_20 MHz_High_QPSK_RB100#0




Date: 30.SEP.2022 14:24:36

Band 7_20 MHz_High_16QAM_RB100#0




Date: 30.SEP.2022 14:25:02

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 30.SEP.2022 16:26:25

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 30.SEP.2022 16:26:53

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 30.SEP.2022 16:27:12

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 30.SEP.2022 16:27:30

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 30.SEP.2022 16:27:52

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 30.SEP.2022 16:28:14

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 30.SEP.2022 16:30:21

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 30.SEP.2022 16:30:46

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 30.SEP.2022 16:31:01

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 30.SEP.2022 16:31:20

Band 5_3 MHz_High_QPSK_RB15#0




Date: 30.SEP.2022 16:31:36

Band 5_3 MHz_High_16QAM_RB15#0




Date: 30.SEP.2022 16:31:54

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 30.SEP.2022 16:32:38

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 30.SEP.2022 16:32:57

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 30.SEP.2022 16:33:17

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 30.SEP.2022 16:33:36

Band 5_5 MHz_High_QPSK_RB25#0




Date: 30.SEP.2022 16:34:01

Band 5_5 MHz_High_16QAM_RB25#0




Date: 30.SEP.2022 16:34:23

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 30.SEP.2022 16:38:58

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 30.SEP.2022 16:39:17

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 30.SEP.2022 16:39:37

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 30.SEP.2022 16:39:57

Band 5_10 MHz_High_QPSK_RB50#0




Date: 30.SEP.2022 16:40:17

Band 5_10 MHz_High_16QAM_RB50#0




Date: 30.SEP.2022 16:40:36

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 8.OCT.2022 09:16:34

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 8.OCT.2022 09:17:05

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 8.OCT.2022 09:17:28

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 8.OCT.2022 09:18:03

Band 38_5 MHz_High_QPSK_RB25#0




Date: 8.OCT.2022 09:18:25

Band 38_5 MHz_High_16QAM_RB25#0




Date: 8.OCT.2022 09:18:54

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 8.OCT.2022 09:29:16

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 8.OCT.2022 09:29:42

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 8.OCT.2022 09:30:11

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 8.OCT.2022 09:30:40

Band 38_10 MHz_High_QPSK_RB50#0




Date: 8.OCT.2022 09:31:13

Band 38_10 MHz_High_16QAM_RB50#0




Date: 8.OCT.2022 09:31:35

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 8.OCT.2022 09:32:46

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 8.OCT.2022 09:33:18

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 8.OCT.2022 09:33:57

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 8.OCT.2022 09:34:22

Band 38_15 MHz_High_QPSK_RB75#0




Date: 8.OCT.2022 09:34:51

Band 38_15 MHz_High_16QAM_RB75#0




Date: 8.OCT.2022 09:35:23

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 8.OCT.2022 09:36:20

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 8.OCT.2022 09:37:01

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 8.OCT.2022 09:37:28

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 8.OCT.2022 09:37:56

Band 38_20 MHz_High_QPSK_RB100#0




Date: 8.OCT.2022 09:38:23

Band 38_20 MHz_High_16QAM_RB100#0




Date: 8.OCT.2022 09:39:01

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 8.OCT.2022 10:29:13

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 8.OCT.2022 10:29:47

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 8.OCT.2022 10:30:15

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 8.OCT.2022 10:30:42

Band 41_5 MHz_High_QPSK_RB25#0




Date: 8.OCT.2022 10:31:11

Band 41_5 MHz_High_16QAM_RB25#0




Date: 8.OCT.2022 10:31:45

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 8.OCT.2022 10:32:10

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 8.OCT.2022 10:32:34

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 8.OCT.2022 10:33:02

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 8.OCT.2022 10:33:33

Band 41_10 MHz_High_QPSK_RB50#0




Date: 8.OCT.2022 10:33:58

Band 41_10 MHz_High_16QAM_RB50#0




Date: 8.OCT.2022 10:34:25

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 8.OCT.2022 10:35:00

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 8.OCT.2022 10:35:26

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 8.OCT.2022 10:35:52

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 8.OCT.2022 10:36:27

Band 41_15 MHz_High_QPSK_RB75#0




Date: 8.OCT.2022 10:36:53

Band 41_15 MHz_High_16QAM_RB75#0




Date: 8.OCT.2022 10:37:18

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 8.OCT.2022 10:37:53

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 8.OCT.2022 10:38:21

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 8.OCT.2022 10:38:50

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 8.OCT.2022 10:39:12

Band 41_20 MHz_High_QPSK_RB100#0



Date: 8.OCT.2022 10:39:41

Band 41_20 MHz_High_16QAM_RB100#0



Date: 8.OCT.2022 10:40:16