



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:49:19

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:49:30

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:49:44

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:49:55

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:50:08

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:50:19

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:52:25

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:52:37

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:52:50

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:53:01

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:53:18

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:53:29

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:54:17

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:54:29

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:54:42

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:54:53

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:55:10

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:55:21

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:57:46

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:57:57

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:58:11

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:58:22

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:58:36

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.SEP.2022 14:58:47

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 14:59:55

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:00:06

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:00:23

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:00:34

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:00:52

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:01:03

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:01:56

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:02:07

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:02:21

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:02:32

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:02:47

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:02:58

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:03:16

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:03:27

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:03:41

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:03:52

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:04:08

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:04:20

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:05:00

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:05:11

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:05:25

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:05:36

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:05:49

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:06:00

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:06:38

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:06:49

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:07:03

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:07:14

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:07:27

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:07:39

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:08:20

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:08:31

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:08:45

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:08:56

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:09:10

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:09:21

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:10:11

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:10:22

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:10:37

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:10:48

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:11:05

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:11:17

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:15:05

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:15:16

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:15:30

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:15:41

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:15:56

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 30.SEP.2022 15:16:07

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:16:26

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:16:37

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:16:54

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:17:05

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:17:19

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:17:30

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:18:18

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:18:29

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:18:43

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:18:54

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:19:08

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:19:19

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:20:17

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:20:28

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:20:42

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:20:53

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:21:11

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:21:22

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:22:48

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:22:59

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:23:13

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:23:24

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 30.SEP.2022 15:23:42

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 30.SEP.2022 15:23:53

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:48:58

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:49:09

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:49:26

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:49:37

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:49:51

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:50:02

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:50:54

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:51:05

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:51:22

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:51:33

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:51:46

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:51:57

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:52:35

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:52:46

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:53:00

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:53:11

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:53:28

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:53:39

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:54:36

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:54:47

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:55:04

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:55:16

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 30.SEP.2022 16:55:33

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 30.SEP.2022 16:55:44

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:47:42

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:47:53

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:48:10

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:48:21

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:48:38

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:48:49

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:51:02

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:51:13

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:51:30

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:51:41

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:51:55

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:52:06

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:53:23

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:53:34

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:53:52

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:54:03

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:54:17

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:54:28

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:55:07

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:55:18

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:55:33

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:55:44

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.OCT.2022 09:56:02

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 09:56:13

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:44:06

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:44:17

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:44:33

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:44:45

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:44:58

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:45:09

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:45:26

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:45:37

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:45:51

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:46:02

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:46:19

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:46:30

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:46:50

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:47:01

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:47:18

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:47:30

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:47:44

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:47:55

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:48:12

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:48:23

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 8.OCT.2022 10:48:38

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 8.OCT.2022 10:48:49

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 8.OCT.2022 10:49:03

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 8.OCT.2022 10:49:14