



Please refer to following plots:

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 1.DEC.2022 13:44:02

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 1.DEC.2022 13:44:09

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 1.DEC.2022 13:44:20

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 1.DEC.2022 13:44:27

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 1.DEC.2022 13:46:19

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 1.DEC.2022 13:46:26

Band 5_3 MHz_High_QPSK_RB15#0




Date: 1.DEC.2022 13:46:34

Band 5_3 MHz_High_16QAM_RB15#0




Date: 1.DEC.2022 13:46:41

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 1.DEC.2022 13:46:50

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 1.DEC.2022 13:46:57

Band 5_5 MHz_High_QPSK_RB25#0




Date: 1.DEC.2022 13:47:06

Band 5_5 MHz_High_16QAM_RB25#0




Date: 1.DEC.2022 13:47:14

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 1.DEC.2022 13:47:24

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 1.DEC.2022 13:47:32

Band 5_10 MHz_High_QPSK_RB50#0




Date: 1.DEC.2022 13:47:42

Band 5_10 MHz_High_16QAM_RB50#0




Date: 1.DEC.2022 13:47:51

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 17.DEC.2022 10:13:25

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 17.DEC.2022 10:13:34

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 17.DEC.2022 10:13:43

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 17.DEC.2022 10:13:51

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 17.DEC.2022 10:14:00

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 17.DEC.2022 10:14:07

Band 2_3 MHz_High_QPSK_RB15#0




Date: 17.DEC.2022 10:14:15

Band 2_3 MHz_High_16QAM_RB15#0




Date: 17.DEC.2022 10:14:23

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 17.DEC.2022 10:14:33

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 17.DEC.2022 10:14:40

Band 2_5 MHz_High_QPSK_RB25#0




Date: 17.DEC.2022 10:14:49

Band 2_5 MHz_High_16QAM_RB25#0




Date: 17.DEC.2022 10:14:57

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 17.DEC.2022 10:15:09

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 17.DEC.2022 10:15:17

Band 2_10 MHz_High_QPSK_RB50#0




Date: 17.DEC.2022 10:15:27

Band 2_10 MHz_High_16QAM_RB50#0




Date: 17.DEC.2022 10:15:35

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 17.DEC.2022 10:15:46

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 17.DEC.2022 10:15:54

Band 2_15 MHz_High_QPSK_RB75#0




Date: 17.DEC.2022 10:16:02

Band 2_15 MHz_High_16QAM_RB75#0




Date: 17.DEC.2022 10:16:09

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 17.DEC.2022 10:16:19

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 17.DEC.2022 10:16:27

Band 2_20 MHz_High_QPSK_RB100#0




Date: 17.DEC.2022 10:16:35

Band 2_20 MHz_High_16QAM_RB100#0




Date: 17.DEC.2022 10:16:43

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 17.DEC.2022 10:16:55

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 17.DEC.2022 10:17:02

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 17.DEC.2022 10:17:10

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 17.DEC.2022 10:17:16

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 17.DEC.2022 10:17:27

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 17.DEC.2022 10:17:35

Band 4_3 MHz_High_QPSK_RB15#0




Date: 17.DEC.2022 10:17:43

Band 4_3 MHz_High_16QAM_RB15#0




Date: 17.DEC.2022 10:17:49

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 17.DEC.2022 10:18:01

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 17.DEC.2022 10:18:09

Band 4_5 MHz_High_QPSK_RB25#0




Date: 17.DEC.2022 10:18:17

Band 4_5 MHz_High_16QAM_RB25#0




Date: 17.DEC.2022 10:18:25

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 17.DEC.2022 10:18:37

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 17.DEC.2022 10:18:46

Band 4_10 MHz_High_QPSK_RB50#0




Date: 17.DEC.2022 10:18:55

Band 4_10 MHz_High_16QAM_RB50#0




Date: 17.DEC.2022 10:19:03

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 17.DEC.2022 10:19:14

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 17.DEC.2022 10:19:22

Band 4_15 MHz_High_QPSK_RB75#0




Date: 17.DEC.2022 10:19:30

Band 4_15 MHz_High_16QAM_RB75#0




Date: 17.DEC.2022 10:19:38

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 17.DEC.2022 10:19:48

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 17.DEC.2022 10:19:57

Band 4_20 MHz_High_QPSK_RB100#0




Date: 17.DEC.2022 10:20:06

Band 4_20 MHz_High_16QAM_RB100#0




Date: 17.DEC.2022 10:20:14

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 17.DEC.2022 15:16:50

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 17.DEC.2022 15:17:12

Band 7_5 MHz_High_QPSK_RB25#0




Date: 17.DEC.2022 15:17:39

Band 7_5 MHz_High_16QAM_RB25#0




Date: 17.DEC.2022 15:17:56

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 1.DEC.2022 15:33:29

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 1.DEC.2022 15:34:19

Band 7_10 MHz_High_QPSK_RB50#0




Date: 1.DEC.2022 15:35:01

Band 7_10 MHz_High_16QAM_RB50#0




Date: 1.DEC.2022 15:36:34

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 4.JAN.2023 17:35:28

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 4.JAN.2023 17:35:47

Band 7_15 MHz_High_QPSK_RB75#0




Date: 4.JAN.2023 17:36:29

Band 7_15 MHz_High_16QAM_RB75#0




Date: 4.JAN.2023 17:36:53

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 1.DEC.2022 15:40:24

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 1.DEC.2022 15:40:43

Band 7_20 MHz_High_QPSK_RB100#0




Date: 1.DEC.2022 15:41:14

Band 7_20 MHz_High_16QAM_RB100#0




Date: 1.DEC.2022 15:41:33

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 10.DEC.2022 19:42:23

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 1.DEC.2022 15:58:23

Band 41_5 MHz_High_QPSK_RB25#0




Date: 1.DEC.2022 15:59:53

Band 41_5 MHz_High_16QAM_RB25#0




Date: 1.DEC.2022 16:00:37

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 28.DEC.2022 16:43:20

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 28.DEC.2022 16:43:35

Band 41_10 MHz_High_QPSK_RB50#0




Date: 28.DEC.2022 16:44:00

Band 41_10 MHz_High_16QAM_RB50#0




Date: 28.DEC.2022 16:44:23

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 28.DEC.2022 16:45:26

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 28.DEC.2022 16:45:47

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 28.DEC.2022 16:47:18

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 28.DEC.2022 16:47:43

Band 41_20 MHz_High_QPSK_RB100#0




Date: 28.DEC.2022 16:48:09

Band 41_20 MHz_High_16QAM_RB100#0




Date: 28.DEC.2022 16:48:29

Band 38_5 MHz_Low_QPSK_RB25#0



Date: 9.JAN.2023 15:59:38

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 9.JAN.2023 16:00:38

Band 38_5 MHz_High_QPSK_RB25#0



* RBW 100 kHz
* VBW 300 kHz
* SWT 5 s




Date: 9.JAN.2023 16:01:12

Band 38_5 MHz_High_16QAM_RB25#0




* RBW 100 kHz
* VBW 300 kHz
* SWT 5 s




Date: 9.JAN.2023 16:01:29

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 9.JAN.2023 16:02:20

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 9.JAN.2023 16:02:44

Band 38_10 MHz_High_QPSK_RB50#0




Date: 9.JAN.2023 16:03:11

Band 38_10 MHz_High_16QAM_RB50#0




Date: 9.JAN.2023 16:03:30

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 9.JAN.2023 16:04:51

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 9.JAN.2023 16:05:09

Band 38_15 MHz_High_QPSK_RB75#0




Date: 9.JAN.2023 16:05:40

Band 38_15 MHz_High_16QAM_RB75#0




Date: 9.JAN.2023 16:05:59

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 9.JAN.2023 16:06:52

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 9.JAN.2023 16:07:10

Band 38_20 MHz_High_QPSK_RB100#0



Date: 9.JAN.2023 16:07:51

Band 38_20 MHz_High_16QAM_RB100#0



Date: 9.JAN.2023 16:08:18