



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:35:04

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:35:15

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:35:35

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:35:45

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:36:05

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:36:16

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:36:35

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:36:46

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:37:02

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:37:13

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:37:33

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:37:44

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:38:02

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:38:13

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:38:30

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:38:40

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:38:57

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:39:08

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:39:29

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:39:40

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:39:59

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:40:09

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:40:29

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:40:39

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:41:08

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:41:19

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:41:43

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:41:53

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:42:17

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:42:27

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:42:53

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:43:03

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:43:27

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:43:38

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:44:01

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:44:12

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:44:34

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:44:45

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:45:01

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:45:12

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:45:29

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:45:40

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:45:58

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:46:09

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:46:26

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:46:37

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:46:53

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:47:04

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:47:26

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:47:37

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:47:54

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:48:04

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:48:21

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:48:32

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:48:56

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:49:07

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:49:29

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:49:40

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:50:02

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:50:12

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:50:39

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:50:49

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:51:13

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:51:24

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:51:47

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:51:58

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:52:26

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:52:37

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:53:04

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:53:15

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:53:41

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 27.MAY.2021 02:53:52

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:54:14

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:54:28

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:54:45

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:54:56

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:55:12

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:55:23

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:55:42

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:55:52

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:56:12

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:56:23

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:56:40

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:56:50

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:57:09

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:57:20

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:57:40

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:57:51

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:58:12

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:58:23

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:58:44

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:58:55

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:59:14

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:59:25

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 02:59:47

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 27.MAY.2021 02:59:57

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:00:16

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:00:27

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:00:44

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:00:54

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:01:11

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:01:22

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:01:43

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:01:54

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:02:13

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:02:23

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:02:46

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:02:56

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:03:22

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:03:33

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:03:59

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:04:10

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:04:33

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:04:44

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:05:13

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:05:23

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:05:50

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:06:01

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 27.MAY.2021 03:06:24

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 27.MAY.2021 03:06:35

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:42:24

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:42:35

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:42:52

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:43:02

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:43:22

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:43:33

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:43:54

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:44:05

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:44:27

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:44:38

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:45:00

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:45:10

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:45:36

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:45:47

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:46:13

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:46:24

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:46:50

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:47:01

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:47:27

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:47:37

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:48:04

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:48:14

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.MAY.2021 20:48:41

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 20:48:52

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:23:31

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:23:41

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:23:58

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:24:09

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:24:29

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:24:39

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:25:03

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:25:14

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:25:33

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:25:44

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:26:03

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:26:13

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:26:39

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:26:49

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:27:13

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:27:24

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:27:47

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:27:58

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:28:27

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:28:38

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 26.MAY.2021 23:29:04

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 26.MAY.2021 23:29:15

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 26.MAY.2021 23:29:38

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 26.MAY.2021 23:29:49