



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 27.MAY.2021 02:04:18

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 27.MAY.2021 02:04:38

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 27.MAY.2021 02:04:59

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 27.MAY.2021 02:05:19

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 27.MAY.2021 02:05:41

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 27.MAY.2021 02:06:01

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 27.MAY.2021 02:06:22

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 27.MAY.2021 02:06:42

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 27.MAY.2021 02:07:01

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 27.MAY.2021 02:07:21

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 27.MAY.2021 02:07:45

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 27.MAY.2021 02:08:05

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 27.MAY.2021 02:08:30

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 27.MAY.2021 02:08:49

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 27.MAY.2021 02:09:09


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 27.MAY.2021 02:09:31




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 27.MAY.2021 02:10:01

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 27.MAY.2021 02:10:27

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 27.MAY.2021 02:10:52

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 27.MAY.2021 02:11:15

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 27.MAY.2021 02:11:45

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 27.MAY.2021 02:12:11

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 27.MAY.2021 02:12:36

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 27.MAY.2021 02:12:59

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 27.MAY.2021 02:13:25

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 27.MAY.2021 02:13:45

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 27.MAY.2021 02:14:06

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 27.MAY.2021 02:14:26

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 27.MAY.2021 02:14:46

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 27.MAY.2021 02:15:02

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 27.MAY.2021 02:15:23


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 27.MAY.2021 02:15:43




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 27.MAY.2021 02:16:03

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 27.MAY.2021 02:16:26

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 27.MAY.2021 02:16:47

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 27.MAY.2021 02:17:07

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 27.MAY.2021 02:17:29

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 27.MAY.2021 02:17:48

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 27.MAY.2021 02:18:11

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 27.MAY.2021 02:18:33

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 27.MAY.2021 02:19:06

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 27.MAY.2021 02:19:33

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 27.MAY.2021 02:19:57

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 27.MAY.2021 02:20:24

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 27.MAY.2021 02:20:53

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 27.MAY.2021 02:21:23

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 27.MAY.2021 02:21:48


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 27.MAY.2021 02:22:20




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 27.MAY.2021 02:22:43

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 27.MAY.2021 02:23:03

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 14.JUL.2021 11:05:39

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 14.JUL.2021 11:10:20

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 27.MAY.2021 02:23:57

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 27.MAY.2021 02:24:17

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 27.MAY.2021 02:24:34

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 27.MAY.2021 02:24:51

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 27.MAY.2021 02:25:13

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 27.MAY.2021 02:25:30

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 27.MAY.2021 02:25:54

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 27.MAY.2021 02:26:14

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 27.MAY.2021 02:26:36

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 27.MAY.2021 02:26:55

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 27.MAY.2021 02:27:18


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 27.MAY.2021 02:27:40




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 27.MAY.2021 02:28:03

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 27.MAY.2021 02:28:23

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 27.MAY.2021 02:28:46

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 27.MAY.2021 02:29:06

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 27.MAY.2021 02:29:28

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 27.MAY.2021 02:29:48

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 27.MAY.2021 02:30:10

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 27.MAY.2021 02:30:33

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 27.MAY.2021 02:30:59

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 27.MAY.2021 02:31:22

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 27.MAY.2021 02:31:47

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 27.MAY.2021 02:32:10

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 27.MAY.2021 02:32:39

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 27.MAY.2021 02:33:06

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 27.MAY.2021 02:33:31


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 27.MAY.2021 02:33:57




### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 26.MAY.2021 20:34:07

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 26.MAY.2021 20:34:36

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 26.MAY.2021 20:35:03

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 26.MAY.2021 20:35:29

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 26.MAY.2021 20:35:54

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 26.MAY.2021 20:36:16

### Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 26.MAY.2021 20:36:39

### Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 26.MAY.2021 20:37:01

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 26.MAY.2021 20:37:28

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 26.MAY.2021 20:37:55

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 26.MAY.2021 20:38:22

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 26.MAY.2021 20:38:52

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 26.MAY.2021 20:39:22

### Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 26.MAY.2021 20:39:48

### Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 26.MAY.2021 20:40:19


### Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 26.MAY.2021 20:40:52




### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 26.MAY.2021 23:15:27

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 26.MAY.2021 23:15:57

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 26.MAY.2021 23:16:20

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 26.MAY.2021 23:16:40

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 26.MAY.2021 23:17:05

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 26.MAY.2021 23:17:30

### Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 26.MAY.2021 23:17:53

### Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 26.MAY.2021 23:18:15

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 26.MAY.2021 23:18:48

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 26.MAY.2021 23:19:18

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 26.MAY.2021 23:19:48

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 26.MAY.2021 23:20:15

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 26.MAY.2021 23:20:41

### Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 26.MAY.2021 23:21:07

### Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 26.MAY.2021 23:21:38

### Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 26.MAY.2021 23:22:04