INFINIX MOBILITY LIMITED Address: FLAT 39 8/F BLOCK D WAH LOK INDUSTRIAL CENTRE 31-35 SHAN MEI STREET FOTAN NT, Hong Kong Tel: +86-755-61803856 Fax: +86-755-33979211 Email: yiting.luo@transsion.com

Date: 2021-8-23

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Dear Sir/Madam,

The Main chip, model: MT6769 installed in our product Mobile Phone, model: X6812B, FCC ID: 2AIZN-X6812B, this chip supports LTE function, but for marketing purpose, this chip only supports LTE band 2/4/5/7/38/41, not support other LTE bands. The other LTE bands was disabled to use by manufacture in the software, the end user has no capability to activate it.

The RF chip, model: MT6631 installed in our product Mobile Phone, model: X6812B, FCC ID: 2AIZN-X6812B, supports 5G Wi-Fi function, but for marketing purpose, this chip only supports 5G Wi-Fi(5150-5250 MHz; 5725-5850 MHz). The 5G Wi-Fi (5250-5350 MHz, 5470-5725 MHz) was disabled to use by manufacture in the software, the end user has no capability to activate it.

Signatute:19 . LW

Yiting Luo Project Manager