



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:04:21

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:04:33

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:04:50

### Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:05:02

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:05:19

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:05:31

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:05:49

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:06:00

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:06:21

### Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:06:32

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:06:53

### Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:07:04

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:07:23

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:07:34

### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:07:52


### Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)



Date: 29.AUG.2021 19:08:03




### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:08:24

### Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:08:36

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:08:56

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:09:08

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:09:27

### Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:09:39

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:10:02

### Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:10:13

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:10:38

### Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:10:50

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:11:17

### Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:11:29

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:11:53

### Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:12:04

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:12:29


### Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)



Date: 29.AUG.2021 19:12:41




### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:13:05

### Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:13:16

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:13:41

### Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:13:52

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:14:14

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:14:25

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:14:46

### Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:14:57

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:15:18

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:15:30

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:15:51

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:16:03

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:16:23

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:16:35

### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:16:52


### Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)



Date: 29.AUG.2021 19:17:04




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:17:22

### Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:17:33

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:17:54

### Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:18:06

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:18:23

### Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:18:34

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:18:55

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:19:06

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:19:26

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:19:37

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:20:00

### Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:20:12

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:20:36

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:20:48

### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:21:12


### Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)



Date: 29.AUG.2021 19:21:24




### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:21:48

### Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:21:59

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:22:24

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:22:35

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:22:59

### Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:23:11

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:23:35

### Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 29.AUG.2021 19:23:47

Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:24:12

Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:24:23

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:24:44

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:24:55

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:25:16

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:25:27

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:25:49


### Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)



Date: 29.AUG.2021 19:26:00




### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:26:21

### Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:26:32

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:26:53

### Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:27:04

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:27:23

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:27:34

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:27:55

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:28:10

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:28:27

### Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 29.AUG.2021 19:28:42






### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:30:05


### Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 29.AUG.2021 19:30:17




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:30:38

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:30:50

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:31:07

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:31:19

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:31:36

### Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:31:48

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:32:08

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:32:20

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:32:39

### Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:32:51

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:33:14

### Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:33:25

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:33:50

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:34:01

### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 19:34:24


### Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 29.AUG.2021 19:34:36




### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:35:00

### Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:35:11

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:35:40

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:35:51

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:36:15

### Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:36:27

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 19:36:51

### Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 19:37:02

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:11:03

### Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:11:14

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:11:35

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:11:46

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:12:04

### Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:12:15

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 21:12:36


### Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)



Date: 29.AUG.2021 21:12:47




### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:13:07

### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:13:18

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:13:38

### Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:13:50

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:14:18

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:14:29

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:14:53

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:15:05

### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:15:32

### Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:15:44

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:16:12

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:16:24

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:16:48

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:16:59

### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 21:17:26


### Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 29.AUG.2021 21:17:38




Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:17:56

Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:18:08

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:18:29

Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:18:40

### Band 41\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:18:58

### Band 41\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:19:09

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:19:30

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:19:42

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:20:01

Band 41\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:20:13

### Band 41\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:20:32

### Band 41\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:20:44

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:21:09

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:21:20

Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 21:21:44


Band 41\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 29.AUG.2021 21:21:56




### Band 41\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:22:20

### Band 41\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:22:32

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:22:57

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:23:08

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 29.AUG.2021 21:23:32

Band 41\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 29.AUG.2021 21:23:44

### Band 41\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)



Date: 29.AUG.2021 21:24:08

### Band 41\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)



Date: 29.AUG.2021 21:24:19