



Please refer to following plots:

### Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 15.SEP.2021 16:45:48

### Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 15.SEP.2021 16:46:09

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 15.SEP.2021 16:46:40

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 15.SEP.2021 16:47:10

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 15.SEP.2021 16:47:32

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 15.SEP.2021 18:54:55

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 15.SEP.2021 16:48:17

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 15.SEP.2021 16:48:44

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.SEP.2021 16:49:16

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.SEP.2021 16:49:47

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.SEP.2021 16:50:05

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.SEP.2021 16:50:22

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.SEP.2021 16:50:46

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.SEP.2021 18:39:15

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 15.SEP.2021 18:40:15


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 15.SEP.2021 18:41:13




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.SEP.2021 18:42:37

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.SEP.2021 16:52:49

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.SEP.2021 16:53:14

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.SEP.2021 16:53:38

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.SEP.2021 16:54:27

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.SEP.2021 16:54:54

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 15.SEP.2021 16:55:19

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 15.SEP.2021 16:55:43

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 15.SEP.2021 16:56:06

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 15.SEP.2021 16:56:23

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 15.SEP.2021 16:56:45

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 15.SEP.2021 16:57:02

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 15.SEP.2021 16:57:21

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 15.SEP.2021 16:57:42

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 15.SEP.2021 16:58:00


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 15.SEP.2021 16:58:17




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.SEP.2021 16:58:36

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.SEP.2021 16:58:54

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.SEP.2021 16:59:12

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.SEP.2021 16:59:30

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.SEP.2021 16:59:51

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.SEP.2021 17:00:11

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.SEP.2021 17:00:31

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.SEP.2021 17:00:54

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.SEP.2021 17:01:19

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.SEP.2021 17:01:44

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.SEP.2021 17:02:09

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.SEP.2021 17:02:36

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.SEP.2021 18:51:36

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.SEP.2021 18:52:24

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 15.SEP.2021 17:03:51


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 15.SEP.2021 17:04:15




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 15.SEP.2021 17:04:37

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 15.SEP.2021 17:04:55

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 15.SEP.2021 17:05:13

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 15.SEP.2021 17:05:34

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 15.SEP.2021 17:05:53

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 15.SEP.2021 17:06:13

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 15.SEP.2021 17:06:35

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 15.SEP.2021 17:06:52

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.SEP.2021 17:07:14

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.SEP.2021 17:07:35

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.SEP.2021 17:07:56

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.SEP.2021 17:08:17

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.SEP.2021 17:08:42

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.SEP.2021 17:09:05

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 15.SEP.2021 17:09:28


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 15.SEP.2021 17:09:48




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.SEP.2021 19:01:43

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.SEP.2021 17:10:28

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.SEP.2021 17:10:49

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.SEP.2021 17:11:07

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.SEP.2021 17:11:28

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.SEP.2021 18:57:51

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.SEP.2021 17:12:12

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.SEP.2021 17:12:31

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.SEP.2021 17:12:57

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.SEP.2021 17:13:21

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.SEP.2021 17:13:46

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.SEP.2021 17:14:10

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.SEP.2021 17:14:36

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.SEP.2021 17:15:00

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 15.SEP.2021 17:15:25


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 15.SEP.2021 17:15:50




### Band 38\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.SEP.2021 17:37:01

### Band 38\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.SEP.2021 17:37:32

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.SEP.2021 19:04:54

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.SEP.2021 17:38:17

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.SEP.2021 17:38:41

### Band 38\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.SEP.2021 19:06:10

### Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.SEP.2021 17:39:31

### Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.SEP.2021 17:39:54

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.SEP.2021 17:40:26

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.SEP.2021 17:40:53

### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.SEP.2021 17:41:27

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.SEP.2021 17:41:55

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.SEP.2021 17:42:27

### Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.SEP.2021 17:42:54

### Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 15.SEP.2021 17:43:22


### Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 15.SEP.2021 17:43:49




### Band 41\_5 MHz\_Low\_QPSK\_RB25#0




Date: 15.SEP.2021 19:14:01

### Band 41\_5 MHz\_Low\_16QAM\_RB25#0




Date: 15.SEP.2021 17:59:54

### Band 41\_5 MHz\_High\_QPSK\_RB25#0




Date: 15.SEP.2021 18:00:21

### Band 41\_5 MHz\_High\_16QAM\_RB25#0




Date: 15.SEP.2021 18:00:42

### Band 41\_10 MHz\_Low\_QPSK\_RB50#0




Date: 15.SEP.2021 18:01:07

### Band 41\_10 MHz\_Low\_16QAM\_RB50#0




Date: 15.SEP.2021 18:01:30

### Band 41\_10 MHz\_High\_QPSK\_RB50#0




Date: 15.SEP.2021 18:01:53

### Band 41\_10 MHz\_High\_16QAM\_RB50#0




Date: 15.SEP.2021 18:02:16

### Band 41\_15 MHz\_Low\_QPSK\_RB75#0




Date: 15.SEP.2021 19:19:50

### Band 41\_15 MHz\_Low\_16QAM\_RB75#0




Date: 15.SEP.2021 19:15:29

### Band 41\_15 MHz\_High\_QPSK\_RB75#0




Date: 15.SEP.2021 18:03:53

### Band 41\_15 MHz\_High\_16QAM\_RB75#0




Date: 15.SEP.2021 18:04:20

### Band 41\_20 MHz\_Low\_QPSK\_RB100#0




Date: 15.SEP.2021 19:17:58

### Band 41\_20 MHz\_Low\_16QAM\_RB100#0




Date: 15.SEP.2021 18:05:20

### Band 41\_20 MHz\_High\_QPSK\_RB100#0



Date: 15.SEP.2021 18:05:48

### Band 41\_20 MHz\_High\_16QAM\_RB100#0



Date: 15.SEP.2021 18:06:18